Table N.--Highly Erodible Land (HEL) List

Map symbol	Soil name	HEL
BdB	Belmore loam, 2 to 6 percent slopes	Potentially highly erodible land
BfF2	Belmore-Morley complex, 18 to 50 percent slopes	Highly erodible land
BgB	Bennington silt loam, 2 to 6 percent slopes	Potentially highly erodible land
BgB2	Bennington silt loam, 2 to 6 percent slopes, eroded	Potentially highly erodible land
BoA	Blount silt loam, 0 to 2 percent slopes	Not highly erodible land
BoB	Blount silt loam, 2 to 6 percent slopes	Potentially highly erodible land
Bp	Bono silty clay, loamy substratum	Not highly erodible land
Ca	Carlisle muck	Not highly erodible land
Ch	Chagrin silt loam, occasionally flooded	Not highly erodible land
CnA	Channahon silt loam, 0 to 2 percent slopes	Not highly erodible land
CnB	Channahon silt loam, 2 to 6 percent slopes	Potentially highly erodible land
Co	Colwood silt loam	Not highly erodible land
DmA	Digby loam, 1 to 4 percent slopes	Not highly erodible land
FcA	Fitchville silt loam, 1 to 4 percent slopes	Not highly erodible land
GaA	Gallman loam, 0 to 2 percent slopes	Not highly erodible land
GaB	Gallman loam, 2 to 6 percent slopes	Potentially highly erodible land
GwA	Glynwood silt loam, 0 to 2 percent slopes	Not highly erodible land
GwB	Glynwood silt loam, 2 to 6 percent slopes	Potentially highly erodible land
GxB2	Glynwood silty clay loam, 2 to 6 percent slopes, eroded	Potentially highly erodible land
GxC2	Glynwood silty clay loam, 6 to 12 percent slopes, eroded	Potentially highly erodible land
HaA	Haney loam, 0 to 2 percent slopes	Not highly erodible land
HaB	Haney loam, 2 to 6 percent slopes	Potentially highly erodible land
HaC2	Haney loam, 6 to 12 percent slopes, eroded	Potentially highly erodible land
HkA	Haskins loam, 0 to 2 percent slopes	Not highly erodible land
HkB	Haskins loam, 2 to 6 percent slopes	Potentially highly erodible land
HmB	Haskins-Seward complex, 2 to 6 percent slopes	Potentially highly erodible land
Ht	Hoytville silty clay loam	Not highly erodible land
KbA	Kibbie fine sandy loam, 0 to 2 percent slopes	Not highly erodible land
Le	Lenawee silty clay loam	Not highly erodible land
Lw	Linwood muck	Not highly erodible land
Me	Mermill loam	Not highly erodible land
Mf	Millgrove loam	Not highly erodible land
Mm	Millsdale silty clay loam	Not highly erodible land
MnA	Milton silt loam, 0 to 2 percent slopes	Not highly erodible land
MnB	Milton silt loam, 2 to 6 percent slopes	Potentially highly erodible land
MoA	Milton variant loam, 0 to 2 percent slopes	Not highly erodible land
MoB	Milton variant loam, 2 to 6 percent slopes	Potentially highly erodible land
MrD2	Morley silt loam, 12 to 18 percent slopes, eroded	Highly erodible land
MrF2	Morley silt loam, 18 to 50 percent slopes, eroded	Highly erodible land
NpA	Nappanee silt loam, 0 to 2 percent slopes	Not highly erodible land
NpB	Nappanee silt loam, 2 to 6 percent slopes	Potentially highly erodible land
OpB	Oshtemo sandy loam, 2 to 6 percent slopes	Potentially highly erodible land

Pa	Pandora silt loam	Not highly erodible land
Pm	Pewamo silty clay loam	Not highly erodible land
Pt	Pits, quarries	
RbA	Randolph silt loam, 0 to 2 percent slopes	Not highly erodible land
RmB	Rawson loam, 2 to 6 percent slopes	Potentially highly erodible land
RoA	Rimer loamy sand, 0 to 2 percent slopes	Not highly erodible land
Ru	Ross silt loam, occasionally flooded	Not highly erodible land
Sb	Sebring silt loam	Not highly erodible land
SdA	Seward loamy fine sand, 0 to 2 percent slopes	Not highly erodible land
SdB	Seward loamy fine sand, 2 to 6 percent slopes	Potentially highly erodible land
Sh	Shoals silt loam, frequently flooded	Not highly erodible land
SpB	Spinks loamy sand, 2 to 6 percent slopes	Not highly erodible land
TrA	Tiro silt loam, 0 to 2 percent slopes	Not highly erodible land
TrB	Tiro silt loam, 2 to 6 percent slopes	Potentially highly erodible land
Ua	Udorthents, loamy	
Ur	Urban land	
W	Water	