

Minnesota Civil 3D Quick Reference Guide Index

100 - Survey

- 100.0 Minnesota Standard Survey Point Codes
- 114.0 GPS Survey Manual – Measure Points Procedures
- 116.0 GPS Survey Manual – Measure Codes Procedures
- 117.0 GPS Survey Manual – Stakeout Procedures
- 118.0 GPS Survey Manual – Method for Setting Tribrach Over Established Point
- 120.0 Trimble S3 Total Station Manual - Begin Survey Procedures
- 130.0 Downloading Survey Text File from TSC2 Data Collector
- 140.0 TSC7 Training Powerpoint

200 - General

- 200.0 The Civil 3D 2010 Ribbons
- 201.0 The Civil 3D 2010 User Interface
- 202.0 Common Drafting Commands and Shortcuts
- 204.0 Adding Report Surface Volume Icon to Ribbon
- 210.0 Moving Around in the Drawing
- 211.0 Snap and Tracking
- 220.0 Basic Linework and Drafting Objects
- 221.0 Move, Copy or Modify Objects
- 240.0 Annotation – Text and Leaders
- 241.0 Annotation - Dimensioning
- 242.0 Annotation – Tables
- 243.0 Text Fields
- 250.0 MN Drawing Template Layers
- 251.0 Using Layers
- 252.0 Layer Filters
- 253.0 Plotting
- 260.0 Model Space and Layouts
- 260.1 Aligning Model Space Objects in a Viewport
- 260.2 Assign a Page Setup to a Layout
- 261.0 Design Center
- 262.0 Working with Tool Palettes
- 263.0 Setting Up MN NRCS Customized Tool Palettes

300 - Points

- 300.0 Using Point Styles
- 301.0 Importing Survey Points From a Text File
- 302.0 Linking to Survey Points in an External Text File
- 310.0 Default MN Drawing Template Point Groups
- 311.0 Working With Point Groups
- 312.0 Controlling the Display of Point Groups
- 313.0 Creating a New Point Group

400 - Surfaces

- 400.0 Styles - Surface Styles
- 410.0 Setting Up the Standard Existing Ground Surface
- 411.0 Creating a Surface From a Point Group
- 412.0 Creating a Surface From 2D Polyline Contours
- 413.0 Creating a Surface from a DEM
- 413.1 Creating a Surface from a DEM with ArcMap Tool
- 414.0 Creating a Surface from a Shapefile
- 415.0 Creating a Surface from an adf File
- 420.0 Cleaning Up a Surface – Breaklines

Minnesota Civil 3D Quick Reference Guide Index

400 – Surfaces (Cont)

- 421.0 Cleaning Up a Surface – Boundaries
- 430.0 Surface Labels – Contour Labels
- 431.0 Surface Labels – Spot Labels
- 440.0 Viewing a Surface in 3D

500 - Alignments

- 500.0 Styles - Alignment Lines
- 501.0 Styles - Alignment Station Labels
- 510.0 Creating an Alignment from Objects
- 511.0 Creating an Alignment Using Alignment Creation Tools
- 512.0 Create an Offset Alignment
- 513.0 Editing Alignments – Alignment Layout Tools

600 - Profiles

- Profile from a 3D Polyline
- 600.0 Styles - Profile Line Styles
- 601.0 Styles – Profile View Styles
- 602.0 Styles – Profile Label Sets
- 610.0 Profile from a Terrain Surface
- 611.0 Developing a Finished Ground Profile
- 620.0 Profile Views
- 621.0 Profile Labels

700 - Sections

- 700.0 Styles - Section Styles
- 701.0 Styles – Group Plot Styles
- 702.0 Styles – Section Band Sets
- 710.0 Creating Sample Lines
- 711.0 Plotting a Single Section
- 712.0 Plotting Multiple Sections

800 - Grading

- 810.0 Grading Groups
- 820.0 Grading a Simple Storage Pond

900 - Corridors and Assemblies

- 910.0 Creating an Assembly
- 911.0 Editing an Assembly
- 912.0 Conditional Cut or Fill subassembly
- 920.0 Simple Corridors
- 930.0 Corridor Example – Waterway
- 940.0 Assembly Guide – Simple Waterway
- 941.0 Assembly Guide – Cond CutFill Wway
- 942.0 Assembly Guide – Cond CutFill Wway wTile

1000 - Quantities

- Volumes Between Surfaces
- Volumes from Sections

1100 - Data Sharing and Transfer

- Transferring Data Using XML Files
- 1101.0 Linking Drawing Files Using Data Shortcuts

Minnesota Civil 3D Quick Reference Guide Index

1200 - Images and GIS Files

- 1200.0 Inserting Georeferenced Images and Shapefiles
- 1201.0 Adding WMS Image to Civil 3D
- 1202.0 Clipping WMS Images
- 1203.0 Connect to Shapefile
- 1204.0 Task Pane

1300 - NRCS Tools

- 1300.0 Stage Storage Extension

1400 - Customization

- 1400.0 Workspaces and Customization
- 1401.0 Transferring Customization Settings

1500 - Automation

- 1500.0 Plan Production Example – Cross Section Sheets
- 1501.0 Printing Multiple Sheets Using the PUBLISH Command