

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
AaA: Aastad-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50 0.02
AbA: Aberdeen-----	45	Very limited Depth to saturated zone Too Sandy	1.00 1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too Sandy	0.50
Exline-----	30	Very limited Depth to saturated zone Too Sandy	1.00 1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too Sandy Depth to saturated zone	0.50 0.44
Ar: Arveson-----	85	Very limited Depth to saturated zone Too Sandy Seepage Flooding	1.00 1.00 1.00 0.40	Very limited Depth to saturated zone Seepage Flooding	1.00 1.00 0.40	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 0.50
AsE: Arvilla-----	60	Very limited Seepage Too Sandy Slope	1.00 1.00 1.00	Very limited Seepage Slope	1.00 1.00	Very limited Too Sandy Seepage Slope Gravel content	1.00 1.00 1.00 0.04
Sioux-----	25	Very limited Seepage Too Sandy Slope	1.00 1.00 1.00	Very limited Seepage Slope	1.00 1.00	Very limited Too Sandy Seepage Gravel content Slope	1.00 1.00 1.00 1.00
Ba: Bearden-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.44

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BdA: Bearden-----	50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.44
Tonka-----	30	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Ponding	1.00 1.00	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50
Be: Marysland-----	45	Very limited Flooding Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Too Sandy Seepage Depth to saturated zone	1.00 1.00 1.00
Divide-----	40	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Too Sandy Seepage Depth to saturated zone	1.00 1.00 0.44
BfA: Beotia-----	90	Very limited Too Sandy	1.00	Not limited		Somewhat limited Too Sandy	0.50
BfB: Beotia-----	90	Very limited Too Sandy	1.00	Not limited		Somewhat limited Too Sandy	0.50
BhA: Beotia-----	55	Very limited Too Sandy	1.00	Not limited		Somewhat limited Too Sandy	0.50
Bearden-----	35	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.44
BkE: Buse-----	45	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Forman-----	30	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
BkF: Buse-----	55	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Forman-----	20	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
BmF: Buse-----	55	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Forman-----	25	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
BsE: Buse-----	40	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Sioux-----	35	Very limited Slope Seepage Too Sandy	1.00 1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Too Sandy Seepage Gravel content	1.00 1.00 1.00 1.00
BtE: Buse-----	40	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Sioux-----	40	Very limited Seepage Too Sandy Slope	1.00 1.00 1.00	Very limited Seepage Slope	1.00 1.00	Very limited Too Sandy Seepage Gravel content Slope	1.00 1.00 1.00 1.00
Co: Colvin-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Do: Castlewood-----	90	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Too clayey Depth to saturated zone	1.00 1.00
EdB: Edgeley-----	90	Very limited Depth to bedrock Too clayey	1.00 0.50	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 0.50
EdC: Edgeley-----	85	Very limited Depth to bedrock Too clayey	1.00 0.50	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 0.50
EdD: Edgeley-----	85	Very limited Depth to bedrock Slope Too clayey	1.00 0.63 0.50	Very limited Depth to bedrock Slope	1.00 0.63	Very limited Depth to bedrock Slope Too clayey	1.00 0.63 0.50
EmA: Embden-----	90	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Somewhat limited Seepage	0.50
EmB: Embden-----	90	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Somewhat limited Seepage	0.50
EnC: Embden-----	60	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Somewhat limited Seepage	0.50
Buse-----	20	Not limited		Not limited		Not limited	
EsA: Estelline-----	90	Very limited Seepage	1.00	Very limited Seepage	1.00	Very limited Seepage	1.00

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
ExA: Exline-----	50	Very limited Depth to saturated zone Too Sandy	1.00 1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too Sandy Depth to saturated zone	0.50 0.44
Aberdeen-----	40	Very limited Depth to saturated zone Too Sandy	1.00 1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too Sandy	0.50
FoA: Fordville-----	90	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy Gravel content	1.00 0.50 0.01
FoB: Fordville-----	90	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy Gravel content	1.00 0.50 0.01
FrA: Forman-----	60	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Aastad-----	25	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50 0.02
FrB: Forman-----	60	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Aastad-----	25	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50 0.02
FrC: Forman-----	60	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Aastad-----	25	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50 0.02
FrD: Forman-----	55	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
Aastad-----	25	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50 0.02
FsC2: Forman-----	55	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Buse-----	25	Not limited		Not limited		Not limited	
FsE: Forman-----	55	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
Buse-----	25	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
FtD: Forman-----	55	Somewhat limited Slope Too clayey	0.96 0.50	Somewhat limited Slope	0.96	Somewhat limited Slope Too clayey	0.96 0.50
Buse-----	25	Somewhat limited Slope	0.96	Somewhat limited Slope	0.96	Somewhat limited Slope	0.96
FxC: Forman-----	40	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Poinsett-----	25	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
FxD: Forman-----	40	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
Poinsett-----	25	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
GbB: Great Bend-----	85	Very limited Too Sandy	1.00	Not limited		Somewhat limited Too Sandy	0.50
GdA: Great Bend-----	60	Very limited Too Sandy	1.00	Not limited		Somewhat limited Too Sandy	0.50
Beotia-----	30	Very limited Too Sandy	1.00	Not limited		Somewhat limited Too Sandy	0.50
GeB: Great Bend-----	70	Very limited Too Sandy	1.00	Not limited		Somewhat limited Too Sandy	0.50
Zell-----	20	Not limited		Not limited		Not limited	
GeC: Great Bend-----	65	Very limited Too Sandy	1.00	Not limited		Somewhat limited Too Sandy	0.50
Zell-----	25	Not limited		Not limited		Not limited	
Gp: Orthents, Gravelly--	100	Very limited Seepage Too Sandy Slope	1.00 1.00 1.00	Very limited Seepage Slope	1.00 1.00	Very limited Seepage Slope Gravel content Too Sandy	1.00 1.00 0.63 0.50
Ha: Hamar-----	85	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Too Sandy Depth to saturated zone Seepage	1.00 1.00 1.00

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Hd: Hamar-----	90	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Too Sandy Depth to saturated zone Seepage	1.00 1.00 1.00
HeA: Harmony-----	60	Very limited Too Sandy	1.00	Not limited		Somewhat limited Too Sandy	0.50
Aberdeen-----	25	Very limited Depth to saturated zone Too Sandy	1.00 1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too Sandy	0.50
HfA: Hecla-----	90	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Seepage Too Sandy	1.00 0.50
HhA: Hecla-----	60	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Seepage Too Sandy	1.00 0.50
Hamar-----	30	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Too Sandy Depth to saturated zone Seepage	1.00 1.00 1.00
HvB2: Hecla-----	60	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Seepage Too Sandy	1.00 0.50

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Venlo-----	25	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00
KbE: Kloten-----	60	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 0.50
Buse-----	20	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Edgeley-----	10	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 0.50	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 0.50
KnA: Kranzburg-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
KnB: Kranzburg-----	85	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
KnC2: Kranzburg-----	85	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
KrA: Kranzburg-----	60	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Aberdeen-----	30	Very limited Depth to saturated zone Too Sandy	1.00 1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too Sandy	0.50
KrB: Kranzburg-----	65	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Aberdeen-----	25	Very limited Depth to saturated zone Too Sandy	1.00 1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too Sandy	0.50
La: Lamoure-----	85	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
Lo: Lamoure-----	85	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
Lu: Ludden-----	90	Very limited Flooding Too clayey	1.00 1.00	Very limited Flooding	1.00	Very limited Too clayey	1.00
M-W: Miscellaneous Water-	100	Not rated		Not rated		Not rated	
MaB: Maddock-----	85	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
MaD: Maddock-----	90	Very limited Seepage Too Sandy Slope	1.00 1.00 0.37	Very limited Seepage Slope	1.00 0.37	Very limited Seepage Too Sandy Slope	1.00 0.50 0.37

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Mr: Southam-----	100	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 1.00	Very limited Ponding Depth to saturated zone	1.00 1.00	Very limited Ponding Depth to saturated zone Too clayey	1.00 1.00 1.00
Od: Oldham-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
Oh: Oldham-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
Or: Orthents, Loamy----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Pa: Parnell-----	85	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50	Very limited Ponding Depth to saturated zone	1.00 1.00	Very limited Ponding Depth to saturated zone Too clayey	1.00 1.00 0.50
PeA: Peever-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
PeB: Peever-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
PeC: Peever-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
PhA: Peever-----	50	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Hamerly-----	25	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50 0.44
Pm: Playmoor-----	85	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
PoB: Poinsett-----	50	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Forman-----	30	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
PwA: Poinsett-----	55	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Waubay-----	35	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
PwB: Poinsett-----	60	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Waubay-----	25	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
RfA: Renshaw-----	55	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy Gravel content	1.00 0.50 0.34

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Fordville-----	35	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy Gravel content	1.00 0.50 0.01
RfB: Renshaw-----	65	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy Gravel content	1.00 0.50 0.34
Fordville-----	25	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy Gravel content	1.00 0.50 0.01
RfC: Renshaw-----	65	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy Gravel content	1.00 0.50 0.34
Fordville-----	20	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy Gravel content	1.00 0.50 0.01
Sa: Minnewaukan-----	90	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone Seepage	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Ponding	1.00
		Seepage	1.00	Seepage	1.00	Too Sandy	0.50
		Too Sandy	1.00	Ponding	1.00		
		Ponding	1.00				
SdD2: Serden-----	90	Very limited Seepage Too Sandy Slope	1.00 1.00 0.96	Very limited Seepage Slope	1.00 0.96	Very limited Too Sandy Seepage Slope	1.00 1.00 0.96
SeB: Serden-----	50	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Venlo-----	35	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00
ShD: Sieche-----	85	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
ShF: Sieche-----	85	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
SkA: Sinai-----	95	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
SkB: Sinai-----	90	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
SkC: Sinai-----	90	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
SmE: Sioux-----	75	Very limited Slope Seepage Too Sandy	1.00 1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Too Sandy Seepage Gravel content	1.00 1.00 1.00 1.00
Arvilla-----	20	Very limited Slope Seepage Too Sandy	1.00 1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Too Sandy Seepage Gravel content	1.00 1.00 1.00 0.04
Su: Stirum-----	65	Very limited Depth to saturated zone Seepage Ponding Too clayey	1.00 1.00 1.00 0.50	Very limited Depth to saturated zone Seepage Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage Ponding Too clayey	1.00 1.00 1.00 0.50

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Ulen-----	25	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Seepage Depth to saturated zone Too Sandy	1.00 0.86 0.50
SwA: Swenoda-----	90	Somewhat limited Depth to saturated zone	0.24	Very limited Seepage	1.00	Somewhat limited Depth to saturated zone	0.02
SwB: Swenoda-----	90	Somewhat limited Depth to saturated zone	0.24	Very limited Seepage	1.00	Somewhat limited Depth to saturated zone	0.02
SxA: Swenoda-----	65	Somewhat limited Depth to saturated zone	0.24	Very limited Seepage	1.00	Somewhat limited Depth to saturated zone	0.02
Larson-----	25	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
To: Tonka-----	90	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Ponding	1.00 1.00	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50
Uf: Ulen-----	85	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Seepage Depth to saturated zone Too Sandy	1.00 0.86 0.50
Us: Ulen-----	50	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Seepage Depth to saturated zone Too Sandy	1.00 0.86 0.50

Section II
Soil and Site Information

Marshall County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Stirum-----	30	Very limited Depth to saturated zone Seepage Ponding Too clayey	1.00 1.00 1.00 0.50	Very limited Depth to saturated zone Seepage Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage Ponding Too clayey	1.00 1.00 1.00 0.50
Va: Vallars-----	80	Very limited Depth to saturated zone Too clayey Flooding	1.00 0.50 0.40	Very limited Depth to saturated zone Flooding	1.00 0.40	Very limited Depth to saturated zone Too clayey	1.00 0.50
W: Water-----	100	Not rated		Not rated		Not rated	
Wa: Rauville-----	95	Very limited Flooding Depth to saturated zone Seepage Too clayey	1.00 1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50

