

Table ENG-5. - Sanitary Facilities

Carroll County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
AIB:					
Altavista	85	Very limited		Very limited	
		Depth to saturated zone	1.00	Seepage	1.00
		Filtering capacity	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Slope	0.68
At:					
Atkins	85	Very limited		Very limited	
		Flooding	1.00	Depth to hard bedrock	1.00
		Depth to bedrock	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
BoE:					
Bolton	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	1.00	Seepage	0.50
BrC:					
Braddock	85	Somewhat limited		Very limited	
		Content of large stones	0.76	Slope	1.00
		Restricted permeability	0.50	Seepage	1.00
		Slope	0.37	Content of large stones	0.34
Bu:					
Buncombe	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Filtering capacity	1.00	Seepage	1.00
Hatboro	3	Not Rated		Not Rated	
CeB:					
Cecil	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
CeB2:					
Cecil	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
CeC:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
CeC:					
Cecil	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
CeC2:					
Cecil	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
CgB:					
Chester	55	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Glenelg	35	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
CgC:					
Chester	55	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Glenelg	35	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
CgC2:					
Chester	55	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Glenelg	35	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
CgE:					
Chester	55	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
CgE:					
Glenelg	35	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
CgE2:					
Chester	55	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Glenelg	35	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
ChB:					
Chester	50	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Glenelg	30	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
ChB2:					
Chester	55	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Glenelg	35	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
ChC:					
Chester	50	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Glenelg	30	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
ChC2:					
Chester	55	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
ChC2:					
Glenelg	35	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
ChE:					
Chester	55	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Glenelg	35	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
ChE2:					
Chester	55	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Glenelg	35	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
CIC:					
Clymer	85	Somewhat limited		Very limited	
		Depth to bedrock	0.70	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
		Slope	0.37	Depth to soft bedrock	0.26
CID:					
Clymer	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	0.70	Seepage	0.50
		Restricted permeability	0.50	Depth to soft bedrock	0.26
Co:					
Codorus	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Seepage	1.00
		Filtering capacity	1.00	Depth to saturated zone	1.00
Hatboro	3	Not Rated		Not Rated	

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Co:					
Toxaway	3	Not Rated		Not Rated	
Cs:					
Codorus	55	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Seepage	1.00
		Filtering capacity	1.00	Depth to saturated zone	1.00
Hatboro	35	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Seepage	1.00
		Filtering capacity	1.00	Depth to saturated zone	1.00
Cu:					
Comus	85	Very limited		Very limited	
		Filtering capacity	1.00	Seepage	1.00
		Flooding	0.40	Flooding	0.40
Hatboro	5	Not Rated		Not Rated	
CyE:					
Corydon	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
EdC:					
Edneyville	85	Somewhat limited		Very limited	
		Slope	0.37	Slope	1.00
				Seepage	1.00
EkC:					
Elioak	85	Somewhat limited		Very limited	
		Restricted permeability	0.73	Slope	1.00
		Slope	0.37	Seepage	0.50
EkC2:					
Elioak	85	Somewhat limited		Very limited	
		Restricted permeability	0.73	Slope	1.00
		Slope	0.37	Seepage	0.50
EkD:					
Elioak	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.73	Seepage	0.50
EkD2:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
EkD2:					
Elioak	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.73	Seepage	0.50
FcC:					
Fletcher	85	Somewhat limited		Very limited	
		Depth to bedrock	0.78	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
		Slope	0.04	Depth to hard bedrock	0.42
FcD:					
Fletcher	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	0.78	Seepage	0.50
		Restricted permeability	0.50	Depth to hard bedrock	0.42
GnC:					
Gilpin	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	1.00
GnC2:					
Gilpin	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	1.00
GnD:					
Gilpin	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	1.00
Gr:					
Gravelly alluvial land	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Depth to bedrock	0.99	Seepage	1.00
Gu:					
Gullied land	85	Not Rated		Not Rated	

Ha:

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Ha:					
Hatboro	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Seepage	1.00
		Filtering capacity	1.00	Depth to saturated zone	1.00
Toxaway	5	Not Rated		Not Rated	
Hb:					
Hatboro	50	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Seepage	1.00
		Filtering capacity	1.00	Depth to saturated zone	1.00
Toxaway	30	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Filtering capacity	1.00	Seepage	1.00
HcC:					
Hayesville	85	Not Rated		Not Rated	
HcD2:					
Hayesville	85	Not Rated		Not Rated	
HeB:					
Hayesville	85	Not Rated		Not Rated	
HeB2:					
Hayesville	85	Not Rated		Not Rated	
HeC:					
Hayesville	85	Not Rated		Not Rated	
HeC2:					
Hayesville	85	Not Rated		Not Rated	
HeD:					
Hayesville	85	Not Rated		Not Rated	
HeD2:					
Hayesville	85	Not Rated		Not Rated	
HmE:					
Hazel	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
HmF:					
Hazel	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
HnC:					
Hazel	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
HnE:					
Hazel	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
HtB:					
Hiwassee	45	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Turbeville	45	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
HtC:					
Hiwassee	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
Turbeville	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
HtD:					
Hiwassee	45	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Turbeville	45	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
HuC:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
HuC:					
Hiwassee	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Turbeville	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
HuD:					
Hiwassee	45	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Turbeville	45	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
HvC:					
Hiwassee	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
Turbeville	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
LcE:					
Louisa	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
LoD:					
Louisburg	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
LoE:					
Louisburg	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
MaC:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MaC:					
Madison	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
MaC2:					
Madison	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
MaD:					
Madison	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
MaD2:					
Madison	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
MaE:					
Madison	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
MdB:					
Madison	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
MdB2:					
Madison	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
MdC:					
Madison	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
MdC2:					
Madison	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
MdD:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MdD:					
Madison	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
MdD2:					
Madison	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
MdE:					
Madison	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
MdE2:					
Madison	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
ML:					
Made land	100	Not Rated		Not Rated	
MnC:					
Manor	85	Somewhat limited		Very limited	
		Slope	0.37	Slope	1.00
				Seepage	1.00
MnD:					
Manor	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
				Seepage	1.00
MnE:					
Manor	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
				Seepage	1.00
MnF:					
Manor	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
				Seepage	1.00
MoC:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MoC:					
Manor	85	Somewhat limited Slope	0.37	Very limited Slope Seepage	1.00 1.00
MoE:					
Manor	85	Very limited Slope	1.00	Very limited Slope Seepage	1.00 1.00
MoF:					
Manor	85	Very limited Slope	1.00	Very limited Slope Seepage	1.00 1.00
MrB:					
Myersville	85	Somewhat limited Depth to bedrock Restricted permeability	0.78 0.50	Somewhat limited Slope Seepage Depth to soft bedrock	0.68 0.50 0.42
MrC:					
Myersville	85	Somewhat limited Depth to bedrock Restricted permeability Slope	0.78 0.50 0.37	Very limited Slope Seepage Depth to soft bedrock	1.00 0.50 0.42
MrC2:					
Myersville	85	Somewhat limited Depth to bedrock Restricted permeability Slope	0.78 0.50 0.37	Very limited Slope Seepage Depth to soft bedrock	1.00 0.50 0.42
MrE:					
Myersville	85	Very limited Slope Depth to bedrock Restricted permeability	1.00 0.78 0.50	Very limited Slope Seepage Depth to soft bedrock	1.00 0.50 0.42
MrE2:					
Myersville	85	Very limited Slope Depth to bedrock Restricted permeability	1.00 0.78 0.50	Very limited Slope Seepage Depth to soft bedrock	1.00 0.50 0.42
MsC:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MsC:					
Myersville	85	Somewhat limited		Very limited	
		Depth to bedrock	0.78	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
		Slope	0.37	Depth to soft bedrock	0.42
MsE:					
Myersville	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	0.78	Seepage	0.50
		Restricted permeability	0.50	Depth to soft bedrock	0.42
MyC:					
Myersville	85	Somewhat limited		Very limited	
		Depth to bedrock	0.78	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
		Slope	0.37	Depth to soft bedrock	0.42
MyE:					
Myersville	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	0.78	Seepage	0.50
		Restricted permeability	0.50	Depth to soft bedrock	0.42
PoC:					
Porters	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
PoD:					
Porters	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	1.00	Seepage	1.00
		Depth to bedrock	0.78	Depth to soft bedrock	0.42
PoE:					
Porters	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	1.00	Seepage	1.00
		Depth to bedrock	0.78	Depth to soft bedrock	0.42
PoF:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
PoF:					
Porters	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	1.00	Seepage	1.00
		Depth to bedrock	0.78	Depth to soft bedrock	0.42
QU:					
Mines	50	Not Rated		Not Rated	
Quarries	50	Not Rated		Not Rated	
RaC:					
Rabun	85	Somewhat limited		Very limited	
		Restricted permeability	0.73	Slope	1.00
		Slope	0.37	Seepage	0.50
RaD:					
Rabun	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.73	Seepage	0.50
RaD2:					
Rabun	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.73	Seepage	0.50
RaE:					
Rabun	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.73	Seepage	0.50
Rg:					
Rock land	85	Not Rated		Not Rated	
RI:					
Rock land	85	Not Rated		Not Rated	
RmE:					
Ramsey	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Content of large stones	0.79	Seepage	1.00
RmF:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
RmF:					
Ramsey	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Content of large stones	0.79	Seepage	1.00
Rr:					
Rock land	85	Not Rated		Not Rated	
ScD:					
Shelocta	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	1.00
ShB:					
Shelocta	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Seepage	1.00
				Slope	0.68
ShC:					
Shelocta	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	1.00
ShD:					
Shelocta	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	1.00
SrB:					
Starr	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
		Flooding	0.40	Seepage	0.50
				Flooding	0.40
SrC:					
Starr	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Flooding	0.40	Seepage	0.50
		Slope	0.37	Flooding	0.40
SsA:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
SsA:					
State	85	Very limited		Very limited	
		Filtering capacity	1.00	Seepage	1.00
		Restricted permeability	0.50		
		Depth to saturated zone	0.40		
SsB:					
State	85	Very limited		Very limited	
		Filtering capacity	1.00	Seepage	1.00
		Restricted permeability	0.50	Slope	0.68
		Depth to saturated zone	0.40		
St:					
Stony colluvial land	85	Not Rated		Not Rated	
SuC:					
Stony land	85	Not Rated		Not Rated	
SuE:					
Stony land	85	Not Rated		Not Rated	
SuF:					
Stony land	85	Not Rated		Not Rated	
TaC:					
Talladega	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	0.21
TaD:					
Talladega	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	0.21
TaE:					
Talladega	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	0.21
To:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
To:					
Toxaway	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Filtering capacity	1.00	Seepage	1.00
Hatboro	5	Not Rated		Not Rated	
TsC:					
Tusquitee	85	Somewhat limited		Very limited	
		Slope	0.37	Slope	1.00
				Seepage	1.00
TuB:					
Tusquitee	85	Not limited		Very limited	
				Seepage	1.00
				Slope	0.68
TuC:					
Tusquitee	85	Somewhat limited		Very limited	
		Slope	0.37	Slope	1.00
				Seepage	1.00
TuD:					
Tusquitee	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
				Seepage	1.00
TvC:					
Tusquitee	85	Somewhat limited		Very limited	
		Slope	0.37	Slope	1.00
				Seepage	1.00
TvD:					
Tusquitee	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
				Seepage	1.00
W:					
Water	100	Not Rated		Not Rated	
WaC:					
Watauga	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
WaD:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
WaD:					
Watauga	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
WaE:					
Watauga	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
WgC:					
Watauga	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
WgD:					
Watauga	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
WgE:					
Watauga	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
WhC:					
Weikert	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
WhD:					
Weikert	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
WhE:					
Weikert	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
WkD:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
WkD:					
Weikert	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
WkE:					
Weikert	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
WkF:					
Weikert	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
WmB:					
Wickham	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.68
		Flooding	0.40	Seepage	0.50
				Flooding	0.40
WmC:					
Wickham	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37	Seepage	0.50
WsB:					
Wickham	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.68
		Flooding	0.40	Seepage	0.50
				Flooding	0.40
WsC:					
Wickham	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37	Seepage	0.50
WsC2:					
Wickham	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37	Seepage	0.50
WtB:					

Table ENG-5. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
WtB:					
Worsham	85	Very limited		Very limited	
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Slope	0.68