


METHODS OF TYING HIGH TENSILE STRENGTH WIRE



THREAD THROUGH KNOT

* Attach Insulator For Positive Charged Wire Or Use Insulated Tube



CRIMPING SLEEVE

* Attach Insulator For Positive Charged Wire Or Use Insulated Tube



SQUARE KNOT



FIGURE EIGHT KNOT



WESTERN UNION SPLICE