

Selected Soil Interpretations

This report allows the customer to produce a report showing the results of the soil interpretation(s) of his or her choice. It is useful when a standard report that displays the results of the selected interpretation(s) is not available.

When customers select this report, they are presented with a list of interpretations with results for the selected map units. The customer may select up to three interpretations to be presented in table format.

For a description of the particular interpretations and their criteria, use the "Selected Survey Area Interpretation Descriptions" report.

Report—Selected Soil Interpretations

Selected Soil Interpretations—Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
AbfA—Adeland silt loam, 0 to 2 percent slopes					
Adeland	97	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
AbhAI—Adrian muck, 0 to 1 percent slopes, frequently flooded, long duration					
Adrian, undrained	90	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Organic matter content	1.00	Organic matter content	1.00
AjaAI—Allison silt loam, 0 to 2 percent slopes, frequently flooded, long duration					
Allison	97	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
ApkA—Angatoka silt loam, outwash substratum, 0 to 2 percent slopes					
Angatoka, outwash substratum	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Ap1A—Angatoka silt loam, 0 to 2 percent slopes					
Angatoka	100	Somewhat limited		Somewhat limited	
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Ap1B2—Angatoka silt loam, 2 to 6 percent slopes, eroded					
Angatoka	95	Somewhat limited		Somewhat limited	
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Ap1C2—Angatoka silt loam, 6 to 12 percent slopes, eroded					
Angatoka	98	Somewhat limited		Somewhat limited	
		Slope	0.39	Dusty	0.06
		Dusty	0.06	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
AzqA—Ayrshire loam, 0 to 2 percent slopes					
Ayrshire	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	0.22	Seepage	0.22
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
BcgAl—Battleground silt loam, 0 to 2 percent slopes, frequently flooded, long duration					
Battleground	87	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BhyA—Birkbeck silt loam, 0 to 2 percent slopes					
Birkbeck	97	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BhyB2—Birkbeck silt loam, 2 to 6 percent slopes, eroded					
Birkbeck	98	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BvlAK—Brouillett silt loam, 0 to 2 percent slopes, occasionally flooded, brief duration					
Brouillett	80	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Seepage	0.22	Seepage	0.22
		Dusty	0.06	Dusty	0.06
CbaA—Camden silt loam, 0 to 2 percent slopes					
Camden	85	Somewhat limited		Somewhat limited	
		Seepage	0.22	Seepage	0.22
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
CbaB2—Camden silt loam, 2 to 6 percent slopes, eroded					
Camden	85	Somewhat limited		Somewhat limited	
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
CfrG—Cates channery silt loam, 25 to 75 percent slopes					
Cates	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	0.52	Seepage	0.52
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
ChqA—Chalmers silty clay loam, 0 to 1 percent slopes					
Chalmers	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
CnaB—Coloma loamy sand, 2 to 6 percent slopes					
Coloma	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Unstable excavation walls	1.00	Unstable excavation walls	1.00
CnaC—Coloma loamy sand, 6 to 15 percent slopes					
Coloma	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Unstable excavation walls	1.00	Unstable excavation walls	1.00
		Slope	0.84	Slope	0.16

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
CsuA—Crane silt loam, 0 to 2 percent slopes					
Crane	95	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
CudA—Crosby silt loam, fine-loamy subsoil, 0 to 2 percent slopes					
Crosby	93	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
DpbA—Drummer silty clay loam, 0 to 1 percent slopes					
Drummer	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
EcoA—Edwardsville silt loam, 0 to 2 percent slopes					
Edwardsville	97	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
EdeAK—Eel and Beckville soils, 0 to 2 percent slopes, occasionally flooded, brief duration					
Eel	52	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	0.22	Seepage	0.22
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Beckville	45	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	0.52	Seepage	0.52
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
EmdA—Elston sandy loam, 0 to 2 percent slopes					
Elston	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Sand content	0.08	Sand content	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
EmdB—Elston sandy loam, 2 to 6 percent slopes					
Elston	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Sand content	0.08	Sand content	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
FamB—Fairpoint gravelly clay loam, 0 to 6 percent slopes					
Fairpoint	100	Somewhat limited		Somewhat limited	
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
FdbA—Fincastle silt loam, Tipton Till Plain, 0 to 2 percent slopes					
Fincastle	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
FdbB—Fincastle silt loam, 2 to 4 percent slopes					
Fincastle	97	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
FdnA—Fincastle-Starks complex, 0 to 2 percent slopes					
Fincastle	62	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Starks	35	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
GcaAK—Genesee soils, 0 to 2 percent slopes, occasionally flooded, brief duration					
Genesee	97	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Seepage	0.22	Seepage	0.22
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
JcfG—Judyville fine sandy loam, 25 to 70 percent slopes					
Judyville	94	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	0.52	Seepage	0.52
		Dusty	0.01	Dusty	0.01
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
KnqD2—Kendallville silt loam, 12 to 18 percent slopes, eroded					
Kendallville	96	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
LbrA—Lafayette silt loam, 0 to 2 percent slopes					
Lafayette	88	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
LdxAK—Landes fine sandy loam, 0 to 2 percent slopes, occasionally flooded, brief duration					
Landes	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.01	Dusty	0.01
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
LfuAI—Lash fine sandy loam, 0 to 2 percent slopes, frequently flooded, long duration					
Lash	97	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
LfzB2—Lauramie silt loam, 2 to 6 percent slopes, eroded					
Lauramie	92	Somewhat limited		Somewhat limited	
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
LugA—Loudonville silt loam, 0 to 2 percent slopes					
Loudonville	86	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
LugB2—Loudonville silt loam, 2 to 6 percent slopes, eroded					
Loudonville	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
LugC2—Loudonville silt loam, 6 to 12 percent slopes, eroded					
Loudonville	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.39	Dusty	0.05
		Dusty	0.05	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
LuhC—Loudonville silt loam, 4 to 12 percent slopes, stony					
Loudonville	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.39	Dusty	0.04
		Dusty	0.04	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
MamA—Mahalasville silty clay loam, 0 to 1 percent slopes					
Mahalasville	67	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Seepage	0.22	Seepage	0.22
		Dusty	0.06	Dusty	0.06
MaoA—Mahalaland silty clay loam, 0 to 1 percent slopes					
Mahalaland	94	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
MapA—Mahalasville silty clay loam, bedrock substratum, 0 to 1 percent slopes					
Mahalasville, bedrock substratum	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	0.52	Seepage	0.52
		Water gathering surface	0.33	Water gathering surface	0.33
MecB2—Martinsville loam, 2 to 6 percent slopes, eroded					
Martinsville	90	Somewhat limited		Somewhat limited	
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
MjuA—Mellott silt loam, 0 to 2 percent slopes					
Mellott	90	Somewhat limited		Somewhat limited	
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MqIG—Minnehaha silt loam, 35 to 75 percent slopes					
Minnehaha	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Seepage	0.52	Seepage	0.52
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MrcA—Mitiwanga silt loam, 0 to 2 percent slopes					
Mitiwanga	76	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
ObmB2—Octagon silt loam, 2 to 6 percent slopes, eroded					
Octagon	90	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
ObmC2—Octagon silt loam, 6 to 12 percent slopes, eroded					
Octagon	90	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Slope	0.39	Dusty	0.04
		Dusty	0.04	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
ObxA—Ockley silt loam, 0 to 2 percent slopes					
Ockley	85	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
ObxB2—Ockley silt loam, 2 to 6 percent slopes, eroded					
Ockley, eroded	85	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
ObxC2—Ockley silt loam, 6 to 12 percent slopes, eroded					
Ockley	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Slope	0.39	Dusty	0.05
		Dusty	0.05	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
ObxD2—Ockley silt loam, 12 to 18 percent slopes, eroded					
Ockley	85	Very limited		Very limited	
		Slope	1.00	Seepage	1.00
		Seepage	1.00	Too sandy	1.00
		Too sandy	1.00	Slope	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Pg—Pits, gravel					
Pits, gravel	100	Not rated		Not rated	

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
PgaA—Pella silty clay loam, 0 to 1 percent slopes					
Pella	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
PnwBQ—Pinevillage gravelly sandy loam, 2 to 8 percent slopes, rarely flooded					
Pinevillage	100	Somewhat limited		Somewhat limited	
		Seepage	0.52	Seepage	0.52
		Flooding	0.40	Flooding	0.40
		Dusty	0.01	Dusty	0.01
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
PvsA—Princeton fine sandy loam, 0 to 2 percent slopes					
Princeton	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
PvsB2—Princeton fine sandy loam, 2 to 6 percent slopes, eroded					
Princeton	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
PvsC2—Princeton fine sandy loam, 6 to 12 percent slopes, eroded					
Princeton	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Slope	0.39	Unstable excavation walls	0.01
		Unstable excavation walls	0.01	Dusty	0.01
		Dusty	0.01		

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
RbfA—Ragsdale silty clay loam, 0 to 1 percent slopes					
Ragsdale	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RbuB2—Rainsville silt loam, 2 to 6 percent slopes, eroded					
Rainsville	97	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RbuC2—Rainsville silt loam, 6 to 12 percent slopes, eroded					
Rainsville	97	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Slope	0.39	Dusty	0.05
		Dusty	0.05	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
RdvA—Raub silt loam, 0 to 2 percent slopes					
Raub	93	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RetA—Rensselaer silty clay loam, 0 to 1 percent slopes					
Rensselaer	95	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Seepage	0.22	Seepage	0.22
		Dusty	0.06	Dusty	0.06

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
RosAK—Rockmill silt loam, 0 to 1 percent slopes, occasionally flooded, brief duration					
Rockmill, drained	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Organic matter content	1.00	Organic matter content	1.00
		Seepage	1.00	Seepage	1.00
RqaE—Rodman sandy loam, 18 to 25 percent slopes					
Rodman	95	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00
		Sand content	0.86	Sand content	0.86
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
RqaG—Rodman sandy loam, 25 to 50 percent slopes					
Rodman	95	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00
		Sand content	0.86	Sand content	0.86
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
RtxAK—Rossburg silt loam, 0 to 2 percent slopes, occasionally flooded, brief duration					
Rossburg	100	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Seepage	0.63	Seepage	0.63
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
RuxA—Raub-Brenton complex, 0 to 2 percent slopes					
Raub	56	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Brenton	36	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RyfA—Rush silt loam, 0 to 2 percent slopes					
Rush	97	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RyfB2—Rush silt loam, 2 to 6 percent slopes, eroded					
Rush	97	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RywB2—Russell silt loam, 2 to 6 percent slopes, eroded					
Russell	76	Somewhat limited		Somewhat limited	
		Wetness	0.31	Wetness	0.31
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RywC2—Russell silt loam, 6 to 12 percent slopes, eroded					
Russell	95	Somewhat limited		Somewhat limited	
		Slope	0.39	Wetness	0.31
		Wetness	0.31	Dusty	0.06
		Dusty	0.06	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
RywD2--Russell silt loam, 12 to 18 percent slopes, eroded					
Russell	87	Very limited		Very limited	
		Slope	1.00	Wetness	1.00
		Wetness	1.00	Slope	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RzcE--Russell-Strawn complex, 18 to 25 percent slopes					
Russell	50	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Strawn	50	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SldAK--Shoals silt loam, 0 to 2 percent slopes, occasionally flooded, brief duration					
Shoals	90	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SlyA--Silverwood silt loam, 0 to 2 percent slopes					
Silverwood	97	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
SlyB2—Silverwood silt loam, 2 to 6 percent slopes, eroded					
Silverwood	95	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SlzA—Silverwood loam, 0 to 2 percent slopes					
Silverwood	97	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SlzB2—Silverwood loam, 2 to 6 percent slopes, eroded					
Silverwood	95	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SlzC2—Silverwood loam, 6 to 12 percent slopes, eroded					
Silverwood	95	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Slope	0.39	Dusty	0.04
		Dusty	0.04	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
SlzD2—Silverwood loam, 12 to 18 percent slopes, eroded					
Silverwood	95	Very limited		Very limited	
		Slope	1.00	Seepage	1.00
		Seepage	1.00	Too sandy	1.00
		Too sandy	1.00	Slope	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
SngA—Sleeth silt loam, 0 to 2 percent slopes					
Sleeth	75	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SnIAP—Southwest silt loam, 0 to 1 percent slopes, ponded, brief duration					
Southwest	90	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SobAI—Sloan and Beaucoup soils, 0 to 1 percent slopes, frequently flooded, long duration					
Sloan	60	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Beaucoup	40	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SseB2—St. Charles silt loam, 2 to 6 percent slopes, eroded					
St. charles	93	Somewhat limited		Somewhat limited	
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
SteA—Starks silt loam, 0 to 2 percent slopes					
Starks	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SvqE—Strawn loam, 18 to 25 percent slopes					
Strawn	90	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SvqG—Strawn loam, 25 to 70 percent slopes					
Strawn	90	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SwdE—Strawn-Rodman complex, 18 to 25 percent slopes					
Strawn	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Rodman	25	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00
		Sand content	0.86	Sand content	0.86
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
SwdG—Strawn-Rodman complex, 25 to 50 percent slopes					
Strawn	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Rodman	25	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00
		Sand content	0.86	Sand content	0.86
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
TfdA—Throckmorton silt loam, 0 to 2 percent slopes					
Throckmorton	95	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
TfdB—Throckmorton silt loam, 2 to 4 percent slopes					
Throckmorton	97	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
ThrA—Treaty silty clay loam, 0 to 1 percent slopes					
Treaty	90	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
TlxA—Toronto silt loam, 0 to 2 percent slopes					
Toronto	97	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
TmcA—Totanang silt loam, 0 to 2 percent slopes					
Totanang	87	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
UbyE—Udorthents, loamy, 3 to 30 percent slopes					
Udorthents, loamy	100	Not rated		Not rated	
Uea—Urban land					
Urban land	100	Not rated		Not rated	
W—Water					
Water	100	Not rated		Not rated	
WkmA—Waupecan silt loam, 0 to 2 percent slopes					
Waupecan	87	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
WkmB2—Waupecan silt loam, 2 to 6 percent slopes, eroded					
Waupecan	95	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
WmnA--Waynetown silt loam, 0 to 2 percent slopes					
Waynetown	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
WmpA--Wea loam, 0 to 2 percent slopes					
Wea	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
WmpB2--Wea loam, 2 to 6 percent slopes, eroded					
Wea	97	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
WqvA--Westland silty clay loam, 0 to 1 percent slopes					
Westland	98	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
WsuA--Whitaker loam, 0 to 2 percent slopes					
Whitaker	93	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Seepage	0.22	Seepage	0.22
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
WtaA—Whitaker silt loam, 0 to 2 percent slopes					
Whitaker	93	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Seepage	0.22	Seepage	0.22
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
WufB2—Williamstown silt loam, 2 to 6 percent slopes, eroded					
Williamstown	82	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
WvaA—Wingate silt loam, 0 to 2 percent slopes					
Wingate	97	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
WvaB2—Wingate silt loam, 2 to 6 percent slopes, eroded					
Wingate	95	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
XabA—Xenia silt loam, 0 to 2 percent slopes					
Xenia	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
XabB2—Xenia silt loam, 2 to 6 percent slopes, eroded					
Xenia	95	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Fountain County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
XfuB2—Miami-Rainsville complex, 2 to 6 percent slopes, eroded					
Miami	60	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Rainsville	30	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
XfuC2—Miami-Rainsville complex, 6 to 12 percent slopes, eroded					
Miami	65	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Slope	0.39	Dusty	0.05
		Dusty	0.05	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
Rainsville	25	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Slope	0.39	Dusty	0.05
		Dusty	0.05	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
YedA—Yeddo silt loam, 0 to 2 percent slopes					
Yeddo	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Data Source Information

Soil Survey Area: Fountain County, Indiana
 Survey Area Data: Version 15, Sep 8, 2014