

Selected Soil Interpretations

This report allows the customer to produce a report showing the results of the soil interpretation(s) of his or her choice. It is useful when a standard report that displays the results of the selected interpretation(s) is not available.

When customers select this report, they are presented with a list of interpretations with results for the selected map units. The customer may select up to three interpretations to be presented in table format.

For a description of the particular interpretations and their criteria, use the "Selected Survey Area Interpretation Descriptions" report.

Report—Selected Soil Interpretations

Selected Soil Interpretations—Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
BaA—Blount silt loam, 0 to 2 percent slopes					
Blount	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BaB2—Blount silt loam, 1 to 4 percent slopes, eroded					
Blount	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BgmA—Blount silt loam, ground moraine, 0 to 2 percent slopes					
Blount, ground moraine	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Egmb2—Blount silt loam, ground moraine, 1 to 4 percent slopes, eroded					
Blount, ground moraine	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BleA—Blount silt loam, end moraine, 0 to 2 percent slopes					
Blount, end moraine	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BleB2—Blount silt loam, end moraine, 1 to 4 percent slopes, eroded					
Blount, end moraine	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Br—Brookston loam					
Brookston	80	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
ChC—Chelsea fine sand, 4 to 15 percent slopes					
Chelsea	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Unstable excavation walls	1.00	Unstable excavation walls	1.00
		Slope	0.37		

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
CrA—Crosby silt loam, 0 to 3 percent slopes					
Crosby	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
CsA—Crosier loam, 0 to 3 percent slopes					
Crosier	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Cy—Cyclone silt loam					
Cyclone	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
FnA—Fincastle silt loam, Tipton Till Plain, 0 to 2 percent slopes					
Fincastle	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
FsA—Fox loam, 0 to 2 percent slopes					
Fox	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
FsB2--Fox loam, 2 to 6 percent slopes, eroded					
Fox	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
FsC2--Fox loam, 6 to 12 percent slopes, eroded					
Fox	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Slope	0.16	Dusty	0.03
		Dusty	0.03	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
FsD2--Fox loam, 12 to 20 percent slopes, eroded					
Fox	90	Very limited		Very limited	
		Slope	1.00	Seepage	1.00
		Seepage	1.00	Too sandy	1.00
		Too sandy	1.00	Slope	0.96
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
FtC3--Fox clay loam, 6 to 12 percent slopes, severely eroded					
Fox, severely eroded	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Slope	0.16	Dusty	0.03
		Dusty	0.03	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
FtD3--Fox clay loam, 12 to 18 percent slopes, severely eroded					
Fox, severely eroded	100	Very limited		Very limited	
		Slope	1.00	Seepage	1.00
		Seepage	1.00	Too sandy	1.00
		Too sandy	1.00	Slope	0.96
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Ge--Genesee loam, occasionally flooded					
Genesee	90	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	0.22	Seepage	0.22
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
GlpC2--Glynwood clay loam, 6 to 12 percent slopes, eroded					
Glynwood	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.63	Dusty	0.06
		Dusty	0.06	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
GlpC3--Glynwood clay loam, 6 to 12 percent slopes, severely eroded					
Glynwood	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.63	Dusty	0.06
		Dusty	0.06	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
GlcC2—Glynwood clay loam, ground moraine, 6 to 12 percent slopes, eroded					
Glynwood	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.63	Dusty	0.06
		Dusty	0.06	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
GlrB2—Glynwood silt loam, end moraine, 2 to 6 percent slopes, eroded					
Glynwood, end moraine	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
GlsB2—Glynwood silt loam, ground moraine, 2 to 6 percent slopes, eroded					
Glynwood, ground moraine	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
GlyC3—Glynwood-Mississinewa clay loams, 6 to 12 percent slopes, severely eroded					
Glynwood	70	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.63	Dusty	0.06
		Dusty	0.06	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Mississinewa	15	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.63	Water gathering surface	0.40
		Water gathering surface	0.40	Dusty	0.06
		Dusty	0.06	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
GnB2—Glynwood silt loam, 2 to 6 percent slopes, eroded					
Glynwood	85	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
GoC3—Glynwood clay loam, 5 to 12 percent slopes, severely eroded					
Glynwood, severely eroded	100	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.16	Dusty	0.03
		Dusty	0.03	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
HaA—Haskins loam, 0 to 3 percent slopes					
Haskins	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
HeG—Hennepin loam, 25 to 50 percent slopes					
Hennepin	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Ho—Homer loam					
Homer	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Ht--Houghton muck, undrained					
Houghton, undrained	75	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Organic matter content	1.00	Organic matter content	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Seepage	0.16	Seepage	0.16
Hx--Houghton muck, drained					
Houghton, drained	75	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Organic matter content	1.00	Organic matter content	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Seepage	0.16	Seepage	0.16
KaA--Kalamazoo sandy loam, 0 to 2 percent slopes					
Kalamazoo	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
KaB--Kalamazoo sandy loam, 2 to 6 percent slopes					
Kalamazoo	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
KsA--Kosciusko sandy loam, 0 to 2 percent slopes					
Kosciusko	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Unstable excavation walls	0.06	Unstable excavation walls	0.06
		Dusty	0.01	Dusty	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
KsB—Kosciusko sandy loam, 2 to 6 percent slopes					
Kosciusko	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Unstable excavation walls	0.06	Unstable excavation walls	0.06
		Dusty	0.01	Dusty	0.01
KsC—Kosciusko sandy loam, 6 to 12 percent slopes					
Kosciusko	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Slope	0.16	Unstable excavation walls	0.06
		Unstable excavation walls	0.06	Dusty	0.01
		Dusty	0.01		
MbA—Martinsville loam, 0 to 2 percent slopes					
Martinsville	90	Somewhat limited		Somewhat limited	
		Seepage	0.22	Seepage	0.22
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MbB—Martinsville loam, 2 to 6 percent slopes					
Martinsville	100	Somewhat limited		Somewhat limited	
		Seepage	0.22	Seepage	0.22
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MbC2—Martinsville loam, 6 to 12 percent slopes, eroded					
Martinsville	100	Somewhat limited		Somewhat limited	
		Seepage	0.22	Seepage	0.22
		Slope	0.16	Dusty	0.02
		Dusty	0.02	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Md--Martisco muck, sandy substratum					
Madaus, drained	80	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Dusty	0.04	Dusty	0.04
MeB--Metea loamy sand, 2 to 6 percent slopes					
Metea	100	Somewhat limited		Somewhat limited	
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MeC--Metea loamy sand, 6 to 12 percent slopes					
Metea	100	Somewhat limited		Somewhat limited	
		Slope	0.63	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MfB2--Miami loam, 2 to 6 percent slopes, eroded					
Miami	95	Somewhat limited		Somewhat limited	
		Wetness	0.90	Wetness	0.90
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MfC2--Miami loam, 6 to 12 percent slopes, eroded					
Miami	100	Somewhat limited		Somewhat limited	
		Wetness	0.90	Wetness	0.90
		Slope	0.16	Dusty	0.03
		Dusty	0.03	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
MfD2--Miami loam, 12 to 18 percent slopes, eroded					
Miami	100	Very limited		Somewhat limited	
		Slope	1.00	Slope	0.96
		Wetness	0.90	Wetness	0.90
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
MfE2--Miami loam, 18 to 25 percent slopes, eroded					
Miami	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MhB2--Miami silt loam, 2 to 6 percent slopes, eroded					
Miami	95	Somewhat limited		Somewhat limited	
		Wetness	0.94	Wetness	0.94
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MhC2--Miami silt loam, 6 to 12 percent slopes, eroded					
Miami	100	Somewhat limited		Somewhat limited	
		Wetness	0.94	Wetness	0.94
		Slope	0.16	Dusty	0.05
		Dusty	0.05	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
MkC3--Miami clay loam, 6 to 12 percent slopes, severely eroded					
Miami, severely eroded	97	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Slope	0.63	Slope	0.04
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MkD3--Miami clay loam, 12 to 25 percent slopes, severely eroded					
Miami, severely eroded	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Wetness	0.94	Wetness	0.94
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
MIC3—Miami clay loam, moderately permeable substratum, 6 to 12 percent slopes, severely eroded					
Miami, severely eroded	100	Somewhat limited		Somewhat limited	
		Wetness	0.90	Wetness	0.90
		Slope	0.37	Dusty	0.03
		Dusty	0.03	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
Mm—Milford silty clay loam					
Milford	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Mp—Millsdale silty clay loam					
Millsdale	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.04	Dusty	0.04
MsA—Milton silt loam, 0 to 2 percent slopes					
Milton	90	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MsB2—Milton silt loam, 2 to 6 percent slopes, eroded					
Milton	100	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
MsC2—Milton silt loam, 6 to 12 percent slopes, eroded					
Milton	100	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.16	Dusty	0.03
		Dusty	0.03	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
MtG—Milton variant silt loam, 30 to 70 percent slopes					
Milton variant	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Large stones	1.00	Large stones	1.00
		Too stony	1.00	Too stony	1.00
		Dusty	0.04	Dusty	0.04
MvC2—Morley silt loam, 7 to 12 percent slopes, eroded					
Morley	100	Somewhat limited		Somewhat limited	
		Wetness	0.94	Wetness	0.94
		Slope	0.16	Dusty	0.03
		Dusty	0.03	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
MvD2—Morley silt loam, 12 to 18 percent slopes, eroded					
Morley	100	Very limited		Somewhat limited	
		Slope	1.00	Slope	0.96
		Wetness	0.94	Wetness	0.94
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MvE2—Morley silt loam, 18 to 25 percent slopes, eroded					
Morley	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
MxD3--Morley clay loam, 12 to 25 percent slopes, severely eroded					
Morley, severely eroded	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Wetness	0.94	Wetness	0.94
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
OcA--Ockley loam, 0 to 2 percent slopes					
Ockley	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
OcB2--Ockley loam, 2 to 6 percent slopes, eroded					
Ockley	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
OmA--Ormas loamy sand, 0 to 2 percent slopes					
Ormas	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Sand content	0.56	Sand content	0.56
		Unstable excavation walls	0.02	Unstable excavation walls	0.02
OmB--Ormas loamy sand, 2 to 6 percent slopes					
Ormas	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Sand content	0.56	Sand content	0.56
		Unstable excavation walls	0.02	Unstable excavation walls	0.02

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
OmC—Ormas loamy sand, 6 to 15 percent slopes					
Ormas	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Slope	0.63	Sand content	0.56
		Sand content	0.56	Slope	0.04
		Unstable excavation walls	0.02	Unstable excavation walls	0.02
Omz—Orthents, earthen dam					
Orthents	100	Not rated		Not rated	
Or—Orthents, loamy					
Udorthents, loamy	100	Not rated		Not rated	
Pa—Palms muck, undrained					
Palms, undrained	75	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Pm—Palms muck, drained					
Palms, drained	80	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Pp—Palms variant muck, drained					
Palms variant, drained	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Water gathering surface	0.50	Water gathering surface	0.50

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Pt--Pella silty clay loam					
Pella	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Pw--Pewamo silty clay loam					
Pewamo	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Unstable excavation walls	0.05	Unstable excavation walls	0.05
		Dusty	0.04	Dusty	0.04
Px--Pits, gravel					
Pits, gravel	100	Not rated		Not rated	
Py--Pits, quarry					
Pits, quarries, limestone	95	Not rated		Not rated	
RaA--Randolph silt loam, 0 to 2 percent slopes					
Randolph	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RcA--Rawson sandy loam, 0 to 2 percent slopes					
Rawson	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
RcB2--Rawson sandy loam, 2 to 6 percent slopes, eroded					
Rawson	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
RcC2—Rawson sandy loam, 6 to 12 percent slopes, eroded					
Rawson	100	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Slope	0.16	Unstable excavation walls	0.01
		Unstable excavation walls	0.01	Dusty	0.01
		Dusty	0.01		
Re—Rensselaer loam					
Rensselaer	75	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RhA—Riddles loam, 0 to 2 percent slopes					
Riddles	100	Somewhat limited		Somewhat limited	
		Dusty	0.01	Dusty	0.01
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RhB2—Riddles loam, 2 to 6 percent slopes, eroded					
Riddles	100	Somewhat limited		Somewhat limited	
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RhC2—Riddles loam, 6 to 12 percent slopes, eroded					
Riddles	100	Somewhat limited		Somewhat limited	
		Slope	0.16	Dusty	0.02
		Dusty	0.02	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
RmG—Rodman gravelly loam, 25 to 50 percent slopes					
Rodman	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00
		Sand content	0.86	Sand content	0.86
		Unstable excavation walls	0.73	Unstable excavation walls	0.73
		Dusty	0.01	Dusty	0.01
Se—Sebewa loam					
Sebewa	85	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
Sf—Sebewa-Milford complex					
Sebewa	60	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Sand content	0.96	Sand content	0.96
		Water gathering surface	0.33	Water gathering surface	0.33
Milford	40	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Sh—Shoals silt loam, 0 to 2 percent slopes, occasionally flooded					
Shoals	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
So--Sloan silty clay loam, frequently flooded					
Sloan	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Seepage	0.16	Seepage	0.16
W--Water					
Water	100	Not rated		Not rated	
Wc--Walkkill silt loam					
Walkkill	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Organic matter content	1.00	Organic matter content	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Seepage	0.16	Seepage	0.16
Wh--Washtenaw silt loam					
Washtenaw	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Ws--Westland loam					
Westland	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.02	Dusty	0.02

Selected Soil Interpretations--Wabash County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Wt--Whitaker loam					
Whitaker	70	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Seepage	0.22	Seepage	0.22
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Data Source Information

Soil Survey Area: Wabash County, Indiana
 Survey Area Data: Version 18, Sep 16, 2014