

## Table ENG-5. - Sanitary Facilities

Augusta County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
1B:					
Allegheny	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
2B:					
Allegheny	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
3B:					
Allegheny	45	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
Cotaco	40	Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
Purdy		Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
3C:					
Allegheny	50	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Cotaco	35	Very limited		Very limited	
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	0.50	Depth to saturated zone	1.00
		Slope	0.37	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
4B:					
Allegheny	40	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
4B:					
Cotaco	40	Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage Slope	0.50 0.32
Purdy		Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
4C:					
Allegheny	50	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Cotaco	35	Very limited		Very limited	
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	0.50	Depth to saturated zone	1.00
		Slope	0.37	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
5:					
Aqualfs	85	Very limited		Very limited	
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Ponding	1.00
		Ponding	1.00		
6:					
Aquents	85	Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Filtering capacity	1.00	Seepage	1.00
7:					
Atkins	95	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.79	Seepage	1.00

8D:

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
8D:					
Berks	70	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Slope	1.00	Seepage	1.00
Wet Spots		Not Rated		Not Rated	
8E:					
Berks	70	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
Wet Spots		Not Rated		Not Rated	
8F:					
Berks	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
9B2:					
Berks	55	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Filtering capacity	1.00	Seepage	1.00
				Slope	0.68
Weikert	25	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
				Seepage	1.00
				Slope	0.68
Wet Spots		Not Rated		Not Rated	
9C2:					
Berks	55	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Slope	0.37	Seepage	1.00
Weikert	25	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
10B2:					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
10B2:					
Bookwood	70	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	0.50	Seepage	1.00
				Slope	0.68
10C2:					
Bookwood	70	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	0.50	Slope	1.00
			0.37	Seepage	1.00
Wet Spots		Not Rated		Not Rated	
10D2:					
Bookwood	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	1.00
10E2:					
Bookwood	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	1.00
11A:					
Buchanan	80	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Seepage	0.50
				Depth to saturated zone	0.06
Purdy		Not Rated		Not Rated	
11B:					
Buchanan	80	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	0.68
				Seepage	0.50
Purdy		Not Rated		Not Rated	
12B:					

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
12B:					
Buchanan	80	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Seepage	0.50
				Slope	0.32
Purdy		Not Rated		Not Rated	
13C:					
Buchanan	45	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Slope	0.37	Seepage	0.50
Monongahela	35	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	0.50	Depth to saturated zone	1.00
Purdy		Not Rated		Not Rated	
14:					
Buckton	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Restricted permeability	0.50	Seepage	1.00
Wet Spots		Not Rated		Not Rated	
15B:					
Burketown	85	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Seepage	1.00
				Slope	0.32
Flooded Soils		Not Rated		Not Rated	
15C:					
Burketown	85	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Slope	0.37	Seepage	1.00
16E:					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
16E:					
Cataska	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Depth to soft bedrock	1.00
				Slope	1.00
16F:					
Cataska	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Depth to soft bedrock	1.00
				Slope	1.00
17E:					
Cataska	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Depth to soft bedrock	1.00
		Content of large stones	0.54	Slope	1.00
18:					
Chagrin	80	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Restricted permeability	0.50	Seepage	0.50
		Depth to saturated zone	0.40		
Fluvaquents		Not Rated		Not Rated	
19:					
Chavies	70	Somewhat limited		Very limited	
		Flooding	0.40	Seepage	1.00
				Flooding	0.40
20B2:					
Chilhowie	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Seepage	1.00
				Slope	0.68
Wet Spots		Not Rated		Not Rated	
20C2:					
Chilhowie	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Slope	0.37	Seepage	1.00
Wet Spots		Not Rated		Not Rated	
21B3:					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>21B3:</b>					
Chilhowie	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Seepage	1.00
				Slope	0.68
Wet Spots		Not Rated		Not Rated	
<b>21C3:</b>					
Chilhowie	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
			0.37	Seepage	1.00
Wet Spots		Not Rated		Not Rated	
<b>21D3:</b>					
Chilhowie	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
Wet Spots		Not Rated		Not Rated	
<b>21E3:</b>					
Chilhowie	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
Wet Spots		Not Rated		Not Rated	
<b>22B2:</b>					
Chilhowie	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Seepage	1.00
				Slope	0.68
Edom	40	Somewhat limited		Somewhat limited	
		Restricted permeability	0.73	Slope	0.68
		Depth to bedrock	<0.01	Seepage	0.27
Wet Spots		Not Rated		Not Rated	
<b>22C2:</b>					
Chilhowie	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Slope	0.37	Seepage	1.00

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>22C2:</b>					
Edom	40	Somewhat limited		Very limited	
		Restricted permeability	0.73	Slope	1.00
		Slope	0.37	Seepage	0.27
		Depth to bedrock	<0.01		
Wet Spots		Not Rated		Not Rated	
<b>22D2:</b>					
Chilhowie	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
Edom	30	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.73	Seepage	0.27
		Depth to bedrock	<0.01		
Wet Spots		Not Rated		Not Rated	
<b>23C3:</b>					
Chilhowie	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Slope	0.37	Seepage	1.00
Edom	40	Somewhat limited		Very limited	
		Restricted permeability	0.73	Slope	1.00
		Slope	0.37	Seepage	0.27
		Depth to bedrock	<0.01		
Wet Spots		Not Rated		Not Rated	
<b>23E3:</b>					
Chilhowie	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
Edom	30	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.73	Seepage	0.27
		Depth to bedrock	<0.01		
Wet Spots		Not Rated		Not Rated	

24B2:

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>24B2:</b>					
Christian	80	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>24C2:</b>					
Christian	70	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>24D2:</b>					
Christian	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>24E2:</b>					
Christian	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
<b>25C2:</b>					
Christian	80	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>25D2:</b>					
Christian	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>26:</b>					
Cotaco Variant	75	Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	<0.01
		Restricted permeability	1.00		

### Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
26: Purdy		Not Rated		Not Rated	
27: Craigsville	85	Very limited Flooding Filtering capacity Content of large stones	1.00 1.00 0.79	Very limited Flooding Seepage Content of large stones	1.00 1.00 0.97
Wet Spots		Not Rated		Not Rated	
28: Craigsville	75	Very limited Flooding Filtering capacity Content of large stones	1.00 1.00 0.95	Very limited Flooding Seepage Content of large stones	1.00 1.00 1.00
Wet Spots		Not Rated		Not Rated	
29E: Drall	55	Very limited Slope Filtering capacity Depth to bedrock	1.00 1.00 0.36	Very limited Slope Seepage Depth to hard bedrock	1.00 1.00 0.01
29F: Drall	55	Very limited Slope Filtering capacity Depth to bedrock	1.00 1.00 0.36	Very limited Slope Seepage Depth to hard bedrock	1.00 1.00 0.01
30B2: Edom	80	Somewhat limited Restricted permeability Depth to bedrock	0.73  <0.01	Somewhat limited Slope Seepage	0.68 0.27
30C2: Edom	80	Somewhat limited Restricted permeability Slope Depth to bedrock	0.73  0.37 <0.01	Very limited Slope Seepage	1.00 0.27
30D2:					

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>30D2:</b>					
Edom	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.73	Seepage	0.27
		Depth to bedrock	<0.01		
<b>31B3:</b>					
Edom	80	Somewhat limited		Somewhat limited	
		Restricted permeability	0.73	Slope	0.68
		Depth to bedrock	<0.01	Seepage	0.27
<b>31C3:</b>					
Edom	80	Somewhat limited		Very limited	
		Restricted permeability	0.73	Slope	1.00
		Slope	0.37	Seepage	0.27
		Depth to bedrock	<0.01		
<b>32C2:</b>					
Edom	55	Somewhat limited		Very limited	
		Restricted permeability	0.73	Slope	1.00
		Depth to bedrock	<0.01	Seepage	0.27
Rock Outcrop	30	Not Rated		Not Rated	
<b>32E2:</b>					
Edom	55	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.73	Seepage	0.27
		Depth to bedrock	<0.01		
Rock Outcrop	30	Not Rated		Not Rated	
<b>33E:</b>					
Elliber	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
				Seepage	1.00
<b>34F:</b>					
Elliber	35	Very limited		Very limited	
		Slope	1.00	Slope	1.00
				Seepage	1.00

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>34F:</b>					
Jefferson	35	Very limited Slope	1.00	Very limited Slope Seepage Content of large stones	1.00 1.00 0.02
<b>35B2:</b>					
Endcav	80	Very limited Restricted permeability Depth to bedrock	1.00 0.27	Somewhat limited Slope	0.68
Wet Spots		Not Rated		Not Rated	
<b>35C2:</b>					
Endcav	80	Very limited Restricted permeability Slope Depth to bedrock	1.00 0.37 0.27	Very limited Slope	1.00
Wet Spots		Not Rated		Not Rated	
<b>36B2:</b>					
Endcav	80	Very limited Restricted permeability Depth to bedrock	1.00 0.27	Somewhat limited Slope	0.68
Wet Spots		Not Rated		Not Rated	
<b>37C2:</b>					
Endcav	45	Very limited Restricted permeability Depth to bedrock Slope	1.00 0.27 0.04	Very limited Slope	1.00
Rock Outcrop	40	Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
<b>38B:</b>					
Ernest	80	Very limited Depth to cemented pan Depth to saturated zone Restricted permeability	1.00 1.00 0.50	Very limited Depth to cemented pan Seepage Slope	1.00 0.50 0.32

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
38B:					
Wet Spots		Not Rated		Not Rated	
38C:					
Ernest	80	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
39:					
Fluvaquents	95	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.79	Seepage	1.00
Very Poorly Drained Soils		Not Rated		Not Rated	
40B2:					
Frederick	50	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Christian	30	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Wet Spots		Not Rated		Not Rated	
40C2:					
Frederick	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Christian	35	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
40D2:					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>40D2:</b>					
Frederick	45	Very limited Slope	1.00	Very limited Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Christian	35	Very limited Slope	1.00	Very limited Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Timberville		Not Rated		Not Rated	
<b>40E2:</b>					
Frederick	45	Very limited Slope	1.00	Very limited Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Christian	40	Very limited Slope	1.00	Very limited Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
<b>41B3:</b>					
Frederick	50	Somewhat limited Restricted permeability	0.50	Somewhat limited Slope	0.68
				Seepage	0.50
Christian	35	Somewhat limited Restricted permeability	0.50	Somewhat limited Slope	0.68
				Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>41C3:</b>					
Frederick	45	Somewhat limited Restricted permeability	0.50	Very limited Slope	1.00
		Slope	0.37	Seepage	0.50
Christian	35	Somewhat limited Restricted permeability	0.50	Very limited Slope	1.00
		Slope	0.37	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>41D3:</b>					

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
41D3:					
Frederick	50	Very limited Slope	1.00	Very limited Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Christian	40	Very limited Slope	1.00	Very limited Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
42B2:					
Frederick	50	Somewhat limited Restricted permeability	0.50	Somewhat limited Slope Seepage	0.68 0.50
Christian	35	Somewhat limited Restricted permeability	0.50	Somewhat limited Slope Seepage	0.68 0.50
Wet Spots		Not Rated		Not Rated	
42C2:					
Frederick	45	Somewhat limited Restricted permeability Slope	0.50 0.37	Very limited Slope Seepage	1.00 0.50
Christian	35	Somewhat limited Restricted permeability Slope	0.50 0.37	Very limited Slope Seepage	1.00 0.50
Wet Spots		Not Rated		Not Rated	
42D2:					
Frederick	45	Very limited Slope Restricted permeability	1.00 0.50	Very limited Slope Seepage	1.00 0.50
Christian	40	Very limited Slope Restricted permeability	1.00 0.50	Very limited Slope Seepage	1.00 0.50
Wet Spots		Not Rated		Not Rated	
42E2:					

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
42E2:					
Frederick	50	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Christian	40	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
43C:					
Frederick	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Christian	35	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
43D:					
Frederick	45	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Christian	35	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
43E:					
Frederick	50	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Christian	40	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
44B2:					
Frederick	50	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
44B2:					
Christian	35	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Wet Spots		Not Rated		Not Rated	
44C2:					
Frederick	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Christian	40	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
44D2:					
Frederick	45	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Christian	35	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
44E2:					
Frederick	50	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Christian	40	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
45C2:					
Frederick	50	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
Rock Outcrop	30	Not Rated		Not Rated	
45E2:					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>45E2:</b>					
Frederick	45	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Rock Outcrop	35	Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
<b>46B:</b>					
Frederick	50	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Nixa	40	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	0.68
				Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>46C:</b>					
Frederick	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Nixa	45	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Slope	0.37	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>47C:</b>					
Guernsey	85	Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to soft bedrock	1.00
		Restricted permeability	1.00	Slope	0.92
		Depth to bedrock	1.00	Seepage	0.27
Poorly Drained Soils		Not Rated		Not Rated	

48E:

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
48E:					
Hartleton	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
49F:					
Hartleton	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	0.78	Content of large stones	1.00
		Content of large stones	0.31	Seepage	1.00
50D:					
Hazleton	80	Very limited		Very limited	
		Filtering capacity	1.00	Slope	1.00
		Slope	1.00	Seepage	1.00
		Depth to bedrock	0.02		
50E:					
Hazleton	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
		Depth to bedrock	0.02		
51D:					
Hazleton	70	Very limited		Very limited	
		Filtering capacity	1.00	Slope	1.00
		Slope	1.00	Seepage	1.00
		Depth to bedrock	0.02		
51F:					
Hazleton	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
		Depth to bedrock	0.02		
52F:					
Hazleton	40	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
		Depth to bedrock	0.02		
Lehew					
	35	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
53C:					

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
53C:					
Jefferson	80	Somewhat limited Slope	0.37	Very limited Slope Seepage	1.00 1.00
53D:					
Jefferson	80	Very limited Slope	1.00	Very limited Slope Seepage	1.00 1.00
54C:					
Leetonia	90	Very limited Filtering capacity Depth to bedrock Slope	1.00 0.94 0.37	Very limited Slope Seepage Depth to hard bedrock	1.00 1.00 0.84
54E:					
Leetonia	90	Very limited Slope Filtering capacity Depth to bedrock	1.00 1.00 0.94	Very limited Slope Seepage Depth to hard bedrock	1.00 1.00 0.84
55D:					
Lehew	85	Very limited Depth to bedrock Filtering capacity Slope	1.00 1.00 1.00	Very limited Depth to hard bedrock Slope Seepage	1.00 1.00 1.00
56D:					
Lehew	90	Very limited Depth to bedrock Filtering capacity Slope	1.00 1.00 1.00	Very limited Depth to hard bedrock Slope Seepage	1.00 1.00 1.00
57E:					
Lehew	85	Very limited Depth to bedrock Slope Filtering capacity	1.00 1.00 1.00	Very limited Depth to hard bedrock Slope Seepage	1.00 1.00 1.00
57F:					
Lehew	85	Very limited Depth to bedrock Slope Filtering capacity	1.00 1.00 1.00	Very limited Depth to hard bedrock Slope Seepage	1.00 1.00 1.00
58D:					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>58D:</b>					
Lew	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
<b>59E:</b>					
Lew	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
<b>59F:</b>					
Lew	60	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
<b>60:</b>					
Massanetta	90	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage	0.50
Wet Soils		Not Rated		Not Rated	
<b>61B:</b>					
Millrock	75	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Filtering capacity	1.00	Seepage	1.00
Frequented Flooded Soils		Not Rated		Not Rated	
<b>62B:</b>					
Monongahela	75	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Seepage	0.50
		Restricted permeability	0.50	Slope	0.32
Purdy		Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
<b>62C:</b>					

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
62C:					
Monongahela	80	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Purdy		Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
63B:					
Monongahela	75	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Seepage	0.50
		Restricted permeability	0.50	Slope	0.32
Purdy		Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
63C:					
Monongahela	70	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Purdy		Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
64C:					
Nixa	85	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Slope	0.04	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
64D:					

### Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>64D:</b>					
Nixa	85	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Slope	1.00	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
<b>65E:</b>					
Opequon	45	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	0.27
Rock Outcrop	45	Not Rated		Not Rated	
<b>66:</b>					
Philo	95	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage	1.00
Wet Spots		Not Rated		Not Rated	
<b>66X:</b>					
Pits And Dumps	100	Not Rated		Not Rated	
<b>67:</b>					
Purdy	80	Very limited		Very limited	
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00		
Ponded Soils		Not Rated		Not Rated	
Very Poorly Drained Soils		Not Rated		Not Rated	
<b>68E:</b>					
Rock Outcrop	50	Not Rated		Not Rated	
Chilhowie	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
<b>69F:</b>					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
69F:					
Rock Outcrop	60	Not Rated		Not Rated	
Drall	30	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
		Depth to bedrock	0.36	Content of large stones	0.06
70C:					
Rock Outcrop	55	Not Rated		Not Rated	
Frederick	40	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.04	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
70E:					
Rock Outcrop	55	Not Rated		Not Rated	
Frederick	30	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Wet Spots		Not Rated		Not Rated	
71:					
Rubble Land	100	Very limited		Not Rated	
		Slope	1.00		
		Content of large stones	1.00		
		Depth to bedrock	1.00		
72F:					
Rushtown	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
73B2:					
Sequoia	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	1.00	Slope	0.68
Wet Soils		Not Rated		Not Rated	
73C2:					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
73C2:					
Sequoia	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37		
Wet Soils		Not Rated		Not Rated	
74B2:					
Sequoia	55	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	1.00	Slope	0.68
Berks	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Filtering capacity	1.00	Seepage	1.00
				Slope	0.68
Wet Soils		Not Rated		Not Rated	
74C2:					
Sequoia	55	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37		
Berks	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Slope	0.37	Seepage	1.00
74D2:					
Sequoia	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
		Restricted permeability	1.00		
Berks	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
Wet Spots		Not Rated		Not Rated	

75B2:

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
75B2:					
Shenval	75	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
75C2:					
Shenval	75	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
75D2:					
Shenval	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
76C:					
Shenval	75	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
76D:					
Shenval	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
77C:					
Sherando	80	Very limited		Very limited	
		Filtering capacity	1.00	Seepage	1.00
		Slope	0.04	Slope	1.00
77D:					
Sherando	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
78C:					
Sherando	85	Very limited		Very limited	
		Filtering capacity	1.00	Seepage	1.00
		Slope	0.04	Slope	1.00
		Content of large stones	0.01	Content of large stones	0.09
78E:					

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
78E:					
Sherando	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
		Content of large stones	0.01	Content of large stones	0.09
79B:					
Timberville	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
Frequently Flooded Soils		Not Rated		Not Rated	
80B:					
Timberville	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
Frequently Flooded Soils		Not Rated		Not Rated	
81:					
Tioga	75	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Filtering capacity	1.00	Seepage	1.00
		Depth to saturated zone	0.84	Depth to saturated zone	0.17
82:					
Udifulvents	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage	1.00
Fluvaquents		Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
83:					
Udorthents	80	Not Rated		Not Rated	
Frequently Flooded Soils		Not Rated		Not Rated	
84:					
Udorthents	95	Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
85:					

**Table ENG-5. - Sanitary Facilities - Continued**

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
85:					
Udorthents	95	Not Rated		Not Rated	
Wet Spots		Not Rated		Not Rated	
86B:					
Unison	80	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
86C2:					
Unison	80	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
86D2:					
Unison	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
87B:					
Unison	80	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
87C:					
Unison	80	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
87E:					
Unison	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
88:					
Urban Land	100	Not Rated		Not Rated	
89D3:					
Weikert	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Wet Areas		Not Rated		Not Rated	
89E3:					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>89E3:</b>					
Weikert	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
<b>89F3:</b>					
Weikert	90	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Wet Soils		Not Rated		Not Rated	
<b>90D2:</b>					
Weikert	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Berks	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Wet Areas		Not Rated		Not Rated	
<b>90E3:</b>					
Weikert	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Berks	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Wet Areas		Not Rated		Not Rated	
<b>91B:</b>					
Wheeling	85	Very limited		Very limited	
		Filtering capacity	1.00	Seepage	1.00
		Restricted permeability	0.50	Flooding	0.40
		Flooding	0.40	Slope	0.32
<b>91C2:</b>					

## Table ENG-5. - Sanitary Facilities - Continued

Augusta County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
91C2:					
Wheeling	85	Very limited		Very limited	
		Filtering capacity	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	1.00
		Flooding	0.40	Flooding	0.40
Frequently Flooded Soils		Not Rated		Not Rated	
92B:					
Wheeling	87	Very limited		Very limited	
		Filtering capacity	1.00	Seepage	1.00
		Restricted permeability	0.50	Slope	0.68
		Flooding	0.40	Flooding	0.40
Frequently Flooded Soils		Not Rated		Not Rated	
92C2:					
Wheeling	85	Very limited		Very limited	
		Filtering capacity	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	1.00
		Flooding	0.40	Flooding	0.40
Frequently Flooded Soils		Not Rated		Not Rated	
DAM:					
Dam	100	Not Rated		Not Rated	
W:					
Water	100	Not Rated		Not Rated	