

Table ENG-6. - Sanitary Facilities

Carroll County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
AIB:							
Altavista	85	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.86
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50				
At:							
Atkins	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to bedrock	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Gravel content	0.81
BoE:							
Bolton	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
BrC:							
Braddock	85	Very limited		Very limited		Very limited	
		Content of large stones	1.00	Seepage	1.00	Content of large stones	1.00
		Seepage	1.00	Slope	0.37	Seepage	0.50
		Too clayey	0.50			Too clayey	0.50
Bu:							
Buncombe	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Seepage	1.00
		Seepage	1.00	Seepage	1.00	Too Sandy	0.50
		Too Sandy	1.00				
Hatboro	3	Not Rated		Not Rated		Not Rated	
CeB:							
Cecil	85	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
CeB2:							
Cecil	85	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
CeC:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
CeC:							
Cecil	85	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Hard to compact Slope	0.50 0.50 0.37
CeC2:							
Cecil	85	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Hard to compact Slope	0.50 0.50 0.37
CgB:							
Chester	55	Not limited		Not limited		Not limited	
Glenelg	35	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
CgC:							
Chester	55	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37
Glenelg	35	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
CgC2:							
Chester	55	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37
Glenelg	35	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
CgE:							
Chester	55	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Glenelg	35	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
CgE2:							
Chester	55	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Glenelg	35	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
ChB:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
ChB:							
Chester	50	Not limited		Not limited		Not limited	
Glenelg	30	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
ChB2:							
Chester	55	Not limited		Not limited		Not limited	
Glenelg	35	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
ChC:							
Chester	50	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37
Glenelg	30	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
ChC2:							
Chester	55	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37
Glenelg	35	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
ChE:							
Chester	55	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Glenelg	35	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
ChE2:							
Chester	55	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Glenelg	35	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
CIC:							
Clymer	85	Very limited Depth to bedrock Slope	1.00 0.37	Somewhat limited Slope Depth to bedrock	0.37 0.26	Somewhat limited Slope Depth to bedrock	0.37 0.26

CID:

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
CID:							
Clymer	85	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 0.26	Very limited Slope Depth to bedrock	1.00 0.26
Co:							
Codorus	85	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Too Sandy Seepage Depth to saturated zone	1.00 1.00 1.00
Hatboro	3	Not Rated		Not Rated		Not Rated	
Toxaway	3	Not Rated		Not Rated		Not Rated	
Cs:							
Codorus	55	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Too Sandy Seepage Depth to saturated zone	1.00 1.00 1.00
Hatboro	35	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone	1.00
Cu:							
Comus	85	Very limited Seepage Too Sandy Flooding	1.00 1.00 0.40	Very limited Seepage Flooding	1.00 0.40	Very limited Too Sandy Seepage Gravel content	1.00 1.00 0.08
Hatboro	5	Not Rated		Not Rated		Not Rated	
CyE:							
Corydon	85	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00
EdC:							
Edneyville	85	Very limited Seepage Slope	1.00 0.37	Very limited Seepage Slope	1.00 0.37	Somewhat limited Seepage Slope	0.50 0.37
EkC:							
Elioak	85	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
EkC2:							
Elioak	85	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37
EkD:							
Elioak	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
EkD2:							
Elioak	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
FcC:							
Fletcher	85	Very limited Depth to bedrock Too clayey Slope	1.00 0.50 0.04	Somewhat limited Depth to bedrock Slope	0.42 0.04	Somewhat limited Too clayey Depth to bedrock Slope	0.50 0.42 0.04
FcD:							
Fletcher	85	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock	1.00 0.42	Very limited Slope Too clayey Depth to bedrock	1.00 0.50 0.42
GnC:							
Gilpin	85	Very limited Depth to bedrock Too clayey Slope	1.00 0.50 0.37	Very limited Depth to bedrock Slope	1.00 0.37	Very limited Depth to bedrock Too clayey Slope	1.00 0.50 0.37
GnC2:							
Gilpin	85	Very limited Depth to bedrock Too clayey Slope	1.00 0.50 0.37	Very limited Depth to bedrock Slope	1.00 0.37	Very limited Depth to bedrock Too clayey Slope	1.00 0.50 0.37
GnD:							
Gilpin	85	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 0.50
Gr:							
Gravelly alluvial land	85	Not Rated		Not Rated		Not Rated	
Gu:							
Gullied land	85	Not Rated		Not Rated		Not Rated	
Ha:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Ha:							
Hatboro	85	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone	1.00
Toxaway	5	Not Rated		Not Rated		Not Rated	
Hb:							
Hatboro	50	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone	1.00
Toxaway	30	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone	1.00
HcC:							
Hayesville	85	Not Rated		Somewhat limited Slope	0.37	Not Rated	
HcD2:							
Hayesville	85	Not Rated		Very limited Slope	1.00	Not Rated	
HeB:							
Hayesville	85	Not Rated		Not limited		Not Rated	
HeB2:							
Hayesville	85	Not Rated		Not limited		Not Rated	
HeC:							
Hayesville	85	Not Rated		Somewhat limited Slope	0.37	Not Rated	
HeC2:							
Hayesville	85	Not Rated		Somewhat limited Slope	0.37	Not Rated	
HeD:							
Hayesville	85	Not Rated		Very limited Slope	1.00	Not Rated	
HeD2:							
Hayesville	85	Not Rated		Very limited Slope	1.00	Not Rated	

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
HmE:							
Hazel	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
HmF:							
Hazel	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
HnC:							
Hazel	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
HnE:							
Hazel	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
HtB:							
Hiwassee	45	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Gravel content	0.02
Turbeville	45	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
HtC:							
Hiwassee	45	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Gravel content	0.02
Turbeville	45	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
HtD:							
Hiwassee	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Gravel content	0.02
Turbeville	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
HuC:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
HuC:							
Hiwassee	45	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Slope Gravel content	0.37 0.03
Turbeville	45	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
HuD:							
Hiwassee	45	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Gravel content	1.00 0.03
Turbeville	45	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
HvC:							
Hiwassee	45	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Gravel content	0.02
Turbeville	45	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
LcE:							
Louisa	85	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 0.50
LoD:							
Louisburg	85	Very limited Depth to bedrock Seepage Slope	1.00 1.00 1.00	Very limited Seepage Depth to bedrock Slope	1.00 1.00 1.00	Very limited Depth to bedrock Seepage Slope	1.00 1.00 1.00
LoE:							
Louisburg	85	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 1.00
MaC:							
Madison	85	Not limited		Not limited		Not limited	
MaC2:							
Madison	85	Not limited		Not limited		Not limited	
MaD:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MaD:							
Madison	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
MaD2:							
Madison	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
MaE:							
Madison	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
MdB:							
Madison	85	Not limited		Not limited		Not limited	
MdB2:							
Madison	85	Not limited		Not limited		Not limited	
MdC:							
Madison	85	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37
MdC2:							
Madison	85	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37
MdD:							
Madison	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
MdD2:							
Madison	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
MdE:							
Madison	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
MdE2:							
Madison	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
ML:							
Made land	100	Not Rated		Not Rated		Not Rated	
MnC:							
Manor	85	Very limited Seepage	1.00	Very limited Seepage	1.00	Somewhat limited Gravel content	0.55
		Slope	0.37	Slope	0.37	Slope	0.37
						Seepage	0.21

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MnD:							
Manor	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
						Seepage	0.21
MnE:							
Manor	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
						Seepage	0.21
MnF:							
Manor	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
						Seepage	0.21
MoC:							
Manor	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
		Slope	0.37	Slope	0.37	Slope	0.37
						Seepage	0.21
MoE:							
Manor	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
						Seepage	0.21
MoF:							
Manor	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
						Seepage	0.21
MrB:							
Myersville	85	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
MrC:							
Myersville	85	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Depth to bedrock	0.42
		Slope	0.37			Slope	0.37
MrC2:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MrC2:							
Myersville	85	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Depth to bedrock	0.42
		Slope	0.37			Slope	0.37
MrE:							
Myersville	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
MrE2:							
Myersville	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
MsC:							
Myersville	85	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Depth to bedrock	0.42
		Slope	0.37			Slope	0.37
MsE:							
Myersville	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
MyC:							
Myersville	85	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Depth to bedrock	0.42
		Slope	0.37			Slope	0.37
MyE:							
Myersville	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
PoC:							
Porters	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
PoD:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
PoD:							
Porters	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	0.50
				Depth to bedrock	0.42	Depth to bedrock	0.42
PoE:							
Porters	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	0.50
				Depth to bedrock	0.42	Depth to bedrock	0.42
PoF:							
Porters	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	0.50
				Depth to bedrock	0.42	Depth to bedrock	0.42
QU:							
Mines	50	Not Rated		Not Rated		Not Rated	
Quarries	50	Not Rated		Not Rated		Not Rated	
RaC:							
Rabun	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
						Slope	0.37
RaD:							
Rabun	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
RaD2:							
Rabun	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
RaE:							
Rabun	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
Rg:							
Rock land	85	Not Rated		Not Rated		Not Rated	

RI:

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
RI: Rock land	85	Not Rated		Not Rated		Not Rated	
RmE: Ramsey	85	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 1.00
RmF: Ramsey	85	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 1.00
Rr: Rock land	85	Not Rated		Not Rated		Not Rated	
ScD: Shelocta	85	Very limited Slope Seepage Too clayey	1.00 1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
ShB: Shelocta	85	Very limited Seepage Too clayey	1.00 0.50	Not limited		Somewhat limited Too clayey	0.50
ShC: Shelocta	85	Very limited Seepage Too clayey Slope	1.00 0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
ShD: Shelocta	85	Very limited Slope Seepage Too clayey	1.00 1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
SrB: Starr	85	Somewhat limited Flooding	0.40	Somewhat limited Flooding	0.40	Not limited	
SrC: Starr	85	Somewhat limited Flooding Slope	0.40 0.37	Somewhat limited Flooding Slope	0.40 0.37	Somewhat limited Slope	0.37
SsA:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
SsA:							
State	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Seepage	1.00
		Too Sandy	1.00	Seepage	1.00	Too Sandy	0.50
		Seepage	1.00				
SsB:							
State	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Seepage	1.00
		Too Sandy	1.00	Seepage	1.00	Too Sandy	0.50
		Seepage	1.00				
St:							
Stony colluvial land	85	Not Rated		Not Rated		Not Rated	
SuC:							
Stony land	85	Not Rated		Not Rated		Not Rated	
SuE:							
Stony land	85	Not Rated		Not Rated		Not Rated	
SuF:							
Stony land	85	Not Rated		Not Rated		Not Rated	
TaC:							
Talladega	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.37	Slope	0.37	Slope	0.37
						Gravel content	0.20
TaD:							
Talladega	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
						Gravel content	0.20
TaE:							
Talladega	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
						Gravel content	0.20
To:							
Toxaway	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
		Seepage	1.00	Seepage	1.00		

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
To:							
Hatboro	5	Not Rated		Not Rated		Not Rated	
TsC:							
Tusquitee	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
TuB:							
Tusquitee	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Too clayey	0.50			Too clayey	0.50
TuC:							
Tusquitee	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
TuD:							
Tusquitee	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Too clayey	0.50			Too clayey	0.50
TvC:							
Tusquitee	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
TvD:							
Tusquitee	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Too clayey	0.50			Too clayey	0.50
W:							
Water	100	Not Rated		Not Rated		Not Rated	
WaC:							
Watauga	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Slope	0.37	Slope	0.37	Slope	0.37
WaD:							
Watauga	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
WaE:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
WaE:							
Watauga	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
WgC:							
Watauga	85	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37
WgD:							
Watauga	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
WgE:							
Watauga	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
WhC:							
Weikert	85	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.37	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.37	Very limited Depth to bedrock Gravel content Seepage	1.00 1.00 0.50
WhD:							
Weikert	85	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 1.00
WhE:							
Weikert	85	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 1.00
WkD:							
Weikert	85	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 1.00
WkE:							
Weikert	85	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 1.00
WkF:							

Table ENG-6. - Sanitary Facilities - Continued

Carroll County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
WkF:							
Weikert	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
WmB:							
Wickham	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Flooding	0.40	Too clayey	0.50
		Flooding	0.40				
WmC:							
Wickham	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
WsB:							
Wickham	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Flooding	0.40	Too clayey	0.50
		Flooding	0.40				
WsC:							
Wickham	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
WsC2:							
Wickham	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
WtB:							
Worsham	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00