

Table ENG-6. - Sanitary Facilities

Fauquier County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Aa:							
Albemarle	85	Very limited		Very limited		Somewhat limited	
		Depth to bedrock	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50	Depth to bedrock	0.42	Depth to bedrock	0.42
		Slope	0.37	Slope	0.37	Slope	0.37
Ab:							
Albemarle	85	Very limited		Very limited		Somewhat limited	
		Depth to bedrock	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50	Depth to bedrock	0.42	Depth to bedrock	0.42
Ba:							
Belvoir	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thin cemented pan	0.50	Depth to saturated zone	1.00	Depth to saturated zone	1.00
Bb:							
Belvoir	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thin cemented pan	0.50	Depth to saturated zone	1.00	Depth to saturated zone	1.00
Bc:							
Bermudian	85	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Seepage	0.21
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Gravel content	0.16
		Seepage	1.00	Seepage	1.00		
Bd:							
Bowmansville	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Seepage	1.00				
Be:							
Braddock	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
Bf:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Bf:							
Braddock	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
Bg:							
Brandywine	85	Somewhat limited		Very limited		Very limited	
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
		Slope	0.37	Slope	0.37	Gravel content	0.94
						Too Sandy	0.50
Bh:							
Brandywine	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
						Gravel content	0.94
Bk:							
Brandywine	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
						Gravel content	0.91
Eubanks							
Eubanks	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
Bl:							
Brandywine	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
						Gravel content	0.91
Bm:							
Brandywine	85	Somewhat limited		Very limited		Very limited	
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
		Slope	0.37	Slope	0.37	Gravel content	0.91
						Too Sandy	0.50
Bn:							
Brandywine	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
						Gravel content	0.91
Bo:							
Brandywine	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
						Gravel content	0.91

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Bp:							
Brandywine	85	Somewhat limited		Very limited		Very limited	
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
		Slope	0.37	Slope	0.37	Gravel content	0.91
						Too Sandy	0.50
Br:							
Bucks	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	0.50			Too clayey	0.50
Ca:							
Calverton	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to bedrock	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Depth to thin cemented pan	0.50	Depth to bedrock	0.42	Too clayey	0.50
Cb:							
Catlett	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00			Gravel content	0.90
Cc:							
Catoctin	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
Cd:							
Catoctin	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
Ce:							
Catoctin	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
Cf:							
Chester	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Cf:							
Brandywine	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
						Gravel content	0.91
Cg:							
Chester	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
Brandywine	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
						Gravel content	0.91
Ch:							
Chester	50	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
Brandywine	30	Somewhat limited		Very limited		Very limited	
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
						Gravel content	0.91
						Too Sandy	0.50
Ck:							
Chester	50	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
Brandywine	30	Somewhat limited		Very limited		Very limited	
		Too Sandy	0.50	Seepage	1.00	Seepage	1.00
		Slope	0.37	Slope	0.37	Gravel content	0.91
						Too Sandy	0.50
Cl:							
Chester	50	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
Eubanks	30	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
Cm:							
Chester	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
Cn:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Cn:							
Chester	85	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Co:							
Chester	85	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Cp:							
Chewacla	85	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone	1.00
Cr:							
Clifton	85	Very limited Depth to bedrock Too clayey Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Slope	1.00 0.37	Very limited Depth to bedrock Too clayey Hard to compact	1.00 1.00 1.00
Cs:							
Congaree	85	Very limited Flooding	1.00	Very limited Flooding	1.00	Not limited	
Ct:							
Congaree	85	Very limited Flooding	1.00	Very limited Flooding	1.00	Not limited	
Cu:							
Croton	85	Very limited Depth to saturated zone Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Depth to bedrock	1.00 0.42	Very limited Depth to saturated zone Too clayey Depth to bedrock	1.00 0.50 0.42
Cv:							
Culpeper	85	Very limited Depth to bedrock Too clayey Slope	1.00 0.50 0.37	Somewhat limited Depth to bedrock Slope	0.61 0.37	Somewhat limited Depth to bedrock Too clayey Slope	0.61 0.50 0.37
Cw:							
Culpeper	85	Very limited Depth to bedrock Too clayey Slope	1.00 0.50 0.37	Somewhat limited Depth to bedrock Slope	0.61 0.37	Somewhat limited Depth to bedrock Too clayey Slope	0.61 0.50 0.37
Cx:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Cx:							
Culpeper	85	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.61	Depth to bedrock	0.61
		Too clayey	0.50			Too clayey	0.50
Da:							
Davidson	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
						Slope	0.37
Db:							
Dyke	85	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Hard to compact	1.00
						Slope	0.37
Ea:							
Elbert	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
		Seepage	1.00			Hard to compact	1.00
Eb:							
Elbert	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
		Seepage	1.00			Hard to compact	1.00
Ec:							
Elioak	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
						Too clayey	0.50
Ed:							
Elioak	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Slope	0.37	Slope	0.37	Too clayey	0.50
						Slope	0.37
Ee:							
Elioak	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Slope	0.37	Slope	0.37	Too clayey	0.50
						Slope	0.37
Ef:							
Elioak	85	Not limited		Not limited		Somewhat limited	
						Too clayey	0.50
Eg:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Eg:							
Eubanks	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
Eh:							
Eubanks	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
Ek:							
Eubanks	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
El:							
Eubanks	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
Em:							
Eubanks	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
Fa:							
Fauquier	50	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Hard to compact	1.00
		Slope	0.37			Depth to bedrock	1.00
Elioak	30	Somewhat limited		Somewhat limited		Somewhat limited	
		Slope	0.37	Slope	0.37	Too clayey	0.50
						Slope	0.37
Fb:							
Fauquier	50	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00			Hard to compact	1.00
						Depth to bedrock	1.00
Elioak	30	Not limited		Not limited		Somewhat limited	
						Too clayey	0.50
Fc:							
Fauquier	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Too clayey	1.00
		Too clayey	1.00	Depth to bedrock	1.00	Hard to compact	1.00
		Slope	1.00			Slope	1.00
Fd:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Fd:							
Fauquier	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Hard to compact	1.00
		Slope	0.37			Depth to bedrock	1.00
Fe:							
Fauquier	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00			Hard to compact	1.00
						Depth to bedrock	1.00
Ff:							
Fauquier	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Too clayey	1.00
		Too clayey	1.00	Depth to bedrock	1.00	Hard to compact	1.00
		Slope	1.00			Slope	1.00
Fg:							
Fauquier	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Hard to compact	1.00
		Slope	0.37			Depth to bedrock	1.00
Fh:							
Fauquier	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00			Hard to compact	1.00
						Depth to bedrock	1.00
Ga:							
Goldvein	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Slope	0.37	Slope	0.37	Slope	0.37
Gb:							
Goldvein	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
						Gravel content	0.08
Ha:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Ha:							
Hazel	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
Hb:							
Hazel	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
Hc:							
Hiwassee	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
						Slope	0.37
Hd:							
Hiwassee	85	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
He:							
Hiwassee	85	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
Hf:							
Hiwassee	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
						Slope	0.37
Ia:							
Iredell	85	Not rated		Very limited		Not rated	
				Depth to saturated zone	1.00		
Ib:							
Iredell	85	Not rated		Very limited		Not rated	
				Depth to saturated zone	1.00		
Ic:							
Iredell	85	Not rated		Very limited		Not rated	
				Depth to saturated zone	1.00		

Id:

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Id:							
Iredell	85	Not rated		Very limited		Not rated	
				Depth to saturated zone	1.00		
Ka:							
Kelly	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Depth to saturated zone	0.86
		Too clayey	1.00			Depth to bedrock	0.42
La:							
Lignum	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Hard to compact	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Depth to saturated zone	0.96
		Too clayey	0.50			Too clayey	0.50
Lb:							
Lloyd	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
						Slope	0.37
Lc:							
Lloyd	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
						Slope	0.37
Ld:							
Louisburg	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
				Depth to bedrock	0.42	Depth to bedrock	0.42
Le:							
Louisburg	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Slope	0.37	Depth to bedrock	0.42	Depth to bedrock	0.42
				Slope	0.37	Slope	0.37
M:							
Made land	85	Not rated		Not rated		Not rated	
Ma:							
Manor	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.21

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Mb:							
Manor	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Slope	0.37
		Slope	0.37	Slope	0.37	Seepage	0.21
Mc:							
Manteo	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.89
Md:							
Masada	85	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
Me:							
Meadowville	85	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Seepage	1.00	Seepage	1.00	Seepage	0.21
		Too clayey	0.50				
Mf:							
Mecklenburg	85	Somewhat limited		Somewhat limited		Very limited	
		Slope	0.37	Slope	0.37	Too clayey	1.00
						Slope	0.37
Mg:							
Mecklenburg	85	Not limited		Not limited		Very limited	
						Too clayey	1.00
Mh:							
Mixed alluvial land	85	Not rated		Not rated		Not rated	
Mk:							
Montalto	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Seepage	1.00			Slope	0.37
Ml:							
Montalto	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00			Too clayey	1.00
		Seepage	1.00				
Mm:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Mm:							
Montalto	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
Mn:							
Montalto	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Seepage	1.00			Slope	0.37
Mo:							
Myersville	50	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Depth to bedrock	0.42
		Slope	0.37			Slope	0.37
Orange	40	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Hard to compact	1.00
		Seepage	1.00			Depth to saturated zone	1.00
Mp:							
Myersville	50	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
Orange	30	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	1.00
		Too clayey	1.00			Hard to compact	1.00
		Seepage	1.00			Depth to saturated zone	1.00
Na:							
Nason	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Hard to compact	1.00
		Slope	0.37			Depth to bedrock	0.42
Nb:							
Nason	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	1.00
		Too clayey	1.00			Hard to compact	1.00
						Depth to bedrock	0.42
Pa:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Pa:							
Penn	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.67
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
Pb:							
Penn	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.67
		Too clayey	0.50			Too clayey	0.50
Pc:							
Penn	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.94
Pd:							
Penn	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.84
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
Pe:							
Penn	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.84
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
Pf:							
Penn	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.67
		Too clayey	0.50			Too clayey	0.50
Ra:							
Rohrersville	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Depth to thick cemented pan	1.00	Depth to cemented pan	0.96	Depth to cemented pan	0.96
		Too clayey	0.50			Too clayey	0.50
Rb:							
Rough gullied land	85	Not rated		Not rated		Not rated	
Rc:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Rc:							
Rowland	85	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	0.86
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Seepage	1.00				
Sa:							
Seneca	85	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.25
		Seepage	1.00				
Sb:							
Starr	85	Very limited		Not limited		Somewhat limited	
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50				
Sc:							
State	85	Very limited		Very limited		Not limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
		Seepage	1.00	Flooding	0.40		
		Flooding	0.40				
Sd:							
Stony colluvium	85	Not rated		Not rated		Not rated	
Se:							
Stony rolling and hilly land	85	Not rated		Not rated		Not rated	
Sf:							
Stony rolling and hilly land	85	Not rated		Not rated		Not rated	
Sg:							
Stony steep land	85	Not rated		Not rated		Not rated	
Sh:							
Stony steep land	85	Not rated		Not rated		Not rated	
Sk:							
Stony (very stony) steep lan	85	Not rated		Not rated		Not rated	
Sl:							
Stony (very stony) steep lan	85	Not rated		Not rated		Not rated	
Ta:							

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Ta:							
Tatum	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Hard to compact	1.00
		Slope	0.37			Depth to bedrock	0.42
Tb:							
Tatum	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	1.00
		Too clayey	1.00			Hard to compact	1.00
						Depth to bedrock	0.42
Tc:							
Tatum	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Hard to compact	1.00
		Slope	0.37			Depth to bedrock	0.42
Td:							
Thurmont	85	Very limited		Very limited		Not limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
Te:							
Tusquitee	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
Wa:							
Wadesboro	85	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Hard to compact	1.00
						Slope	0.37
Wb:							
Wadesboro	85	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Hard to compact	1.00
						Slope	0.37
Wc:							
Wadesboro	85	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
						Hard to compact	1.00
Wd:							
Watt	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
				Seepage	1.00	Seepage	0.50

Table ENG-6. - Sanitary Facilities - Continued

Fauquier County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
We:							
Wehadkee	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Seepage	1.00				
Wf:							
Worsham	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	0.50			Too clayey	0.50
Za:							
Zion	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	0.50			Too clayey	0.50
						Gravel content	0.37