

## Table ENG-6. - Sanitary Facilities

Warren County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
1B:							
Berks	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.29
						Seepage	0.21
1C:							
Berks	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Slope	0.37
		Slope	0.37	Slope	0.37	Seepage	0.21
1D:							
Berks	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.21
2B:							
Blairton	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to saturated zone	0.96
		Too clayey	0.50			Too clayey	0.50
2C:							
Blairton	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to saturated zone	0.96
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
3C:							
Buchanan	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.96
		Slope	0.37	Slope	0.37	Slope	0.37
4C:							
Buchanan	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.96
		Slope	0.37	Slope	0.37	Slope	0.37

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
5:							
Buckton	90	Very limited Flooding Seepage	1.00 1.00	Very limited Flooding	1.00	Not limited	
Wet spots	5	Not Rated		Not Rated		Not Rated	
6C:							
Carbo	50	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.37	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.37	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.37
Endcav	45	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.37	Somewhat limited Depth to bedrock Slope	0.42 0.37	Very limited Too clayey Depth to bedrock Slope	1.00 0.42 0.37
7C:							
Carbo	35	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.37	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.37	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.37
Endcav	30	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.37	Somewhat limited Depth to bedrock Slope	0.42 0.37	Very limited Too clayey Depth to bedrock Slope	1.00 0.42 0.37
Rock outcrop	30	Not Rated		Not Rated		Not Rated	
8C:							
Cataska	85	Very limited Depth to bedrock Slope	1.00 0.37	Very limited Depth to bedrock Slope	1.00 0.37	Very limited Depth to bedrock Gravel content Slope	1.00 1.00 0.37
8D:							
Cataska	85	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 1.00
8E:							
Cataska	85	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 1.00
9:							

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
9:							
Chagrin	80	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
Wet spots	5	Not Rated		Not Rated		Not Rated	
10C:							
Chester	80	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
10D:							
Chester	80	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
10E:							
Chester	80	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
11D:							
Chester	50	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50	Very limited Slope Depth to saturated zone	1.00 1.00	Very limited Slope Too clayey	1.00 0.50
Manor	30	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 0.21
11E:							
Chester	45	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50	Very limited Slope Depth to saturated zone	1.00 1.00	Very limited Slope Too clayey	1.00 0.50
Manor	35	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 0.21
12D:							
Chilhowie	75	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
13B:							
Clearbrook	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00			Depth to saturated zone	0.96
13C:							
Clearbrook	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Depth to saturated zone	0.96
14:							
Craigsville	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Seepage	1.00
		Seepage	1.00	Seepage	1.00	Content of large stones	0.93
		Content of large stones	0.93			Gravel content	0.27
Wet spots	5	Not Rated		Not Rated		Not Rated	
15E:							
Dekalb	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Seepage	1.00	Slope	1.00
		Seepage	1.00	Depth to bedrock	1.00	Seepage	1.00
16F:							
Drall	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Too Sandy	1.00	Depth to bedrock	0.42	Gravel content	0.68
Rubble land	25	Not Rated		Not Rated		Not Rated	
17B:							
Dyke	85	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
17C:							
Dyke	85	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
18B:							
Endcav	90	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	0.42

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
18C:							
Endcav	90	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Depth to bedrock	0.42
		Slope	0.37			Slope	0.37
19B:							
Hawksbill	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Content of large stones	1.00
		Content of large stones	1.00			Too clayey	0.50
		Seepage	1.00			Gravel content	<0.01
Wet spots	5	Not Rated		Not Rated		Not Rated	
20B:							
Hawksbill	90	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Content of large stones	1.00
		Content of large stones	1.00			Too clayey	0.50
		Seepage	1.00			Gravel content	0.01
Wet spots	5	Not Rated		Not Rated		Not Rated	
20C:							
Hawksbill	90	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Content of large stones	1.00
		Content of large stones	1.00	Slope	0.37	Too clayey	0.50
		Seepage	1.00			Slope	0.37
21D:							
Lew	85	Very limited		Very limited		Very limited	
		Content of large stones	1.00	Slope	1.00	Content of large stones	1.00
		Slope	1.00			Slope	1.00
		Too clayey	0.50			Too clayey	0.50
22E:							
Lew	90	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Content of large stones	1.00			Content of large stones	1.00
		Too clayey	0.50			Too clayey	0.50
23B:							
Lodi	75	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
23C:							

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
23C:							
Lodi	75	Very limited Too clayey Slope	1.00 0.37	Somewhat limited Slope	0.37	Very limited Too clayey Slope	1.00 0.37
23D:							
Lodi	85	Very limited Slope Too clayey	1.00 1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 1.00
24B:							
Lodi	85	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
24C:							
Lodi	80	Very limited Too clayey Slope	1.00 0.37	Somewhat limited Slope	0.37	Very limited Too clayey Slope	1.00 0.37
24D:							
Lodi	90	Very limited Slope Too clayey	1.00 1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 1.00
25C:							
Lodi	70	Very limited Too clayey Slope	1.00 0.37	Somewhat limited Slope	0.37	Very limited Too clayey Slope	1.00 0.37
25D:							
Lodi	75	Very limited Slope Too clayey	1.00 1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 1.00
26C:							
Lodi	50	Very limited Too clayey Slope	1.00 0.04	Somewhat limited Slope	0.04	Very limited Too clayey Slope	1.00 0.04
Rock outcrop	30	Not Rated		Not Rated		Not Rated	
26E:							
Lodi	50	Very limited Slope Too clayey	1.00 1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 1.00
Rock outcrop	30	Not Rated		Not Rated		Not Rated	
27B:							

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>27B:</b>							
Millrock	95	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Seepage	1.00
		Seepage	1.00	Seepage	1.00	Too Sandy	0.50
		Too Sandy	1.00				
Wet spots	3	Not Rated		Not Rated		Not Rated	
<b>28B:</b>							
Monongahela	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.68
Purdy	5	Not Rated		Not Rated		Not Rated	
<b>28C:</b>							
Monongahela	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.68
		Slope	0.37	Slope	0.37	Slope	0.37
Purdy	5	Not Rated		Not Rated		Not Rated	
<b>29C:</b>							
Montalto	80	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
<b>30C:</b>							
Myersville	80	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Depth to bedrock	0.42
		Slope	0.37			Slope	0.37
<b>30D:</b>							
Myersville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
<b>31C:</b>							
Myersville	50	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Depth to bedrock	0.42
		Slope	0.37			Slope	0.37

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
31C:							
Catoctin	40	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.37	Seepage	1.00	Seepage	0.50
				Slope	0.37	Slope	0.37
31D:							
Myersville	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
Catoctin	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
				Seepage	1.00	Seepage	0.50
31E:							
Myersville	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
Catoctin	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
				Seepage	1.00	Seepage	0.50
32C:							
Myersville	50	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Depth to bedrock	0.42
		Slope	0.37			Slope	0.37
Montalto	40	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
32D:							
Myersville	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
Montalto	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
32E:							

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
32E:							
Myersville	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
Montalto	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
33:							
Newark	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
Wet spots	5	Not Rated		Not Rated		Not Rated	
34:							
Pits	100	Not Rated		Not Rated		Not Rated	
35:							
Purdy	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	0.50			Too clayey	0.50
36E:							
Rigley	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
						Gravel content	<0.01
37D:							
Rigley	60	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
						Gravel content	<0.01
Berks	15	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.21
Weikert	15	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	1.00

38B:

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
38B:							
Sequoia	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00			Too clayey	1.00
38C:							
Sequoia	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
39B:							
Unison	80	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50				
39C:							
Unison	80	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Slope	0.37
		Slope	0.37				
39D:							
Unison	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50				
40C:							
Unison	75	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Slope	0.37
		Slope	0.37				
41C:							
Weikert	55	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Slope	0.37	Gravel content	1.00
		Slope	0.37			Seepage	0.50
Berks	35	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Slope	0.37
		Slope	0.37	Slope	0.37	Seepage	0.21
41D:							
Weikert	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	1.00

**Table ENG-6. - Sanitary Facilities - Continued**

Warren County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
<b>41D:</b>							
Berks	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.21
Wet spots	3	Not Rated		Not Rated		Not Rated	
<b>41E:</b>							
Weikert	55	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	1.00
Berks	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.21
<b>42B:</b>							
Zoar	85	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.86
		Too clayey	0.50			Too clayey	0.50
<b>W:</b>							
Water	100	Not Rated		Not Rated		Not Rated	