

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
5B: Ackmore-----	50	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone Too clayey	1.00 0.50	Depth to saturated zone	1.00	Too clayey	0.50
Colo-----	35	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone Too clayey	1.00 0.50	Depth to saturated zone	1.00	Too clayey	0.50
7: Wiota-----	95	Somewhat limited Too clayey Flooding	0.50 0.40	Somewhat limited Flooding	0.40	Somewhat limited Too clayey	0.50
8: Judson-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
8B: Judson-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
8C: Judson-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
20C2: Killduff-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
20D2: Killduff-----	100	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
20E2: Killduff-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
24D2: Shelby-----	95	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
24E2: Shelby-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
24F2: Shelby-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
27B: Terril-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
41B: Sparta-----	100	Very limited Too Sandy Seepage	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
41C2: Sparta-----	100	Very limited Too Sandy Seepage	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
41D2: Sparta-----	100	Very limited Too Sandy Seepage Slope	1.00 1.00 0.96	Very limited Seepage Slope	1.00 0.96	Very limited Too Sandy Seepage Slope	1.00 1.00 0.96
43: Bremer-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
54: Zook-----	90	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
55: Nicollet-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
62D: Storden-----	95	Somewhat limited Slope	0.16	Somewhat limited Slope	0.16	Somewhat limited Slope	0.16
62E: Storden-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
62F: Storden-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
63C: Chelsea-----	90	Very limited Too Sandy Seepage	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
63D: Chelsea-----	100	Very limited Too Sandy Seepage Slope	1.00 1.00 0.63	Very limited Seepage Slope	1.00 0.63	Very limited Too Sandy Seepage Slope	1.00 1.00 0.63
63E: Chelsea-----	100	Very limited Too Sandy Seepage Slope	1.00 1.00 1.00	Very limited Seepage Slope	1.00 1.00	Very limited Too Sandy Seepage Slope	1.00 1.00 1.00
65E: Lindley-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
65E3: Lindley-----	95	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
65F: Lindley-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
65G: Lindley-----	95	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
76B: Ladoga-----	100	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
76C2: Ladoga-----	100	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
76D2: Ladoga-----	95	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50	Very limited Depth to saturated zone Slope	1.00 0.63	Somewhat limited Slope Too clayey	0.63 0.50
80C2: Clinton-----	100	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
80D2: Clinton-----	95	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50	Very limited Depth to saturated zone Slope	1.00 0.63	Somewhat limited Slope Too clayey	0.63 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
80D3: Clinton-----	85	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50
80E2: Clinton-----	85	Very limited Depth to saturated zone Slope Too clayey	1.00  1.00 0.50	Very limited Depth to saturated zone Slope	1.00  1.00	Very limited Slope Too clayey	1.00  0.50
88: Nevin-----	90	Very limited Depth to saturated zone Too clayey Flooding	1.00  0.50 0.40	Very limited Depth to saturated zone Flooding	1.00  0.40	Very limited Depth to saturated zone Too clayey	1.00  0.50
93D2: Shelby-----	60	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50
Adair-----	30	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00  1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00  1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00  1.00 0.63
93E2: Shelby-----	70	Very limited Depth to saturated zone Slope Too clayey	1.00  1.00 0.50	Very limited Depth to saturated zone Slope	1.00  1.00	Very limited Slope Too clayey	1.00  0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Adair-----	20	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 1.00	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 1.00
94D2: Caleb-----	55	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50	Very limited Depth to saturated zone Slope	1.00 0.63	Somewhat limited Slope Too clayey	0.63 0.50
Mystic-----	45	Very limited Depth to saturated zone Depth to saturated zone Slope Too clayey	1.00 1.00 0.63 0.50	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50
94E2: Caleb-----	50	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Slope	1.00 1.00	Very limited Slope Too clayey	1.00 0.50
Mystic-----	50	Very limited Depth to saturated zone Depth to saturated zone Slope Too clayey	1.00 1.00 1.00 0.50	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 1.00	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50
107: Webster-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map  unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
117: Garwin-----	60	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
Sperry-----	35	Very limited Depth to saturated zone Too clayey  Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Ponding	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey Ponding	1.00 1.00 1.00 1.00
118: Garwin-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
119: Muscatine-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
120: Tama-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
120B: Tama-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
120C2: Tama-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
120D2: Tama-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
122: Sperry-----	90	Very limited Depth to saturated zone Too clayey  Ponding	1.00  1.00  1.00	Very limited Depth to saturated zone Ponding	1.00  1.00	Very limited Hard to compact  Depth to saturated zone Too clayey Ponding	1.00  1.00 1.00 1.00
133: Colo-----	100	Very limited Flooding  Depth to saturated zone Too clayey	1.00  1.00 0.50	Very limited Flooding  Depth to saturated zone	1.00  1.00	Very limited Depth to saturated zone Too clayey	1.00  0.50
133+: Colo-----	100	Very limited Flooding  Depth to saturated zone Too clayey	1.00  1.00 0.50	Very limited Flooding  Depth to saturated zone	1.00  1.00	Very limited Depth to saturated zone Too clayey	1.00  0.50
135: Coland-----	95	Very limited Flooding  Depth to saturated zone Seepage	1.00  1.00 1.00	Very limited Flooding  Depth to saturated zone Seepage	1.00  1.00 1.00	Very limited Depth to saturated zone Seepage	1.00  0.21
135B: Coland-----	100	Very limited Flooding  Depth to saturated zone Seepage	1.00  1.00 1.00	Very limited Flooding  Depth to saturated zone Seepage	1.00  1.00 1.00	Very limited Depth to saturated zone Seepage	1.00  0.21
138B: Clarion-----	95	Not limited		Not limited		Not limited	
138C2: Clarion-----	95	Not limited		Not limited		Not limited	

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
138D2: Clarion-----	95	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
138E2: Clarion-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
162: Downs-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
162B: Downs-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
162C2: Downs-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
162D2: Downs-----	100	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
162E2: Downs-----	100	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
163B: Fayette-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
163C2: Fayette-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
163D2: Fayette-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
163D3: Fayette-----	85	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
163E2: Fayette-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
163F2: Fayette-----	100	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
168E2: Hayden-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
168F: Hayden-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
168G: Hayden-----	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
172: Wabash-----	95	Very limited Flooding Depth to saturated zone Too clayey Ponding	1.00 1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Ponding	1.00 1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey Ponding	1.00 1.00 1.00 1.00
174: Bolan-----	95	Very limited Seepage Too Sandy	1.00 0.50	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
175B: Dickinson-----	95	Very limited Seepage Too Sandy	1.00 0.50	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
175C: Dickinson-----	100	Very limited Seepage Too Sandy	1.00 0.50	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
175D: Dickinson-----	100	Very limited Seepage Slope Too Sandy	1.00 0.63 0.50	Very limited Seepage Slope	1.00 0.63	Very limited Seepage Slope Too Sandy	1.00 0.63 0.50
179D2: Gara-----	85	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
179E2: Gara-----	85	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
179F2: Gara-----	95	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
179G: Gara-----	95	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
185E2: Bauer-----	95	Very limited Depth to saturated zone Depth to bedrock Too clayey Slope	1.00 1.00 1.00 0.96	Very limited Depth to saturated zone Depth to bedrock Slope	1.00 1.00 0.96	Very limited Hard to compact Depth to bedrock Too clayey Slope	1.00 1.00 1.00 1.00 0.96
185F2: Bauer-----	95	Very limited Depth to saturated zone Slope Depth to bedrock Too clayey	1.00 1.00 1.00 1.00	Very limited Slope Depth to saturated zone Depth to bedrock	1.00 1.00 1.00	Very limited Hard to compact Depth to bedrock Slope Too clayey	1.00 1.00 1.00 1.00 1.00

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
192D2: Adair-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
212: Kennebec-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Somewhat limited Too clayey	0.50
220: Nodaway-----	85	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
222C2: Clarinda-----	95	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
222D2: Clarinda-----	90	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Hard to compact Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63
225: Lawler-----	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 0.50	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
226: Lawler-----	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00  1.00 0.50	Very limited Depth to saturated zone Seepage	1.00  1.00	Very limited Depth to saturated zone Seepage Too Sandy	1.00  1.00 0.50
236B: Lester-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
236C2: Lester-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
236D2: Lester-----	95	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
273B: Olmitz-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
273C: Olmitz-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
279: Taintor-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Hard to compact  Depth to saturated zone Too clayey	1.00  1.00 0.50
280: Mahaska-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Hard to compact  Depth to saturated zone Too clayey	1.00  1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
281B: Otley-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
281C2: Otley-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
281D2: Otley-----	85	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50	Very limited Depth to saturated zone Slope	1.00 0.63	Somewhat limited Slope Too clayey	0.63 0.50
284B: Flagler-----	90	Very limited Seepage Too Sandy	1.00 0.50	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
291: Atterberry-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
293G: Chelsea-----	50	Very limited Too Sandy Slope Seepage	1.00 1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Too Sandy Seepage	1.00 1.00 1.00
Fayette-----	40	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
315: Alluvial Land-----	65	Not Rated Not rated; Fragments > 75mm  Not rated; pH  Not rated Flooding	1.00	Very limited Flooding	1.00	Not Rated Not rated: Unified or minerology class Not rated; Fragments > 75mm	
Nodaway-----	25	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
354: Marsh-----	90	Very limited Flooding  Depth to saturated zone Ponding Too clayey	1.00 1.00 1.00 0.50	Very limited Flooding  Depth to saturated zone Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50
428B: Ely-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
430: Ackmore-----	85	Very limited Flooding  Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding  Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
453: Tuskeego-----	95	Very limited Depth to saturated zone Too clayey  Flooding	1.00 0.50 0.40	Very limited Depth to saturated zone Flooding	1.00 0.40	Very limited Hard to compact  Depth to saturated zone Too clayey	1.00 1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
507: Canisteo-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
570B2: Nira-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
570C2: Nira-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
570D2: Nira-----	95	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50	Very limited Depth to saturated zone Slope	1.00 0.63	Somewhat limited Slope Too clayey	0.63 0.50
620C2: Port Byron-----	95	Not limited		Not limited		Not limited	
620D2: Port Byron-----	95	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
620E2: Port Byron-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
620F2: Port Byron-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
742B: Martinsburg-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
742C: Martinsburg-----	90	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
792D2: Armstrong-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
822D2: Lamoni-----	95	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Hard to compact Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63
822E2: Lamoni-----	95	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 1.00
993D2: Gara-----	50	Somewhat limited Slope Too clayey	0.63  0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
Armstrong-----	40	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
993E2: Gara-----	50	Very limited Slope Too clayey	1.00  0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00  0.50
Armstrong-----	30	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00  1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00  1.00 1.00	Very limited Depth to saturated zone Too clayey Slope	1.00  1.00 1.00
993E3: Gara-----	50	Very limited Slope Too clayey	1.00  0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00  0.50
Armstrong-----	30	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00  1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00  1.00 1.00	Very limited Depth to saturated zone Too clayey Slope	1.00  1.00 1.00
5010: Pits, Sand And Gravel-----	100	Not rated		Not rated		Not rated	
C5B: Ackmore-----	50	Very limited Flooding  Depth to saturated zone Too clayey	1.00  1.00 0.50	Very limited Flooding  Depth to saturated zone	1.00  1.00	Very limited Depth to saturated zone Too clayey	1.00  0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Jasper County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Colo-----	35	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone Too clayey	1.00 0.50	Depth to saturated zone	1.00	Too clayey	0.50
C315: Alluvial Land-----	85	Very limited Flooding	1.00	Very limited Flooding	1.00	Not limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
T120B: Tama-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
T120C: Tama-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
T162B: Downs-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
T162C: Downs-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
W: Water-----	100	Not rated		Not rated		Not rated	