

HIGHLY ERODIBLE LAND CLASSIFICATION REPORT
 Marion County, Kentucky: Detailed Soil Map Legend
 (FOR OFFICE DETERMINATIONS ONLY)

Map Symbol	Soil Mapunit Name	HEL Classification
BaB	Beasley silt loam, 2 to 6 percent slopes	highly erodible
BcC2	Beasley silty clay loam, 6 to 12 percent slopes, eroded	highly erodible
BeC3	Beasley silty clay, 6 to 12 percent slopes, severely eroded	highly erodible
BeD3	Beasley silty clay, 12 to 25 percent slopes, severely eroded	highly erodible
CaB	Carpenter gravelly silt loam, 2 to 6 percent slopes	highly erodible
CaC	Carpenter gravelly silt loam, 6 to 12 percent slopes	highly erodible
CaD	Carpenter gravelly silt loam, 12 to 20 percent slopes	highly erodible
CbF2	Carpenter-Lenberg complex, 20 to 45 percent slopes, eroded	highly erodible
CeB	Chenault gravelly silt loam, 2 to 8 percent slopes	highly erodible
ChC2	Christian silt loam, 6 to 12 percent slopes, eroded	highly erodible
ChD2	Christian silt loam, 12 to 20 percent slopes, eroded	highly erodible
CnD3	Christian clay loam, 12 to 20 percent slopes, severely eroded	highly erodible
CrB	Crider silt loam, 2 to 6 percent slopes	highly erodible
CrC2	Crider silt loam, 6 to 12 percent slopes, eroded	highly erodible
CyF2	Cynthiana-Faywood-Rock outcrop complex, 20 to 60 percent slopes, eroded	highly erodible
DAM	Dam, large	
EdD2	Eden silty clay loam, 6 to 20 percent slopes, eroded	highly erodible
EeE2	Eden-Cynthiana complex, 20 to 35 percent slopes, eroded, rocky	highly erodible
EkB	Elk silt loam, 2 to 6 percent slopes, rarely flooded	highly erodible
EkC2	Elk silt loam, 6 to 12 percent slopes, eroded	highly erodible
FaC2	Faywood silty clay loam, 6 to 12 percent slopes, eroded	highly erodible
FaD2	Faywood silty clay loam, 12 to 20 percent slopes, eroded	highly erodible
FcE2	Faywood-Cynthiana complex, 20 to 30 percent slopes, eroded, very rocky	highly erodible
FrC	Frankstown gravelly silt loam, 6 to 12 percent slopes	highly erodible
FrD	Frankstown gravelly silt loam, 12 to 20 percent slopes	highly erodible
GaF	Garmon channery silt loam, 30 to 80 percent slopes, very rocky	highly erodible
GrB	Greenbriar silt loam, 2 to 6 percent slopes	highly erodible
JeB	Jessietown-Trappist complex, 2 to 6 percent slopes	highly erodible
La	Lawrence silt loam	not highly erodible
LbC2	Lenberg silt loam, 6 to 12 percent slopes, eroded	highly erodible
LbD2	Lenberg silt loam, 12 to 20 percent slopes, eroded	highly erodible
LeE2	Lenberg silty clay loam, 20 to 30 percent slopes, eroded	highly erodible
LnB	Lowell silt loam, 2 to 6 percent slopes	highly erodible
LoC2	Lowell silty clay loam, 6 to 12 percent slopes, eroded	highly erodible
LoD2	Lowell silty clay loam, 12 to 20 percent slopes, eroded	highly erodible
LpC3	Lowell silty clay, 6 to 12 percent slopes, severely eroded	highly erodible
LpD3	Lowell silty clay, 12 to 20 percent slopes, severely eroded	highly erodible
LsC2	Lowell silty clay loam, shale substratum, 2 to 12 percent slopes, eroded	highly erodible
Me	Melvin silt loam, occasionally flooded	not highly erodible
Mn	Melvin silt loam, frequently flooded	not highly erodible

HIGHLY ERODIBLE LAND CLASSIFICATION REPORT--Continued
 Marion County, Kentucky: Detailed Soil Map Legend
 (FOR OFFICE DETERMINATIONS ONLY)

Map Symbol	Soil Mapunit Name	HEL Classification
MoB	Mountview silt loam, 2 to 6 percent slopes	highly erodible
MoC2	Mountview silt loam, 6 to 12 percent slopes, eroded	highly erodible
Na	Newark silt loam, occasionally flooded	not highly erodible
Ne	Newark silt loam, frequently flooded	not highly erodible
NhB	Nicholson silt loam, 2 to 6 percent slopes	highly erodible
NhC2	Nicholson silt loam, 6 to 12 percent slopes, eroded	highly erodible
No	Nolin silt loam, frequently flooded	not highly erodible
OtB	Otwell silt loam, 2 to 8 percent slopes	highly erodible
Pt	Pits, quarry	
RaC	Riney loam, 6 to 12 percent slopes	highly erodible
RcE2	Riney-Christian complex, 20 to 35 percent slopes, eroded	highly erodible
Ro	Robertsville silt loam	not highly erodible
RtD2	Rohan-Trappist complex, 6 to 20 percent slopes, eroded, very rocky	highly erodible
RtF2	Rohan-Trappist complex, 20 to 50 percent slopes, eroded, very rocky	highly erodible
SaB	Sandview silt loam, 2 to 6 percent slopes	highly erodible
SaC2	Sandview silt loam, 6 to 12 percent slopes, eroded	highly erodible
Se	Sensabaugh gravelly silt loam, frequently flooded	not highly erodible
SrE2	Shrouts-Brassfield complex, 12 to 30 percent slopes, eroded, very rocky	highly erodible
TbA	Tilsit-Berea silt loams, 0 to 2 percent slopes	not highly erodible
TbB	Tilsit-Berea silt loams, 2 to 6 percent slopes	highly erodible
TbC2	Tilsit-Berea silt loams, 6 to 12 percent slopes, eroded	highly erodible
TeC2	Trappist-Jessietown complex, 6 to 12 percent slopes, eroded	highly erodible
TrD2	Trappist-Rohan-Greenbriar complex, 12 to 20 percent slopes, eroded, rocky	highly erodible
TrD3	Trappist-Rohan-Greenbriar complex, 12 to 25 percent slopes, severely eroded, rocky	highly erodible
W	Water	