

Selected Soil Interpretations

This report allows the customer to produce a report showing the results of the soil interpretation(s) of his or her choice. It is useful when a standard report that displays the results of the selected interpretation(s) is not available.

When customers select this report, they are presented with a list of interpretations with results for the selected map units. The customer may select up to three interpretations to be presented in table format.

For a description of the particular interpretations and their criteria, use the "Selected Survey Area Interpretation Descriptions" report.

Report—Selected Soil Interpretations

Selected Soil Interpretations—Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
AfB2—Alford silt loam, 2 to 6 percent slopes, eroded					
Alford	90	Somewhat limited		Somewhat limited	
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Am—Armiesburg variant silty clay loam, frequently flooded					
Armiesburg variant	90	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BbA—Barce silt loam, 0 to 2 percent slopes					
Barce	85	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
BdB2—Barce-Montmorenci silt loams, 2 to 6 percent slopes, eroded					
Barce	50	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Montmorenci	35	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Be—Beaucoup silty clay loam, frequently flooded, undrained					
Beaucoup, undrained	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.08	Dusty	0.08
Bk—Beckville loam, occasionally flooded					
Beckville	90	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	0.52	Seepage	0.52
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BmB2—Billett sandy loam, 1 to 4 percent slopes, eroded					
Billett	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
BnC2--Billett sandy loam, 6 to 12 percent slopes, eroded					
Billett	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Slope	0.37	Dusty	0.02
		Dusty	0.02	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
BoA--Blount silt loam, Lake Michigan Lobe, 0 to 2 percent slopes					
Blount, lake mighican lobe	95	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BpD2--Boyer-Mudlavia complex, 8 to 20 percent slopes, eroded					
Boyer	55	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Slope	1.00	Slope	0.96
		Unstable excavation walls	0.05	Unstable excavation walls	0.05
Mudlavia	45	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Slope	1.00	Slope	0.96
		Dusty	0.05	Dusty	0.05
		Large stones	0.02	Large stones	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BrA--Brenton silt loam, 0 to 2 percent slopes					
Brenton	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
BsA—Brenton silt loam, till substratum, 0 to 2 percent slopes					
Brenton	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
BwA—Brenton silt loam, moderately fine substratum, 0 to 2 percent slopes					
Brenton	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
CaB2—Cadiz silt loam, moderately wet, 1 to 6 percent slopes, eroded					
Cadiz	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
CbA—Camden silt loam, 0 to 2 percent slopes					
Camden	90	Somewhat limited		Somewhat limited	
		Seepage	0.22	Seepage	0.22
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
CbB2—Camden silt loam, 2 to 6 percent slopes, eroded					
Camden	90	Somewhat limited		Somewhat limited	
		Seepage	0.22	Seepage	0.22
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
CdB2—Camden silt loam, till substratum, 2 to 6 percent slopes, eroded					
Camden	90	Somewhat limited		Somewhat limited	
		Wetness	0.31	Wetness	0.31
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
CfA—Carmi loam, 0 to 2 percent slopes					
Carmi	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Unstable excavation walls	0.16	Unstable excavation walls	0.16
		Dusty	0.04	Dusty	0.04
Cg—Comfrey loam, stratified substratum, rarely flooded					
Comfrey	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Flooding	0.40	Flooding	0.40
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.04	Dusty	0.04
Cs—Comfrey loam, stratified substratum, frequently flooded, undrained					
Comfrey, undrained	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.04	Dusty	0.04
CtB2—Corwin silt loam, 2 to 6 percent slopes, eroded					
Corwin	85	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Cz—Cyclone silty clay loam					
Cyclone	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Dw—Drummer silty clay loams					
Drummer	55	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Drummer	45	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Seepage	0.22	Seepage	0.22
		Dusty	0.06	Dusty	0.06
Dx—Drummer silty clay loam, gravelly substratum					
Drummer	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
Dy—Du Page loam, frequently flooded					
Du page	90	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
EdB2—Eldean gravelly loam, 2 to 6 percent slopes, eroded					
Eldean	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	0.99	Too sandy	0.99
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
EgA—Eldean silt loam, 0 to 2 percent slopes					
Eldean	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	0.99	Too sandy	0.99
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
EvA—Elston sandy loam, 0 to 3 percent slopes					
Elston	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Sand content	0.08	Sand content	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
GgA—Gilboa silt loam, 0 to 2 percent slopes					
Gilboa	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
GhB2—Glenhall silt loam, 1 to 4 percent slopes, eroded					
Glenhall	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	0.52	Seepage	0.52
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
GkB2—Glenhall silt loam, till substratum, 1 to 4 percent slopes, eroded					
Glenhall	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
GoF—Gosport channery silt loam, 25 to 40 percent slopes					
Gosport	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
HeG—Hennepin loam, 30 to 70 percent slopes					
Hennepin	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
HfB—High Gap silt loam, 2 to 9 percent slopes, stony					
High gap	90	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
HhB2—High Gap variant loam, 2 to 6 percent slopes, eroded					
High gap variant	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
HhC2—High Gap variant loam, 6 to 12 percent slopes, eroded					
High gap variant	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.63	Dusty	0.06
		Dusty	0.06	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Hm—Houghton muck, drained					
Houghton, drained	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Organic matter content	1.00	Organic matter content	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Seepage	0.16	Seepage	0.16
Ho—Houghton muck, undrained					
Houghton, undrained	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Organic matter content	1.00	Organic matter content	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Seepage	0.16	Seepage	0.16
IoB2—Iona silt loam, 1 to 4 percent slopes, eroded					
Iona	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
IpA—Ipava silt loam, 0 to 2 percent slopes					
Ipava	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Ju—Jules silt loam, frequently flooded					
Jules	90	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
LcA—Lafayette silt loam, 0 to 2 percent slopes					
Lafayette	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.27	Water gathering surface	0.27
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Ld—La Hogue silt loam, 0 to 2 percent slopes					
La hogue	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	0.22	Seepage	0.22
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Lk—La Hogue silt loam, till substratum, 0 to 2 percent slopes					
La hogue	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Lp--Landes-Chatterton complex, frequently flooded					
Landes	55	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Seepage	1.00	Seepage	1.00
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Chatterton	35	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Unstable excavation walls	1.00	Unstable excavation walls	1.00
MaB3--Markham silty clay loam, 2 to 6 percent slopes, severely eroded					
Markham, severely eroded	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
McB2--Markham-Symerton silt loams, 2 to 6 percent slopes, eroded					
Markham	55	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Symerton	30	Somewhat limited		Somewhat limited	
		Wetness	0.90	Wetness	0.90
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MdA--Martinsville loam, 0 to 2 percent slopes					
Martinsville	90	Somewhat limited		Somewhat limited	
		Seepage	0.22	Seepage	0.22
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
MdB2—Martinsville loam, 2 to 6 percent slopes, eroded					
Martinsville	90	Somewhat limited		Somewhat limited	
		Seepage	0.22	Seepage	0.22
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MdC2—Martinsville loam, 6 to 12 percent slopes, eroded					
Martinsville	90	Somewhat limited		Somewhat limited	
		Slope	0.63	Seepage	0.22
		Seepage	0.22	Slope	0.04
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MoE2—Miami loam, 15 to 25 percent slopes, eroded					
Miami	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MpC3—Miami clay loam, 6 to 12 percent slopes, severely eroded					
Miami, severely eroded	97	Somewhat limited		Somewhat limited	
		Wetness	0.97	Wetness	0.97
		Slope	0.63	Slope	0.04
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MpD3—Miami clay loam, 12 to 18 percent slopes severely eroded					
Miami, severely eroded	90	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Mr--Milford silty clay loam, pothole					
Milford	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MtA--Millbrook silt loam, till substratum, 0 to 2 percent slopes					
Millbrook	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MuC2--Montmorenci-Barce complex, 6 to 12 percent slopes, eroded					
Montmorenci	60	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Slope	0.63	Slope	0.04
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Barce	30	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Slope	0.63	Dusty	0.05
		Dusty	0.05	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MvE2--Morley silt loam, moderately wet, 15 to 25 percent slopes, eroded					
Morley	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Wetness	1.00	Wetness	1.00
		Dusty	0.07	Dusty	0.07
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
MwC3—Morley silty clay loam, moderately wet, 6 to 12 percent slopes, severely eroded					
Morley, severely eroded	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.63	Dusty	0.08
		Dusty	0.08	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
MxC2—Morley-Cadiz silt loams, moderately wet, 6 to 12 percent slopes, eroded					
Morley	55	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.63	Dusty	0.07
		Dusty	0.07	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Cadiz	35	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Slope	0.37	Dusty	0.08
		Dusty	0.08	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
MyA—Mudlavia gravelly silt loam, 0 to 2 percent slopes, stony					
Mudlavia	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Unstable excavation walls	0.98	Unstable excavation walls	0.98
		Dusty	0.06	Dusty	0.06
MzB2—Mudlavia cobbly silt loam, 2 to 4 percent slopes, eroded, stony					
Mudlavia	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Unstable excavation walls	0.98	Unstable excavation walls	0.98
		Dusty	0.06	Dusty	0.06

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
OcA—Ockley silt loam, 0 to 2 percent slopes					
Ockley	85	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
OcB2—Ockley silt loam, 2 to 6 percent slopes, eroded					
Ockley, eroded	85	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
OpB—Ormas loamy sand, 1 to 4 percent slopes					
Ormas	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
OsA—Oshtemo coarse sandy loam, 0 to 2 percent slopes					
Oshtemo	100	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
		Dusty	0.01	Dusty	0.01
OsB—Oshtemo coarse sandy loam, 2 to 6 percent slopes					
Oshtemo	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.01	Dusty	0.01
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Pm—Peotone silty clay loam, pothole					
Peotone	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Po—Piankeshaw variant gravelly silt loam, rarely flooded					
Piankeshaw variant	100	Somewhat limited		Somewhat limited	
		Seepage	0.52	Seepage	0.52
		Flooding	0.40	Flooding	0.40
		Dusty	0.05	Dusty	0.05
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Pp—Pits, gravel					
Pits	100	Not rated		Not rated	
PrA—Proctor silt loam, 0 to 2 percent slopes					
Proctor	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	0.22	Seepage	0.22
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
PrB2—Proctor silt loam, 2 to 6 percent slopes, eroded					
Proctor	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	0.22	Seepage	0.22
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
PuA—Proctor silt loam, till substratum, 0 to 2 percent slopes					
Proctor	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
PuB2—Proctor silt loam, till substratum, 2 to 6 percent slopes, eroded					
Proctor	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Rb—Ragsdale silt loam					
Ragsdale	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RdA—Rainsville silt loam, 0 to 2 percent slopes					
Rainsville	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
RfB2—Rainsville-Williamstown-Rockfield silt loams, 2 to 6 percent slopes, eroded					
Rainsville	40	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.07	Dusty	0.07
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Williamstown	35	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Rockfield	15	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RIA—Reesville silt loam, 0 to 2 percent slopes					
Reesville	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RoA—Rockfield silt loam, 0 to 2 percent slopes					
Rockfield	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RoB2—Rockfield silt loam, 2 to 6 percent slopes, eroded					
Rockfield	90	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
RpG—Rodman gravelly loam, 25 to 60 percent slopes					
Rodman	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00
		Sand content	0.96	Sand content	0.96
		Unstable excavation walls	0.77	Unstable excavation walls	0.77
		Dusty	0.02	Dusty	0.02
RtA—Rush silt loam, 0 to 2 percent slopes					
Rush	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
RtB2—Rush silt loam, 2 to 6 percent slopes, eroded					
Rush	90	Very limited		Very limited	
		Seepage	1.00	Seepage	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Sb—Sable silty clay loam					
Sable	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
SeA—Shadeland variant silt loam, 0 to 2 percent slopes					
Shadeland variant	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
SIA—Starks silt loam, till substratum, 0 to 2 percent slopes					
Starks	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Sr—Stonelick-Moundhaven complex, frequently flooded					
Stonelick	55	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Seepage	0.52	Seepage	0.52
		Dusty	0.03	Dusty	0.03
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Moundhaven	35	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Seepage	1.00	Seepage	1.00
		Too sandy	1.00	Too sandy	1.00
		Unstable excavation walls	0.09	Unstable excavation walls	0.09
StB3—Strawn clay loam, 2 to 6 percent slopes, severely eroded					
Strawn, severely eroded	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
StC3—Strawn clay loam, 6 to 12 percent slopes, severely eroded					
Strawn, severely eroded	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.63	Dusty	0.06
		Dusty	0.06	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
SyB—Symerton-Varna silt loams, 1 to 3 percent slopes					
Symerton	50	Somewhat limited		Somewhat limited	
		Wetness	0.90	Wetness	0.90
		Dusty	0.04	Dusty	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Varna	35	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
TuC2—Tuscola loam, till substratum, 6 to 12 percent slopes, eroded					
Tuscola	90	Somewhat limited		Somewhat limited	
		Wetness	0.94	Wetness	0.94
		Slope	0.37	Dusty	0.05
		Dusty	0.05	Unstable excavation walls	0.01
		Unstable excavation walls	0.01		
TwB2—Tuscola silt loam, till substratum, 2 to 6 percent slopes, eroded					
Tuscola	90	Somewhat limited		Somewhat limited	
		Wetness	0.94	Wetness	0.94
		Dusty	0.07	Dusty	0.07
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Ud—Udorthents, loamy					
Udorthents	100	Not rated		Not rated	
Ur—Udorthents, loamy, reclaimed					
Udorthents	100	Not rated		Not rated	
W—Water					
Water	100	Not rated		Not rated	

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Wc--Wakeland Variant silt loam, occasionally flooded					
Wakeland variant	100	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	0.52	Seepage	0.52
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.08	Dusty	0.08
We--Walkkill variant silty clay loam					
Walkkill variant, drained	90	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Organic matter content	1.00	Organic matter content	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Seepage	0.16	Seepage	0.16
Wg--Warners variant silty clay, drained					
Warners variant	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Water gathering surface	0.50	Water gathering surface	0.50
		Adsorption	0.25	Adsorption	0.25
Wh--Washtenaw silt loam					
Washtenaw	100	Very limited		Very limited	
		Ponding	1.00	Ponding	1.00
		Wetness	1.00	Wetness	1.00
		Water gathering surface	0.33	Water gathering surface	0.33
		Dusty	0.08	Dusty	0.08
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
WIA--Waupecan silt loam, moderately wet, 0 to 2 percent slopes					
Waupecan	90	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Seepage	1.00	Seepage	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
WpG--Weikert Variant fine sandy loam, 35 to 80 percent slopes, very bouldery					
Weikert variant	100	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	0.52	Seepage	0.52
		Dusty	0.02	Dusty	0.02
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
WrA--Williamsport-Elliott silt loams, 0 to 2 percent slopes					
Williamsport	55	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Elliott	35	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Dusty	0.06	Dusty	0.06
		Unstable excavation walls	0.04	Unstable excavation walls	0.04

Selected Soil Interpretations--Warren County, Indiana					
Map symbol and soil name	Pct. of map unit	Dhs - catastrophic mortality, large animal disposal, pit		Dhs - catastrophic mortality, large animal disposal, trench	
		Rating class and limiting features	Value	Rating class and limiting features	Value
WtC2--Williamstown-Rainsville silt loams, 6 to 12 percent slopes, eroded					
Williamstown	60	Very limited		Very limited	
		Wetness	1.00	Wetness	1.00
		Slope	0.63	Dusty	0.06
		Dusty	0.06	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01
Rainsville	30	Somewhat limited		Somewhat limited	
		Wetness	0.99	Wetness	0.99
		Slope	0.63	Dusty	0.06
		Dusty	0.06	Slope	0.04
		Unstable excavation walls	0.01	Unstable excavation walls	0.01

Data Source Information

Soil Survey Area: Warren County, Indiana
 Survey Area Data: Version 17, Sep 15, 2014