

Leaching Index

Linn County, Kansas

Map Symbol	Soil Name	Map Unit Name	Hydrologic Group	OM %	kfact	Leaching Potential
7677	Welda	Welda silt loam, 2 to 5 percent slopes	C	0.75	0.37	Low
8101	Hepler	Hepler silt loam, occasionally flooded	C	1.50	0.37	Intermediate
8150	Lanton	Lanton silt loam, occasionally flooded	C	3.00	0.37	Intermediate
8201	Osage	Osage silty clay loam, occasionally flooded	D	3.50	0.37	High
8203	Osage	Osage silty clay, occasionally flooded	D	3.00	0.28	High
8301	Verdigris	Verdigris silt loam, 0 to 1 percent slopes, frequently flooded	B	3.00	0.37	Low
8302	Verdigris	Verdigris silt loam, occasionally flooded	B	3.00	0.32	Low
8501	Mason	Mason silt loam, rarely flooded	B	2.00	0.37	Low
8621	Bates	Bates loam, 1 to 3 percent slopes	C	2.50	0.28	Low
8623	Bates	Bates loam, 3 to 7 percent slopes	C	2.50	0.28	Low
8630	Brazilton	Brazilton silty clay loam, 1 to 3 percent slopes	D	2.00	0.37	Low
8661	Eram	Clareson-Eram silty clay loams, 3 to 15 percent slopes	C	2.00	0.37	Low
8661	Clareson	Clareson-Eram silty clay loams, 3 to 15 percent slopes	C	3.00	0.32	Low
8663	Clareson	Clareson-Rock outcrop complex, 3 to 15 percent slopes	C	3.00	0.32	Low
8670	Coalvale	Coalvale silty clay, 1 to 5 percent slopes	D	4.00	0.15	Low
8671	Collinsville	Collinsville complex, 3 to 15 percent slopes	D	2.00	0.28	Low
8671	Bates	Collinsville complex, 3 to 15 percent slopes	B	2.50	0.32	Low
8679	Dennis	Dennis silt loam, 1 to 3 percent slopes	C	2.50	0.43	Intermediate
8683	Dennis	Dennis silt loam, 3 to 7 percent slopes	C	2.00	0.43	Intermediate
8733	Eram	Eram silty clay loam, 1 to 3 percent slopes	C	3.00	0.37	Intermediate
8735	Eram	Eram silty clay loam, 3 to 7 percent slopes	C	2.00	0.37	Intermediate
8745	Eram	Eram-Clareson complex, 1 to 15 percent slopes	C	2.50	0.37	High
8745	Clareson	Eram-Clareson complex, 1 to 15 percent slopes	C	3.50	0.32	High
8755	Lebo	Eram-Lebo silty clay loams, 5 to 20 percent slopes	B	4.00	0.37	Intermediate

Leaching Index

Linn County, Kansas

Map Symbol	Soil Name	Map Unit Name	Hydrologic Group	OM %	kfact	Leaching Potential
8755	Eram	Eram-Lebo silty clay loams, 5 to 20 percent slopes	C	2.00	0.37	Intermediate
8771	Kanima	Kanima silty clay loam, 15 to 50 percent slopes	C	0.75	0.24	Low
8775	Kenoma	Kenoma silt loam, 1 to 3 percent slopes	D	3.25	0.43	High
8789	Lebo	Lebo channery silty clay loam, 15 to 30 percent slopes	B	4.00	0.37	Low
8847	Okemah	Okemah silt loam, 0 to 3 percent slopes	C	2.00	0.43	Intermediate
8863	Parsons	Parsons silt loam, 0 to 1 percent slopes	D	3.30	0.43	High
8909	Talihina	Stony land-Talihina complex, 15 to 45 percent slopes	D	2.00	0.32	Low
8911	Summit	Summit silty clay loam, 1 to 3 percent slopes	C	3.00	0.37	Intermediate
8912	Summit	Summit silty clay loam, 3 to 7 percent slopes	C	3.00	0.37	Intermediate
8961	Woodson	Woodson silt loam, 0 to 1 percent slopes	D	2.50	0.49	High
8962	Woodson	Woodson silt loam, 1 to 3 percent slopes	D	2.50	0.49	High
9970	Aquolls	Aquolls	B/D			High
MT250B	Aliceville	Aliceville silty clay loam, 1 to 3 percent slopes	D	4.49	0.28	Intermediate
MT324B	Bucyrus	Bucyrus silty clay loam, 1 to 3 percent slopes	C	4.49	0.32	Intermediate
MT328C	Bucyrus	Bucyrus silty clay loam, 3 to 8 percent slopes	B	4.49	0.37	Intermediate
MT850B	Wagstaff	Wagstaff silty clay loam, 1 to 3 percent slopes	D	5.00	0.28	Low

This report produces Leaching Index Values (1, 2 and 3) suitable for use as described in Part 539.58 - National Ranking Factor N2, Subfactor B in the CRP Manual.

The values 1, 2 and 3 are derived by using the same algorithm included in the SSSD RV Generator to produce values 1, 2, 3 and 4 but this report reverses the order of meaning and combines values 3 and 4. Thus, this report correctly reports 1 as low, 2 as medium, and 3 as high. These values are ready for use in determining signup scores for National ranking subfactor N2 without further code conversion.