



Natural Resources Conservation Service  
P.O. Box 1458  
Bismarck, ND 58502-1458

---

April 18, 2013

## TECHNICAL GUIDE NOTICE ND-141

### Section I

The [Soil Survey Interpretive Ratings for Subsurface Water Management](http://websoilsurvey.nrcs.usda.gov/app/HomePage.htm) brochure explains the subsurface water management interpretations and identifies soils property and site limitations to consider for tile drainage. The interpretations are in Web Soil Survey, at <http://websoilsurvey.nrcs.usda.gov/app/HomePage.htm>, and can be used to evaluate and identify soil limitations related to the installation, performance, and outflow quality of subsurface water management systems. These soil suitability ratings are available for use in the North Dakota portions of MRLAs 53A, 53B, 55A, 55B, 56, and 102A.

The link to the *Soil Survey Interpretive Ratings for Subsurface Water Management* brochure is located in FOTG - Section I – Reference Subjects – Soil. Question may be directed to Wade Bott, State Soil Scientist, at 701-530-2021 or [wade.bott@nd.usda.gov](mailto:wade.bott@nd.usda.gov).

\s\

TODD A. SCHWAGLER  
State Resource Conservationist

Distribution: All FOTG Holders

