

## PART 544 EQUIPMENT

### Subpart A - Adjustment, Calibration, and Maintenance

NE544.03

#### §NE544.02 Adjustment and Calibration

Levels and transits will be checked and adjusted at least annually. If the equipment is either dropped or suspected to be out of adjustment, it will also be checked and adjusted prior to use. Form NE-ADS-4 will be kept in the instrument box; and all checks, adjustments, cleaning or repairs will be shown on the form.

#### §NE544.03 Maintenance

Levels that aren't self leveling and transits that aren't theodolites may be cleaned and repaired by qualified SCS personnel. Self leveling instruments and theodolites should be cleaned and repaired by qualified private vendors or the manufacturer.