



Natural Resources Conservation Service  
Nebraska State Office  
Federal Building, Room 152  
100 Centennial Mall North  
Lincoln, NE 68508-3866  
(402) 437-5300

<http://www.ne.nrcs.usda.gov>  
February 9, 2011

TECHNICAL GUIDE NOTICE NO. 623

This notice transmits updates to Section II – Cultural Resources Information and Section IV – Practice Standards and Specifications in the Field Office Technical Guide (FOTG).

**SECTION II - Cultural Resources Information**

Part 10, Practices and Potential Effects to Cultural Resources has been added to the Table of Contents. Roof Runoff Structure (558) Effects will be located under this folder.

If you have any questions, contact Elisha Mackling, State Cultural Resources Specialist at (402) 437-4128 or [Elisha.mackling@ne.usda.gov](mailto:Elisha.mackling@ne.usda.gov).

**SECTION IV – Practice Standards and Specifications**

**Access Road (560)** – Update includes minor edits required due to changes in the national standard.

**Pond Sealing or Lining, Flexible Membrane (521A)** – Update includes edits required due to changes in the national standard. State standard requires padding beneath liner to protect from puncture and venting to relieve gas build up.

**Roof Runoff Structure (558)** – This is a new state standard and generally will apply to instances where roof runoff needs to be collected and redirected away from an animal waste storage facility. Roof runoff structure is classified within Section IV Practice Standards and Specifications Table of Contents as a practice that must be reviewed (+) to determine potential effects to cultural resources.

If you have any questions about these standards, contact Kevin Gustafson, ASCE, at (402) 437-4042 or [Kevin.gustafson@ne.usda.gov](mailto:Kevin.gustafson@ne.usda.gov).

Changes for all field offices are noted by "**ALL COUNTIES**" and should be made in all Field Office Technical Guides.

DIST: allemp

*Helping People Help the Land*

An Equal Opportunity Provider and Employer



<b>REMOVE AND RECYCLE</b>	<b>INSERT</b>
<b>ALL COUNTIES</b>	<b>ALL COUNTIES</b>
Section II – Natural Resources Information Table of Contents T.G. Notice 622 January 2011	Section II – Natural Resources Information <a href="#">Table of Contents</a> T.G. Notice 623 February 2011
<b>ALL COUNTIES</b>	<b>ALL COUNTIES</b>
Section II – Subsection II - Cultural Resources Information Table of Contents T.G. Notice 613 May 2010	Section II – Subsection II - Cultural Resources Information <a href="#">Table of Contents</a> T.G. Notice 623 February 2011
<b>ALL COUNTIES</b>	<b>ALL COUNTIES</b>
NONE	Section II – Subsection II - Cultural Resources Information, 10. Practices and Potential Effects to Cultural Resources, <a href="#">Roof Runoff Structure (558) Effects</a> T.G. Notice 623 February 2011
<b>ALL COUNTIES</b>	<b>ALL COUNTIES</b>
Section IV – Practice Standards and Specifications Table of Contents T.G. Notice 622 January 2011	Section IV – Practice Standards and Specifications <a href="#">Table of Contents</a> T.G. Notice 623 February 2011
<b>ALL COUNTIES</b>	<b>ALL COUNTIES</b>
Section IV – Practice Standards and Specifications Access Road (560) T.G. Notice 520 July 2002	Section IV – Practice Standards and Specifications <a href="#">Access Road (560)</a> T.G. Notice 623 February 2011
<b>ALL COUNTIES</b>	<b>ALL COUNTIES</b>
Section IV – Practice Standards and Specifications Pond Sealing or Lining, Flexible Membrane (521A) T.G. Notice 488 August 2000	Section IV – Practice Standards and Specifications <a href="#">Pond Sealing or Lining, Flexible Membrane (521A)</a> T.G. Notice 623 February 2011
<b>ALL COUNTIES</b>	<b>ALL COUNTIES</b>
NONE	Section IV – Practice Standards and Specifications <a href="#">Roof Runoff Structure (558)</a> T.G. Notice 623 February 2011

/s/

CRAIG DERICKSON  
State Conservationist