

NATURAL RESOURCES CONSERVATION SERVICE
VIRGINIA CONSERVATION PRACTICE STANDARD

LAND RECLAMATION
TOXIC DISCHARGE CONTROL

(No.)

CODE 455

DEFINITION

Control of acid or otherwise toxic aqueous discharge from abandoned coal mines or coal-mine waste.

PURPOSE

To improve water quality, eliminate unsightly residues, reduce erosion, and restore areas to beneficial use.

CONDITIONS WHERE PRACTICE APPLIES

This standard applies to locations where acid or toxic drainage is degrading water quality and the environment in and adjacent to streams, lakes, reservoirs, or wetlands.

CRITERIA

There are four primary methods for controlling toxic mine drainage: (1) mine sealing, (2) infiltration control, (3) "daylighting," and (4) neutralization and precipitation.

Mine sealing. This method is usually used to reduce the amount of water entering or to promote inundation by water of underground mine workings to reduce or prevent oxidation of pyritic materials.

In locations where air and surface water enter underground mines, use Virginia Conservation Practice Standard *Mine Shaft and Adit Closing* (Code 452). Use diversions or drains to keep water from entrances. Reducing the amount of water entering the mine may solve the problem.

In the inundation process, physical barriers are constructed in the mine opening to control the escape of water. Sealing mines to reduce acid mine drainage by constructing wet seals at the mouths of mine portal drain ways provide air locks while allowing water to discharge. These seals must be designed to withstand maximum expected hydrostatic heads and be constructed of suitable materials such as masonry, concrete, grouted limestone, or clay.

Infiltration control. This method is designed to reduce the amount of water entering toxic surface materials. Surface mine overburden and deep mine refuse can be reshaped for better surface drainage and blanketed with compacted, slowly permeable soil materials to deter infiltration. Diversions, underground outlets, lined waterways, and grade stabilization structures can be used to control surface runoff or divert clean upslope runoff. All surfaces should be left with positive grades. Blanketing with pulverized limestone before revegetating may increase the pH of the infiltrate. Surface soils shall be amended as necessary to promote a healthy root environment for planned vegetation.

Another method of infiltration control is designed to prevent or reduce surface water from entering deep mines. This condition usually occurs where the bedrock has been fractured due to underground mining, allowing stream flow directly into deep mine workings. Two methods frequently used to control this type of infiltration are grouting of the streambed and piping the stream through the affected area.

Daylighting. This practice consists of surface mining the existing underground coal, selectively placing toxic materials, regrading and vegetating the area, and diverting water to natural drainage ways. This method may work on surface mines if deeper coal seams are present that can be economically mined.

Neutralization and Precipitation. One method of treating acidic mine drainage is the chemical addition of alkaline material. By selecting the proper alkaline agent, many metal cations can be removed during neutralization as insoluble hydroxides. Several alkaline materials are available, such as hydrated lime ($\text{Ca}(\text{OH})_2$), caustic soda (NaOH), and limestone. A properly sized settling basin shall be provided to allow for the precipitation of metals. Chemical treatment is the least desirable measure for long term treatment of acidic water because of the long-term nature of the action and the excessive operation and maintenance costs involved.

Passive treatment is the most frequently used long-term method for treating acidic mine drainage. Vertical flow wetlands and anoxic limestone drains are two commonly used passive systems to neutralize acidity and provide collection of precipitated metals. Both of these systems rely upon extended contact of acid waters with high calcium carbonate limestone. The type of system used is based on the chemistry and volume of the raw mine water. The size of each component within the treatment system is based on the design flow rate.

Net alkaline discharges can usually be treated by providing adequate detention time to precipitate contaminating metals.

Site Investigations. Site investigations shall include the following items:

1. Mine water quality and flow rates.
2. Geologic environment of the immediate area, including characteristics of overburden such as lithology, faults, joints and attitude.
3. Surface and subsurface hydrologic conditions.
4. Mining history.
5. Land use.

6. Post mining history and conditions.
7. Soils investigation.
8. Topography.
9. Spatial and stratigraphic location of pyrites and other sulfides
10. Availability of high quality limestone or other alkaline material.
11. Availability of blanketing materials.
12. Use of water.

CONSIDERATIONS

In drainage systems, pipes should be used with caution because of the potential of breaking and/or misalignment with soil movement on site.

Consider visual resource with other design features during planning, design, and installation. All disturbed areas can be reshaped and regarded to blend in with the surrounding land features.

Appropriate reagent mixing or dispensing/metering equipment should be used.

PLANS AND SPECIFICATIONS

Plans and specifications for toxic discharge control shall be in keeping with this standard and shall describe the requirements for applying the practice to achieve its intended purpose.

Record all required information in an engineer field book, on a plan sheet or design computation sheet, or in another appropriate location.

DESIGN DATA

1. Completed Environmental Evaluation (Form VA-EE-1) and subsequent requirements.
2. Site investigation.
3. Survey and plot data: profile, cross-sections, topography, as needed.
4. Design computations, including purpose of practice and references used.

- a. Specific alkaline agent to be used for neutralization, if needed.
- b. Details for handling, disposal, and/or utilization of precipitated metals.
5. Plan view of site with existing and planned features, including dimensions, distances, etc.
6. Standard Cover Sheet (VA-SO-100A).
7. Materials and quantities needed. Identify borrow material and/or spoil area, as needed.
8. Vegetation and/or ground cover requirements.
9. Identification of needed Erosion & Sediment Control measures.
10. Supplemental practices required.
11. Virginia Conservation Practice Specifications (700 Series) or NEH, Part 642, Specifications for Construction Contracts.
12. Operation and Maintenance Plan.
13. Safety Plan, if needed, including construction and post-construction components.

CHECK DATA

1. As-built survey.
2. As-built plans including dimensions, types and quantities of materials installed, and variations from design. Include justification for variations.
3. Locations of appurtenant practices.
4. Adequacy of vegetation and/or ground cover.
5. Complete as-built section of Cover Sheet.

OPERATION AND MAINTENANCE

A specific operation and maintenance plan shall be developed for each long term treatment system. The plan will outline the flushing sequence to allow removal of

accumulated metals and inert material from passive treatment systems.

A monitoring plan shall be developed to assess the efficiency and performance of the treatment system. It is recommended that water samples be taken monthly for one year after the system is in operation and quarterly thereafter. Flow rates at all measuring points shall be recorded when samples are collected. [What should the samples be tested for and who will pay the bill? And what will happen if the sample falls into an unacceptable (but not currently defined) range? Query sent to Wayne Bogovich 6-11-09]

Accumulated precipitate shall be removed from the treatment system components when capacity is reduced by one half. Disposal shall be done in an environmentally safe manner.

REFERENCES

Pennsylvania Department of Environmental Protection, Bureau of Abandoned Mine Reclamation. "The Science of Acid Mine Drainage and Passive Treatment." 1999.

Kepler, D. A., and E. C. McCleary. 1994. Successive alkalinity-producing systems (SAPS) for the treatment of acidic mine drainage. pp 195-204 *in* Volume 1 of Proceedings of the International Land Reclamation and Mine Drainage Conference and the Third International Conference on the Abatement of Acidic Drainage, Pittsburgh, PA, April 24 – 29, 1994.

Skovran, G. A. and C. R. Clouser. 1998. Design Considerations and Construction Techniques for Successive Alkalinity Producing Systems. pp 235 – 242 *in* Proceedings of the American Society for Surface Mining and Reclamation Annual Conference, St. Louis, MO, May 17 – 21, 1998.

Pennsylvania's Efforts to Address Operation, Maintenance and Replacement of AMD Passive Treatment Systems. Milavec, P.A. and D.R. Seibert. Proceedings from National Association of Abandoned Mine Land Programs Conference in Park City, UT, Sept. 15-18, 2002.

USDA-Natural Resources Conservation Service. Electronic Field Office Technical Guide (eFOTG), Section IV [Online]. Available at <http://www.nrcs.usda.gov/technical/eFOTG>.

USDA-Natural Resources Conservation Service. Virginia 700 Series Construction

Specifications. [On-line]. Available at <http://www.nrcs.usda.gov/technical/eFOTG>.

USDA-Natural Resources Conservation Service. NEH, Part 642, Specifications for Construction Contracts.

The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer.