

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
AD: ADEL-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
AF: AGUA FRIA-----	90	Not limited		Not limited		Not limited	
AG: ALLUVIAL LAND, GRAVELLY-----	80	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Minerology class Flooding	1.00	Not rated Not rated Not rated Not rated Flooding Depth to saturated zone	1.00 1.00	Not rated Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Depth to saturated zone	1.00
AL: ALLUVIAL LAND-----	80	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Minerology class Flooding	1.00	Not rated Not rated Not rated Not rated Flooding Depth to saturated zone	1.00 1.00	Not rated Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Depth to saturated zone	1.00
AM: ALLUVIAL LAND-----	85	Not rated Not rated; SAR Not rated; pH		Not rated Not rated Not rated		Not rated Not rated Not rated	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
AM: continued ALLUVIAL LAND		Not rated		Not rated		Not rated; Minerology class	
		Not rated; Minerology class		Flooding	1.00	Not rated: Unified or minerology class	
		Flooding	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
An: ANCHO-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Ao: ANCHO-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.68
		Too clayey	0.50			Too clayey	0.50
AP: APACHE-----	90	Very limited Depth to bedrock Content of large stones	1.00 0.45	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Content of large stones	1.00 0.45
BA: BADLAND-----	95	Not rated		Not rated		Not rated	
		Not rated; SAR Not rated; pH Not rated		Not rated Not rated Not rated		Not rated Not rated Not rated; Minerology class	
		Not rated; Minerology class		Slope	1.00	Not rated: Unified or minerology class	
		Slope	1.00			Depth to bedrock	1.00

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BD: BASALT ROCK LAND-----	100	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Not rated Slope		Not rated Not rated Not rated Not rated; Minerology class Not rated; Unified or minerology class Not rated; Fragments > 75mm	
Be: BLUEWING-----	90	Very limited Too Sandy	1.00	Not limited		Very limited Too Sandy Seepage Gravel content	1.00 1.00 1.00
Bf: BLUEWING-----	90	Very limited Depth to saturated zone Too Sandy Flooding	1.00 1.00 0.40	Very limited Depth to saturated zone Flooding	1.00 0.40	Very limited Too Sandy Seepage Gravel content Depth to saturated zone	1.00 1.00 0.86
Bg: BLUEWING-----	90	Very limited Too Sandy	1.00	Not limited		Very limited Too Sandy Seepage Gravel content	1.00 1.00 1.00

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BH: BLUEWING-----	90	Very limited Too Sandy	1.00	Not limited		Very limited Too Sandy Seepage Gravel content	1.00 1.00 1.00
BM: BOBTAIL-----	90	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage Gravel content	1.00 1.00 1.00 0.01
BO: BOBTAIL-----	60	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage Gravel content	1.00 1.00 1.00 0.01
ROCK OUTCROP-----	25	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Slope		Not rated Not rated Not rated; Minerology class Not rated; Unified or minerology class Not rated; Fragments > 75mm	
BR: BORREGO-----	90	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CA: CALABASAS-----	90	Not limited		Not limited		Not limited	
CB: CALABASAS-----	95	Somewhat limited Slope	0.16	Somewhat limited Slope	0.16	Somewhat limited Slope	0.16
CC: CAPILLO-----	80	Very limited Depth to bedrock Seepage Slope	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 0.42	Very limited Slope Depth to bedrock	1.00 0.42
CE: CAPILLO-----	55	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 0.42	Very limited Slope Depth to bedrock	1.00 0.42
ROCK OUTCROP-----	25	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Not rated Slope	1.00	Not rated Not rated Not rated; Minerology class Not rated; Unified or minerology class Not rated; Fragments > 75mm	
Cf: CERRILLOS-----	90	Not limited		Not limited		Not limited	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CG: CERRILLOS-----	90	Not limited		Not limited		Not limited	
Ch: CERRILLOS-----	95	Not limited		Not limited		Not limited	
CM: CHIMAYO-----	90	Not rated Not rated Slope Depth to bedrock Content of large stones	 1.00 1.00 1.00	Very limited Slope Depth to bedrock	 1.00 1.00	Very limited Depth to bedrock Slope Content of large stones	 1.00 1.00 1.00
CO: CLOVIS-----	80	Not limited		Not limited		Somewhat limited Seepage	 0.52
CU: CUEVA-----	85	Very limited Slope Depth to bedrock	 1.00 1.00	Very limited Slope	 1.00	Very limited Depth to bedrock Slope	 1.00 1.00
CV: CUNDIYO-----	90	Very limited Slope Seepage Content of large stones	 1.00 1.00 1.00	Very limited Slope Seepage	 1.00 1.00	Very limited Slope Content of large stones Seepage	 1.00 1.00 0.52
DP: DEAN-----	70	Not limited		Not limited		Somewhat limited Gravel content	 0.11
PASTURA-----	20	Somewhat limited Depth to thin cemented pan	 0.50	Not limited		Very limited Depth to cemented pan	 1.00

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Ec: EL RANCHO-----	90	Not limited		Not limited		Not limited	
Ed: EL RANCHO-----	90	Not limited		Not limited		Not limited	
Ee: EL RANCHO-----	85	Not limited		Not limited		Not limited	
Eh: EL RANCHO VARIANT---	90	Very limited Too Sandy	1.00	Not limited		Very limited Too Sandy Seepage Gravel content	1.00 1.00 0.65
EL: EL RANCHO-----	65	Not limited		Not limited		Not limited	
FRUITLAND-----	25	Not limited		Not limited		Somewhat limited Seepage	0.52
EN: ENCIERRO-----	90	Very limited Depth to bedrock Slope	1.00 0.16	Very limited Depth to bedrock Slope	1.00 0.16	Very limited Depth to bedrock Hard to compact Slope	1.00 1.00 0.16
Fe: FIVEMILE-----	90	Not limited		Not limited		Not limited	
FF: FIVEMILE-----	90	Not limited		Not limited		Not limited	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
FG: FORTWINGATE VARIANT-	85	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 0.42	Very limited Slope Depth to bedrock	1.00 0.42
Fn: FRUITLAND-----	90	Not limited		Not limited		Somewhat limited Seepage	0.52
Fr: FRUITLAND-----	90	Not limited		Not limited		Somewhat limited Seepage	0.52
Fs: FRUITLAND-----	90	Not limited		Not limited		Somewhat limited Seepage	0.52
Ft: FRUITLAND-----	90	Not limited		Not limited		Somewhat limited Seepage	0.52
GG: GALISTEO-----	70	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Hard to compact	1.00
GULLIED LAND-----	15	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Minerology class Flooding	 1.00	Not rated Not rated Not rated Not rated Flooding	 1.00	Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
GL: GUAJE-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Seepage Gravel content Slope	1.00 1.00 1.00
HA: HAGERMAN-----	85	Very limited Depth to bedrock	1.00	Not limited		Very limited Depth to bedrock	1.00
HC: HARVEY-----	80	Not limited		Not limited		Not limited	
HD: HARVEY-----	60	Not limited		Not limited		Not limited	
DEAN-----	30	Not limited		Not limited		Very limited Depth to cemented pan Carbonate content	1.00 1.00
HP: HARVEY-----	45	Not limited		Not limited		Not limited	
PENISTAJA-----	35	Not limited		Not limited		Somewhat limited Seepage	0.52
HR: HARVEY-----	40	Not limited		Not limited		Not limited	
CERRILLOS-----	30	Not limited		Not limited		Not limited	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
LB: LA BRIER-----	90	Somewhat limited Too clayey Flooding	0.50 0.40	Somewhat limited Flooding	0.40	Very limited Hard to compact Too clayey	1.00 0.50
Lf: LA FONDA-----	95	Not limited		Not limited		Not limited	
Lg: LAPORTE-----	65	Not rated Not rated; Fragments > 75mm Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00	Not rated Not rated; Fragments > 75mm Depth to bedrock Gravel content Slope	1.00 1.00 1.00 1.00
ROCK OUTCROP-----	25	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Not rated Slope	1.00	Not rated Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	
LH: LAPORTE-----	65	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.01

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
LH: continued ROCK OUTCROP-----	25	Not rated Not rated; SAR Not rated; pH Not rated		Not rated Not rated Not rated Not rated		Not rated Not rated Not rated Not rated;	
ROCK OUTCROP		Not rated; Fragments > 75mm		Slope	1.00	Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	
LL: LAS LUCAS-----	90	Very limited Depth to bedrock	1.00	Not limited		Somewhat limited Depth to bedrock	0.42
LS: LOS ALAMOS-----	55	Very limited Depth to bedrock	1.00	Not limited		Somewhat limited Depth to bedrock	1.00
SILVER-----	35	Not limited		Not limited		Very limited Hard to compact	1.00
LU: LUNCH VARIANT-----	90	Very limited Depth to saturated zone Flooding	1.00 0.40	Very limited Depth to saturated zone Flooding	1.00 0.40	Somewhat limited Gravel content Depth to saturated zone	0.98 0.86
MA: MAJADA-----	90	Very limited Slope Content of large stones	1.00 0.04	Very limited Slope	1.00	Very limited Slope Gravel content Content of large stones	1.00 0.37 0.04

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
MC: MCVICKERS VARIANT---	90	Somewhat limited Slope Too clayey	0.84 0.50	Somewhat limited Slope	0.84	Somewhat limited Slope Too clayey Hard to compact	0.84 0.50 0.50
MD: MIRABAL-----	90	Very limited Depth to bedrock Seepage Content of large stones Slope	1.00 1.00 1.00 1.00	Very limited Seepage Depth to bedrock Slope	1.00 1.00 1.00	Very limited Depth to bedrock Content of large stones Slope Seepage	1.00 1.00 1.00 0.52
ME: MIRABAL-----	90	Very limited Slope Depth to bedrock Seepage Content of large stones	1.00 1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Content of large stones Seepage	1.00 1.00 1.00 0.52
MF: MIRABAL-----	60	Very limited Slope Depth to bedrock Seepage Content of large stones	1.00 1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Content of large stones Seepage	1.00 1.00 1.00 0.52
ROCK OUTCROP-----	30	Not rated Not rated; SAR Not rated; pH		Not rated Not rated Not rated		Not rated Not rated Not rated	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
MF: continued ROCK OUTCROP		Not rated		Not rated		Not rated;	
		Not rated; Fragments > 75mm		Slope	1.00	Minerology class	
		Not rated; Minerology class				Not rated: Unified or minerology class	
						Not rated; Fragments > 75mm	
MG: MONTOSO-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Seepage	1.00
						Gravel content	1.00
						Slope	1.00
MH: MONTOSO-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
						Seepage	1.00
						Gravel content	1.00
MO: MORIARTY-----	90	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Hard to compact	1.00
NA: NAMBE-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
		Seepage	1.00	Seepage	1.00	Content of large stones	0.62
		Content of large stones	0.62			Seepage	0.52
						Gravel content	0.01

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
NB: NAMBE-----	90	Very limited Slope Seepage Content of large stones	1.00 1.00 0.89	Very limited Slope Seepage	1.00 1.00	Very limited Slope Content of large stones Seepage	1.00 0.89 0.52
NE: NAMBE-----	90	Very limited Slope Seepage Content of large stones	1.00 1.00 0.87	Very limited Slope Seepage	1.00 1.00	Very limited Slope Content of large stones Seepage	1.00 0.87 0.52
NM: NAMBE-----	65	Very limited Slope Seepage Content of large stones	1.00 1.00 0.87	Very limited Slope Seepage	1.00 1.00	Very limited Slope Content of large stones Seepage	1.00 0.87 0.52
ROCK OUTCROP-----	25	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Not rated Slope	1.00	Not rated Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
NR: NAMBE-----	65	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Content of large stones Seepage	1.00 0.87 0.52
ROCK OUTCROP-----	25	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Slope	1.00	Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	
OG: ORTIZ-----	90	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Slope	1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.11
OP: OTERO-----	40	Not limited		Not limited		Somewhat limited Seepage	0.52
PALMA-----	40	Not limited		Not limited		Somewhat limited Seepage	0.52
Pa: PANKY-----	90	Not limited		Not limited		Not limited	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
PB: PANKY-----	90	Not limited		Not limited		Not limited	
PC: PENA-----	85	Somewhat limited Slope Content of large stones	0.84 0.28	Somewhat limited Slope	0.84	Somewhat limited Slope Content of large stones Gravel content	0.84 0.28 0.01
PD: PENISTAJA-----	90	Not limited		Not limited		Not limited	
PE: PENITENTE-----	90	Very limited Content of large stones Slope	1.00 1.00	Very limited Slope	1.00	Very limited Content of large stones Slope	1.00 1.00
PH: PERSAYO-----	60	Very limited Depth to bedrock Slope	1.00 0.96	Somewhat limited Slope	0.96	Very limited Depth to bedrock Slope Gravel content	1.00 0.96 0.21
SHALE ROCK LAND-----	30	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Slope	0.96	Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
PK: POJOAQUE-----	60	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope Gravel content	1.00 0.26
PANKY-----	35	Not limited		Not limited		Not limited	
Pm: POJOAQUE-----	50	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope Gravel content	1.00 0.26
ROUGH BROKEN LAND---	40	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Slope	1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 0.52
PN: POJOAQUE-----	50	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope Gravel content	1.00 0.26
ROUGH BROKEN LAND---	40	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Slope	1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 0.52
PR: PREWITT-----	90	Somewhat limited Too clayey Flooding	0.50 0.40	Somewhat limited Flooding	0.40	Somewhat limited Too clayey	0.50

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
RD: REDNUN-----	90	Not limited		Not limited		Not limited	
RE: REDNUN-----	50	Not limited		Not limited		Not limited	
PENA-----	30	Somewhat limited Slope	0.84	Somewhat limited Slope	0.84	Somewhat limited Gravel content Slope	0.99 0.84
RG: REDNUN-----	60	Not limited		Not limited		Not limited	
TRAVESSILLA-----	30	Very limited Depth to bedrock	1.00	Not limited		Very limited Depth to bedrock Gravel content	1.00 0.14
RH: RIVERWASH, SANDY----	90	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Minerology class Flooding	 1.00	Not rated Not rated Not rated Not rated Flooding	 1.00	Not rated Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Depth to saturated zone	 1.00
BLUEWING-----	10	Very limited Too Sandy	1.00	Not limited		Very limited Too Sandy Seepage Gravel content	1.00 1.00 1.00

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
RK: ROCK OUTCROP-----	100	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Not rated		Not rated Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	
RL: ROCK OUTCROP-----	70	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Not rated Slope	1.00	Not rated Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	
CHIMAYO-----	20	Very limited Slope Depth to bedrock Content of large stones	1.00 1.00 0.19	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Content of large stones	1.00 1.00 0.19
RO: ROCK SLIDES-----	100	Not rated Not rated; SAR Not rated; pH		Not rated Not rated Not rated		Not rated Not rated Not rated	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
RO: continued ROCK SLIDES		Not rated		Not rated		Not rated; Minerology class	
		Not rated; Minerology class		Slope	1.00	Not rated: Unified or minerology class	
		Slope	1.00			Slope	1.00
RU: ROUGH BROKEN LAND---	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00			Slope	1.00
						Seepage	0.52
SF: SANTA FE-----	45	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	1.00	Slope	1.00	Gravel content	1.00
						Slope	1.00
LA FONDA----- Sk:	45	Not limited		Not limited		Not limited	
SANTA FE-----	65	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	1.00	Slope	1.00	Gravel content	1.00
		Too clayey	0.50			Slope	1.00
						Too clayey	0.50
ROCK OUTCROP-----	25	Not rated		Not rated		Not rated	
		Not rated; SAR		Not rated		Not rated	
		Not rated; pH		Not rated		Not rated	
		Not rated		Not rated		Not rated; Minerology class	
		Not rated; Fragments > 75mm		Slope	1.00	Not rated: Unified or minerology class	
		Not rated; Minerology class				Not rated; Fragments > 75mm	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
SM: SANTA FE-----	65	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00
ROCK OUTCROP-----	25	Not rated Not rated; SAR Not rated; pH Not rated Not rated; Fragments > 75mm Not rated; Minerology class		Not rated Not rated Not rated Not rated Slope	1.00	Not rated Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	
SP: SILVER-----	50	Not limited		Not limited		Very limited Hard to compact	1.00
POJOAQUE-----	30	Not limited		Not limited		Somewhat limited Gravel content	0.26
SR: SILVER-----	90	Not limited		Not limited		Very limited Hard to compact	1.00
ST: STONY ROCK LAND-----	80	Not rated Not rated; SAR Not rated; pH Not rated		Not rated Not rated Not rated Not rated		Not rated Not rated Not rated Not rated;	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
ST: continued STONY ROCK LAND		Not rated; Fragments > 75mm		Slope	1.00	Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	
ROCK OUTCROP-----	20	Not rated; Not rated; SAR Not rated; pH Not rated		Not rated Not rated Not rated		Not rated Not rated Not rated; Minerology class Not rated: Unified or minerology class Not rated; Fragments > 75mm	
ST: continued ROCK OUTCROP		Not rated; Fragments > 75mm Not rated; Minerology class					
SU: SUPERVISOR-----	90	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 0.52
SV: SUPERVISOR-----	65	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Gravel content Seepage	1.00 1.00 0.55 0.52
ROCK OUTCROP-----	25	Not rated Not rated; SAR		Not rated Not rated		Not rated Not rated	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
SV: continued ROCK OUTCROP		Not rated; pH Not rated		Not rated Not rated		Not rated Not rated; Minerology class	
		Not rated; Fragments > 75mm		Slope	1.00	Not rated; Unified or minerology class	
		Not rated; Minerology class				Not rated; Fragments > 75mm	
TA: TAPIA-----	50	Not limited		Not limited		Not limited	
DEAN-----	30	Not limited		Not limited		Somewhat limited Gravel content	0.12
TB: TRAVESSILLA-----	50	Very limited Depth to bedrock	1.00	Not limited		Very limited Depth to bedrock	1.00
BERNAL-----	30	Very limited Depth to bedrock Too clayey	1.00 0.50	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 0.50
TR: TRAVESSILLA-----	50	Very limited Depth to bedrock Slope	1.00 0.84	Somewhat limited Slope	0.84	Very limited Depth to bedrock Slope	1.00 0.84
ROCK OUTCROP-----	25	Not rated Not rated; SAR Not rated; pH Not rated		Not rated Not rated Not rated Not rated		Not rated Not rated Not rated Not rated; Minerology class	

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
TR: continued ROCK OUTCROP		Not rated; Fragments > 75mm				Not rated: Unified or minerology class Not rated; Fragments > 75mm	
TU: TUFF ROCK LAND-----	90	Not rated; Not rated; SAR Not rated; pH Not rated		Not rated Not rated Not rated		Not rated Not rated Not rated; Minerology class	
		Not rated; Fragments > 75mm		Slope	1.00	Not rated: Unified or minerology class	
		Not rated; Minerology class				Not rated; Fragments > 75mm	
W: WATER-----	95	Not rated Not rated; Slope Not rated; SAR Not rated; pH Not rated		Not rated Not rated; Slope Not rated Not rated		Not rated Not rated; Slope Not rated Not rated; Minerology class	
		Not rated; Fragments > 75mm				Not rated: Unified or minerology class	
WC: WILCOXSON VARIANT---	90	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Hard to compact Too clayey	1.00 1.00 1.00 0.50

United States Department of Agriculture
Natural Resources Conservation Service

03/02/2004

Santa Fe Area, New Mexico, Santa Fe County and Part of Rio Arriba County
Table ENG-6.--Sanitary Facilities

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
WL: WILLARD-----	90	Not limited		Not limited		Not limited	
WN: WITT-----	90	Not limited		Not limited		Not limited	
ZU: ZUNI VARIANT-----	85	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 0.42	Very limited Too clayey Hard to compact Slope Depth to bedrock	1.00 1.00 1.00 0.42

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)