

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
8B: Judson-----	100	Not limited		Not limited		Not limited	
11B: Colo-----	50	Very limited Depth to saturated zone Flooding	1.00 0.40	Very limited Depth to saturated zone Flooding	1.00 0.40	Very limited Flooding Depth to saturated zone	1.00 1.00
Ely-----	30	Not limited		Not limited		Not limited	
21: Muck-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Content of organic matter	1.00 1.00
41A: Sparta-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.05
41B: Sparta-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.05
41C: Sparta-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.05
41D: Sparta-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Very limited Slope Droughty	0.96 0.05
63A: Chelsea-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.48
63B: Chelsea-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.48
63C: Chelsea-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.48

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
63D: Chelsea-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Very limited Slope Droughty	0.96 0.48
63F: Chelsea-----	100	Somewhat limited Slope Too sandy	0.98 0.95	Somewhat limited Too sandy	0.95	Very limited Slope Droughty	1.00 0.48
83B: Kenyon-----	100	Not limited		Not limited		Not limited	
83C: Kenyon-----	95	Not limited		Not limited		Not limited	
83C2: Kenyon-----	95	Not limited		Not limited		Not limited	
83D2: Kenyon-----	95	Not limited		Not limited		Somewhat limited Slope	0.63
84: Clyde-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
88: Nevin-----	95	Not limited		Not limited		Not limited	
110B: Lamont-----	100	Not limited		Not limited		Not limited	
110C: Lamont-----	100	Not limited		Not limited		Not limited	
118: Garwin-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
119A: Muscatine-----	95	Not limited		Not limited		Not limited	
120A: Tama-----	100	Not limited		Not limited		Not limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
120B: Tama-----	100	Not limited		Not limited		Not limited	
120C: Tama-----	100	Not limited		Not limited		Not limited	
120C2: Tama-----	100	Not limited		Not limited		Not limited	
133: Colo-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Flooding	1.00 0.60
133+: Colo-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Flooding	1.00 0.60
151: Marshan-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
152: Marshan-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
154F: Loamy Terrace Escarp	100	Not rated		Not rated		Not rated	
160: Walford-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
162B: Downs-----	100	Not limited		Not limited		Not limited	
162C: Downs-----	100	Not limited		Not limited		Not limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
162C2: Downs-----	100	Not limited		Not limited		Not limited	
162D: Downs-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
162D2: Downs-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
163B: Fayette-----	100	Not limited		Not limited		Not limited	
163C: Fayette-----	100	Not limited		Not limited		Not limited	
163C2: Fayette-----	100	Not limited		Not limited		Not limited	
163D: Fayette-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
163D2: Fayette-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
163D3: Fayette-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
163E: Fayette-----	100	Somewhat limited Slope	0.02	Not limited		Very limited Slope	1.00
163E2: Fayette-----	100	Somewhat limited Slope	0.02	Not limited		Very limited Slope	1.00
163E3: Fayette-----	100	Somewhat limited Slope	0.02	Not limited		Very limited Slope	1.00
163F: Fayette-----	95	Somewhat limited Slope	0.98	Not limited		Very limited Slope	1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
163F2: Fayette-----	95	Somewhat limited Slope	0.98	Not limited		Very limited Slope	1.00
165A: Stronghurst-----	95	Not limited		Not limited		Somewhat limited Depth to saturated zone	0.19
171B: Bassett-----	95	Not limited		Not limited		Not limited	
171C: Bassett-----	100	Not limited		Not limited		Not limited	
171C2: Bassett-----	95	Not limited		Not limited		Not limited	
171D2: Bassett-----	95	Not limited		Not limited		Somewhat limited Slope	0.63
171E2: Bassett-----	95	Somewhat limited Slope	0.02	Not limited		Very limited Slope	1.00
171F2: Bassett-----	100	Somewhat limited Slope	0.82	Not limited		Very limited Slope	1.00
175A: Dickinson, Maat<50--	95	Not limited		Not limited		Not limited	
175B: Dickinson, Maat<50--	100	Not limited		Not limited		Not limited	
175C: Dickinson, Maat<50--	100	Not limited		Not limited		Not limited	
175D: Dickinson, Maat<50--	100	Not limited		Not limited		Somewhat limited Slope	0.63
177A: Saude-----	100	Not limited		Not limited		Not limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
177B: Saude-----	100	Not limited		Not limited		Not limited	
177C: Saude-----	100	Not limited		Not limited		Not limited	
178A: Waukee-----	95	Not limited		Not limited		Not limited	
178B: Waukee-----	100	Not limited		Not limited		Not limited	
184A: Klinger-----	95	Not limited		Not limited		Not limited	
198B: Floyd-----	95	Not limited		Not limited		Not limited	
204B: Dodgeville-----	95	Not limited		Not limited		Somewhat limited Depth to bedrock Content of large stones	0.46 0.01
204C: Dodgeville-----	95	Not limited		Not limited		Somewhat limited Depth to bedrock Content of large stones	0.46 0.01
207C2: Whalan-----	95	Not limited		Not limited		Somewhat limited Depth to bedrock	0.46
212: Kennebec-----	95	Not limited		Not limited		Somewhat limited Flooding	0.60
213B: Rockton-----	95	Not limited		Not limited		Somewhat limited Depth to bedrock	0.46
213C: Rockton-----	95	Not limited		Not limited		Somewhat limited Depth to bedrock	0.46
214B: Rockton-----	95	Not limited		Not limited		Somewhat limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
						Depth to bedrock	0.46
214C: Rockton-----	95	Not limited		Not limited		Somewhat limited Depth to bedrock	0.46
214D: Rockton-----	95	Not limited		Not limited		Somewhat limited Slope Depth to bedrock	0.63 0.46
220A: Nodaway-----	95	Not limited		Not limited		Somewhat limited Flooding	0.60
220B: Nodaway-----	95	Not limited		Not limited		Somewhat limited Flooding	0.60
221: Muck-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Content of organic matter	1.00 1.00
225: Lawler-----	90	Not limited		Not limited		Not limited	
226: Lawler-----	95	Not limited		Not limited		Not limited	
284A: Flagler-----	100	Not limited		Not limited		Somewhat limited Droughty	0.08
284B: Flagler-----	100	Not limited		Not limited		Somewhat limited Droughty	0.08
284C: Flagler-----	100	Not limited		Not limited		Somewhat limited Droughty	0.08
284C2: Flagler-----	100	Not limited		Not limited		Somewhat limited Droughty	0.08

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
285C: Burkhardt-----	100	Not limited		Not limited		Somewhat limited Droughty	0.67
285D2: Burkhardt-----	100	Not limited		Not limited		Somewhat limited Droughty Slope	0.67 0.63
291A: Atterberry-----	90	Not limited		Not limited		Somewhat limited Depth to saturated zone	0.19
291B: Atterberry-----	95	Not limited		Not limited		Somewhat limited Depth to saturated zone	0.19
293C: Chelsea-----	40	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.48
Lamont-----	30	Not limited		Not limited		Not limited	
Fayette-----	20	Not limited		Not limited		Not limited	
293C2: Chelsea-----	40	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.48
Fayette-----	30	Not limited		Not limited		Not limited	
Lamont-----	30	Not limited		Not limited		Not limited	
293D: Chelsea-----	40	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Very limited Slope Droughty	0.96 0.48
Fayette-----	30	Not limited		Not limited		Very limited Slope	0.96
Lamont-----	30	Not limited		Not limited		Very limited Slope	0.96
293D2: Chelsea-----	40	Somewhat limited		Somewhat limited		Very limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Too sandy	0.95	Too sandy	0.95	Slope Droughty	0.96 0.48
Fayette-----	30	Not limited		Not limited		Very limited Slope	0.96
Lamont-----	30	Not limited		Not limited		Very limited Slope	0.96
293F: Chelsea-----	40	Somewhat limited Slope Too sandy	0.98 0.95	Somewhat limited Too sandy	0.95	Very limited Slope Droughty	1.00 0.48
Fayette-----	30	Somewhat limited Slope	0.98	Not limited		Very limited Slope	1.00
Lamont-----	30	Somewhat limited Slope	0.82	Not limited		Very limited Slope	1.00
293F2: Chelsea-----	40	Somewhat limited Slope Too sandy	0.98 0.95	Somewhat limited Too sandy	0.95	Very limited Slope Droughty	1.00 0.48
Fayette-----	30	Somewhat limited Slope	0.98	Not limited		Very limited Slope	1.00
Lamont-----	30	Somewhat limited Slope	0.98	Not limited		Very limited Slope	1.00
302C2: Coggon-----	100	Not limited		Not limited		Not limited	
315: Loamy Alluvial Land-	95	Not rated		Not rated		Not rated	
350A: Waukegan-----	100	Not limited		Not limited		Not limited	
350B: Waukegan-----	100	Not limited		Not limited		Not limited	
350C: Waukegan-----	100	Not limited		Not limited		Not limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
351A: Atterberry-----	95	Not limited		Not limited		Not limited	
352A: Whittier-----	100	Not limited		Not limited		Not limited	
352B: Whittier-----	100	Not limited		Not limited		Not limited	
352C2: Whittier-----	100	Not limited		Not limited		Not limited	
353B: Tell-----	100	Not limited		Not limited		Not limited	
353C2: Tell-----	100	Not limited		Not limited		Not limited	
354: Marsh-----	95	Not rated		Not rated		Not rated	
377B: Dinsdale-----	95	Not limited		Not limited		Not limited	
377C: Dinsdale-----	95	Not limited		Not limited		Not limited	
377C2: Dinsdale-----	100	Not limited		Not limited		Not limited	
381B: Klinger-----	50	Not limited		Not limited		Not limited	
Maxfield-----	30	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
382: Maxfield-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
391B: Clyde-----	40	Very limited		Very limited		Very limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
Floyd-----	30	Not limited		Not limited		Not limited	
Schley-----	30	Not limited		Not limited		Somewhat limited Depth to saturated zone	0.19
393B: Sparta-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.07
393C: Sparta-----	100	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.07
398: Tripoli-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
399A: Readlyn-----	95	Not limited		Not limited		Not limited	
407B: Schley-----	95	Not limited		Not limited		Somewhat limited Depth to saturated zone	0.19
408B: Olin-----	100	Not limited		Not limited		Not limited	
408C: Olin-----	100	Not limited		Not limited		Not limited	
409B: Dickinson-----	100	Not limited		Not limited		Not limited	
409C: Dickinson-----	100	Not limited		Not limited		Not limited	
412C: Sogn-----	100	Not limited		Not limited		Very limited Depth to bedrock Droughty	1.00 1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
412D: Sogn-----	100	Not limited		Not limited		Content of large stones	0.01
						Very limited	
						Depth to bedrock	1.00
						Droughty	1.00
						Slope	0.96
						Content of large stones	0.01
412G: Sogn-----	100	Somewhat limited Slope	0.98	Not limited		Very limited	
						Depth to bedrock	1.00
						Slope	1.00
						Droughty	1.00
						Content of large stones	0.01
426A: Aredale-----	100	Not limited		Not limited		Not limited	
426B: Aredale-----	95	Not limited		Not limited		Not limited	
426C: Aredale-----	95	Not limited		Not limited		Not limited	
428B: Ely-----	95	Not limited		Not limited		Not limited	
442C: Dickinson-----	40	Not limited		Not limited		Not limited	
	30	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Droughty	0.10
Tama-----	30	Not limited		Not limited		Not limited	
442D: Dickinson-----	40	Not limited		Not limited		Somewhat limited Slope	0.63
	30	Somewhat limited Too sandy	0.95	Somewhat limited Too sandy	0.95	Somewhat limited Slope	0.63
						Droughty	0.10
Tama-----	30	Not limited		Not limited		Somewhat limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
						Slope	0.63
471A: Oran-----	95	Not limited		Not limited		Not limited	
471B: Oran-----	95	Not limited		Not limited		Not limited	
478G: Steep Rock Land-----	100	Not rated		Not rated		Not rated	
484: Lawson-----	95	Not limited		Not limited		Somewhat limited Flooding Depth to saturated zone	0.60 0.19
485: Spillville-----	95	Not limited		Not limited		Somewhat limited Flooding	0.60
578A: Waukee-----	100	Not limited		Not limited		Not limited	
578B: Waukee-----	100	Not limited		Not limited		Not limited	
578C: Waukee-----	100	Not limited		Not limited		Not limited	
663D: Seaton-----	95	Not limited		Not limited		Somewhat limited Slope	0.63
663D2: Seaton-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
663E: Seaton-----	100	Somewhat limited Slope	0.02	Not limited		Very limited Slope	1.00
663E2: Seaton-----	100	Somewhat limited		Not limited		Very limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Slope	0.02			Slope	1.00
663F: Seaton-----	100	Somewhat limited Slope	0.98	Not limited		Very limited Slope	1.00
663F2: Seaton-----	100	Somewhat limited Slope	0.98	Not limited		Very limited Slope	1.00
725: Hayfield-----	95	Not limited		Not limited		Not limited	
726: Hayfield-----	95	Not limited		Not limited		Not limited	
761A: Franklin-----	95	Not limited		Not limited		Not limited	
761B: Franklin-----	95	Not limited		Not limited		Not limited	
771B: Waubeek-----	100	Not limited		Not limited		Not limited	
771C2: Waubeek-----	100	Not limited		Not limited		Not limited	
772: Donnan Variant-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
777A: Wapsie-----	100	Not limited		Not limited		Not limited	
777B: Wapsie-----	100	Not limited		Not limited		Not limited	
778A: Sattre-----	100	Not limited		Not limited		Not limited	
778B: Sattre-----	100	Not limited		Not limited		Not limited	
778C2: Sattre-----	100	Not limited		Not limited		Not limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
782B: Donnan-----	95	Not limited		Not limited		Not limited	
782C2: Donnan-----	95	Not limited		Not limited		Not limited	
793A: Bertrand-----	95	Not limited		Not limited		Not limited	
793B: Bertrand-----	95	Not limited		Not limited		Not limited	
809B: Bertram-----	95	Not limited		Not limited		Somewhat limited Depth to bedrock Droughty	0.46 0.02
809C: Bertram-----	95	Not limited		Not limited		Somewhat limited Depth to bedrock Droughty	0.46 0.02
977: Richwood-----	100	Not limited		Not limited		Not limited	
Bp: Borrow Areas-----	100	Not rated		Not rated		Not rated	
ML: Made Land-----	100	Not rated		Not rated		Not rated	
Q: Limestone Quarries--	100	Not rated		Not rated		Not rated	
SP: Pits, Sand And Gravel-----	100	Not rated		Not rated		Not rated	

FIELD OFFICE TECHNICAL GUIDE Sec. II
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Linn County, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
T119A: Muscatine-----	95	Not limited		Not limited		Not limited	
T120A: Tama-----	100	Not limited		Not limited		Not limited	
T120B: Tama-----	100	Not limited		Not limited		Not limited	
T160: Walford-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
T163B: Fayette-----	100	Not limited		Not limited		Not limited	
T291A: Atterberry-----	95	Not limited		Not limited		Somewhat limited Depth to saturated zone	0.19