

Table ENG-6. - Sanitary Facilities

Clarke County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
1B:							
Berks	45	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
						Seepage	0.21
Berks variant	35	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to saturated zone	0.96
		Content of large stones	<0.01			Gravel content	0.93
1C:							
Berks	50	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
		Slope	0.63	Slope	0.63	Slope	0.63
Berks variant	30	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to saturated zone	0.96
		Slope	0.63	Slope	0.63	Gravel content	0.93
2B:							
Braddock	80	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
		Seepage	1.00			Seepage	0.21
2C:							
Braddock	80	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.63	Too clayey	1.00
		Seepage	1.00			Slope	0.63
		Slope	0.63			Seepage	0.21
3D:							
Braddock	98	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
		Seepage	1.00			Seepage	0.21
4:							
Buckton	80	Very limited		Very limited		Not limited	
		Flooding	1.00	Flooding	1.00		
		Seepage	1.00				
5B:							

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
5B:							
Carbo	30	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
Opequon	25	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
Rock outcrop	25	Not Rated		Not Rated		Not Rated	
5C:							
Carbo	30	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.63	Slope	0.63	Slope	0.63
Opequon	25	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.63	Slope	0.63	Slope	0.63
Rock outcrop	25	Not Rated		Not Rated		Not Rated	
6B:							
Cardiff	80	Very limited		Very limited		Somewhat limited	
		Depth to bedrock	1.00	Seepage	1.00	Content of large stones	0.68
		Content of large stones	0.68	Depth to bedrock	0.42	Depth to bedrock	0.42
						Gravel content	0.14
Wet spots	3	Not Rated		Not Rated		Not Rated	
6C:							
Cardiff	75	Very limited		Very limited		Somewhat limited	
		Depth to bedrock	1.00	Seepage	1.00	Content of large stones	0.68
		Content of large stones	0.68	Slope	0.63	Slope	0.63
		Slope	0.63	Depth to bedrock	0.42	Depth to bedrock	0.42
Wet spots	3	Not Rated		Not Rated		Not Rated	
7D:							
Cataska	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
7D:							
Cardiff	35	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Content of large stones	0.68
		Content of large stones	0.68	Depth to bedrock	0.42	Depth to bedrock	0.42
Wet spots	3	Not Rated		Not Rated		Not Rated	
8D:							
Catoctin	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.66
Myersville	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
9D:							
Catoctin	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.66
Myersville	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.42
10:							
Chagrín	80	Very limited		Very limited		Not limited	
		Flooding	1.00	Flooding	1.00		
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
11B:							
Clymer	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Slope	0.04	Slope	0.04	Gravel content	0.97
						Slope	0.04
12D:							
Dekalb	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Seepage	1.00	Slope	1.00
		Seepage	1.00	Depth to bedrock	1.00	Seepage	1.00

12E:

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
12E:							
Dekalb	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Seepage	1.00	Slope	1.00
		Seepage	1.00	Depth to bedrock	1.00	Seepage	1.00
13D:							
Dekalb	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Seepage	1.00	Depth to bedrock	1.00
		Seepage	1.00	Depth to bedrock	1.00	Seepage	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
13E:							
Dekalb	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Seepage	1.00	Slope	1.00
		Seepage	1.00	Depth to bedrock	1.00	Seepage	1.00
14C:							
Dekalb	45	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Seepage	1.00	Depth to bedrock	1.00
		Seepage	1.00	Depth to bedrock	1.00	Seepage	1.00
		Slope	0.04	Slope	0.04	Gravel content	0.89
Hazleton	35	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Seepage	1.00	Gravel content	1.00
		Seepage	1.00	Slope	0.04	Seepage	1.00
		Slope	0.04			Slope	0.04
15B:							
Endcav	45	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.42	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	0.42
Dandridge	35	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00			Too clayey	1.00
						Gravel content	1.00
15C:							
Endcav	45	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Slope	0.63	Too clayey	1.00
		Too clayey	1.00	Depth to bedrock	0.42	Slope	0.63
		Slope	0.63			Depth to bedrock	0.42
Dandridge	35	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Slope	0.63	Too clayey	1.00
		Slope	0.63			Gravel content	1.00
16B:							

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
16B:							
Fluvaquents	75	Not Rated		Not Rated		Not Rated	
17B:							
Hagerstown	30	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Slope	0.04	Too clayey	1.00
		Too clayey	1.00			Slope	0.04
		Seepage	1.00				
Opequon	25	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.04	Slope	0.04	Slope	0.04
Rock outcrop	25	Not Rated		Not Rated		Not Rated	
18:							
Hollywood	80	Very limited		Not limited		Very limited	
		Depth to bedrock	1.00			Too clayey	1.00
		Too clayey	1.00				
19D:							
Laidig	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Slope	1.00
		Slope	1.00	Slope	1.00	Gravel content	0.23
20D:							
Laidig	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Slope	1.00
		Slope	1.00	Slope	1.00	Gravel content	0.23
21B:							
Lakin	80	Very limited		Very limited		Very limited	
		Seepage	1.00	Seepage	1.00	Seepage	1.00
		Too Sandy	1.00			Too Sandy	0.50
22C:							
Lew	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Content of large stones	0.82	Slope	0.63	Content of large stones	0.82
		Slope	0.63			Slope	0.63
		Too clayey	0.50			Gravel content	0.55
22D:							

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
22D:							
Lew	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Content of large stones	0.82			Content of large stones	0.82
		Too clayey	0.50			Gravel content	0.55
23:							
Lobdell	80	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	0.25
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Seepage	0.21
		Seepage	1.00	Seepage	1.00		
Wet spots	5	Not Rated		Not Rated		Not Rated	
24:							
McGary	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	1.00
		Too clayey	1.00			Depth to saturated zone	0.86
Wet spots	5	Not Rated		Not Rated		Not Rated	
25B:							
Monongahela	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.68
26B:							
Monongahela	45	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.68
Braddock	35	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
		Seepage	1.00			Seepage	0.21
26C:							
Monongahela	40	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.68
		Slope	0.63	Slope	0.63	Slope	0.63

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
26C:							
Braddock	35	Very limited Too clayey Seepage Slope	1.00 1.00 0.63	Somewhat limited Slope	0.63	Very limited Too clayey Slope Seepage	1.00 0.63 0.21
27B:							
Monongahela	50	Very limited Depth to saturated zone Depth to thick cemented pan	1.00 1.00	Very limited Depth to cemented pan Depth to saturated zone	1.00 1.00	Very limited Depth to cemented pan Depth to saturated zone	1.00 0.68
Zoar	30	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Too clayey Depth to saturated zone	1.00 0.86
28B:							
Myersville	45	Very limited Depth to bedrock Too clayey	1.00 0.50	Somewhat limited Depth to bedrock	0.42	Somewhat limited Too clayey Depth to bedrock Gravel content	0.50 0.42 0.09
Catoctin	40	Very limited Depth to bedrock Seepage Content of large stones	1.00 1.00 0.02	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Gravel content Seepage	1.00 0.66 0.50
28C:							
Myersville	45	Very limited Depth to bedrock Slope Too clayey	1.00 0.63 0.50	Somewhat limited Slope Depth to bedrock	0.63 0.42	Somewhat limited Slope Too clayey Depth to bedrock	0.63 0.50 0.42
Catoctin	40	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.63	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.63	Very limited Depth to bedrock Gravel content Slope	1.00 0.66 0.63
29C:							
Myersville	45	Very limited Depth to bedrock Slope Too clayey	1.00 0.63 0.50	Somewhat limited Slope Depth to bedrock	0.63 0.42	Somewhat limited Slope Too clayey Depth to bedrock	0.63 0.50 0.42
Catoctin	40	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.63	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.63	Very limited Depth to bedrock Gravel content Slope	1.00 0.66 0.63

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
30B:							
Nicholson	50	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thin cemented pan	0.50	Depth to saturated zone	1.00	Depth to saturated zone	0.86
Duffield	35	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
31B:							
Oaklet	80	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
32B:							
Oaklet	40	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
Carbo	35	Not Rated		Very limited		Not Rated	
				Depth to bedrock	1.00		
				Seepage	1.00		
33B:							
Pagebrook	80	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Too clayey	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.09
		Too clayey	1.00				
34:							
Pits	80	Not Rated		Not Rated		Not Rated	
35B:							
Poplimento	80	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
35C:							
Poplimento	80	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.63	Too clayey	1.00
		Slope	0.63			Slope	0.63
36B:							
Poplimento	75	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
36C:							
Poplimento	75	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.63	Too clayey	1.00
		Slope	0.63			Slope	0.63
37B:							

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
37B:							
Poplimento	55	Very limited Too clayey Slope	1.00 0.04	Somewhat limited Slope	0.04	Very limited Too clayey Slope	1.00 0.04
Rock outcrop	25	Not Rated		Not Rated		Not Rated	
38B:							
Poplimento	45	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Webbtown	35	Very limited Depth to bedrock Too clayey	1.00 0.50	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Gravel content Too clayey	1.00 1.00 0.50
38C:							
Poplimento	45	Very limited Too clayey Slope	1.00 0.63	Somewhat limited Slope	0.63	Very limited Too clayey Slope	1.00 0.63
Webbtown	35	Very limited Depth to bedrock Slope Too clayey	1.00 0.63 0.50	Very limited Depth to bedrock Slope	1.00 0.63	Very limited Depth to bedrock Gravel content Slope	1.00 1.00 0.63
38D2:							
Poplimento	40	Very limited Slope Too clayey	1.00 1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 1.00
Webbtown	35	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 1.00
39B:							
Poplimento	45	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Webbtown	35	Very limited Depth to bedrock Too clayey	1.00 0.50	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Gravel content Too clayey	1.00 1.00 0.50
39C:							
Poplimento	45	Very limited Too clayey Slope	1.00 0.63	Somewhat limited Slope	0.63	Very limited Too clayey Slope	1.00 0.63

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
39C:							
Webbtown	35	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.63	Slope	0.63	Gravel content	1.00
		Too clayey	0.50			Slope	0.63
39D2:							
Poplimento	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
Webbtown	35	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	0.50			Gravel content	1.00
40:							
Quarries	55	Not Rated		Not Rated		Not Rated	
Dumps	25	Not Rated		Not Rated		Not Rated	
41C:							
Rock outcrop	55	Not Rated		Not Rated		Not Rated	
Catoctin	25	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.66
42C:							
Rock outcrop	55	Not Rated		Not Rated		Not Rated	
Dekalb	25	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Seepage	1.00	Depth to bedrock	1.00
		Seepage	1.00	Depth to bedrock	1.00	Seepage	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
43C:							
Rock outcrop	55	Not Rated		Not Rated		Not Rated	
Opequon	25	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Slope	1.00	Too clayey	1.00
		Slope	1.00	Seepage	1.00	Slope	1.00
44B:							
Swimley	80	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
45B:							

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
45B:							
Swimley	80	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
46B:							
Swimley	45	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Hagerstown	35	Very limited Depth to bedrock Too clayey Seepage	1.00 1.00 1.00	Not limited		Very limited Too clayey	1.00
47B:							
Swimley	40	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Hagerstown	35	Very limited Depth to bedrock Too clayey Seepage	1.00 1.00 1.00	Not limited		Very limited Too clayey	1.00
47C:							
Swimley	40	Very limited Too clayey Slope	1.00 0.63	Somewhat limited Slope	0.63	Very limited Too clayey Slope	1.00 0.63
Hagerstown	35	Very limited Depth to bedrock Too clayey Seepage	1.00 1.00 1.00	Somewhat limited Slope	0.63	Very limited Too clayey Slope	1.00 0.63
48B:							
Swimley	50	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Rock outcrop	25	Not Rated		Not Rated		Not Rated	
49B:							
Thurmont	80	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
50B:							
Thurmont	80	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
51B:							

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
51B:							
Timberville	80	Very limited Flooding Too clayey	1.00 1.00	Very limited Flooding	1.00	Very limited Too clayey	1.00
52B:							
Udipsamments	75	Not Rated		Not Rated		Not Rated	
53:							
Udorthents	85	Not Rated		Not Rated		Not Rated	
54C:							
Udorthents	75	Not Rated		Not Rated		Not Rated	
Fluvaquents	5	Not Rated		Not Rated		Not Rated	
55D:							
Udufts	50	Not Rated		Not Rated		Not Rated	
Udalfs	30	Not Rated		Not Rated		Not Rated	
56:							
Weaver	80	Very limited Flooding Depth to saturated zone Depth to bedrock	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Depth to bedrock	1.00 1.00 0.42	Somewhat limited Depth to saturated zone Depth to bedrock	0.86 0.42
57C2:							
Webbtown	30	Very limited Depth to bedrock Too clayey Slope	1.00 0.50 0.04	Very limited Depth to bedrock Slope	1.00 0.04	Very limited Depth to bedrock Gravel content Too clayey	1.00 1.00 0.50
Poplimento	25	Very limited Too clayey Slope	1.00 0.04	Somewhat limited Slope	0.04	Very limited Too clayey Slope	1.00 0.04
Rock outcrop	20	Not Rated		Not Rated		Not Rated	
57D2:							
Webbtown	30	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 1.00
Poplimento	25	Very limited Slope Too clayey	1.00 1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 1.00
Rock outcrop	20	Not Rated		Not Rated		Not Rated	

Table ENG-6. - Sanitary Facilities - Continued

Clarke County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
58D:							
Weikert	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	1.00
Berks	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
59B:							
Whiteford	80	Very limited		Very limited		Somewhat limited	
		Depth to bedrock	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50	Depth to bedrock	0.42	Depth to bedrock	0.42
						Gravel content	0.22
NS:							
Unsurveyed	100	Not Rated		Not Rated		Not Rated	
W:							
Water	100	Not Rated		Not Rated		Not Rated	