

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
6: Okoboji-----	95	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Ponding	1.00 1.00	Very limited Hard to compact Depth to saturated zone Ponding Too clayey	1.00 1.00 1.00 0.50
28B: Dickman-----	100	Very limited Seepage Too Sandy	1.00 0.50	Very limited Seepage	1.00	Somewhat limited Seepage Too Sandy	0.50 0.50
55: Nicollet-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
62C2: Storden-----	90	Not limited		Not limited		Not limited	
62D2: Storden-----	90	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
62E2: Storden-----	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
73B: Salida-----	100	Very limited Too Sandy Seepage	1.00 1.00	Very limited Seepage	1.00	Very limited Gravel content Too Sandy Seepage	1.00 1.00 1.00
73E: Salida-----	100	Very limited Too Sandy Seepage Slope	1.00 1.00 0.96	Very limited Seepage Slope	1.00 0.96	Very limited Gravel content Too Sandy Seepage Slope	1.00 1.00 1.00 0.96

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
90: Okoboji-----	100	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Ponding	1.00 1.00	Very limited Hard to compact Depth to saturated zone Ponding Too clayey	1.00 1.00 1.00 0.50
95: Harps-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
107: Webster-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
135: Coland-----	95	Very limited Flooding Depth to saturated zone Seepage Too clayey	1.00 1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
135B: Coland-----	100	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
138B: Clarion-----	85	Not limited		Not limited		Not limited	
138C: Clarion-----	100	Not limited		Not limited		Not limited	
138C2: Clarion-----	85	Not limited		Not limited		Not limited	
138D2: Clarion-----	85	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
150: Hanska-----	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 0.50	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 0.50
168B: Hayden-----	100	Not limited		Not limited		Not limited	
168C: Hayden-----	90	Not limited		Not limited		Not limited	
168D2: Hayden-----	90	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
168E: Hayden-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
175B: Dickinson-----	95	Very limited Too Sandy Seepage	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
221: Palms-----	100	Very limited Depth to saturated zone Content of organic matter Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Content of organic matter Ponding Seepage	1.00 1.00 1.00 0.16
224: Linder-----	95	Very limited Too Sandy Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00
236B: Lester-----	95	Not limited		Not limited		Not limited	

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
236C2: Lester-----	95	Not limited		Not limited		Not limited	
236D2: Lester-----	90	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
236E2: Lester-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
236F: Lester-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
307: Dundas-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
321: Boots-----	95	Very limited Depth to saturated zone Content of organic matter Seepage Ponding	1.00 1.00 1.00 1.00	Very limited Depth to saturated zone Seepage Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Content of organic matter Ponding Seepage	1.00 1.00 1.00 0.21
325: Le Sueur-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
349: Darfur-----	95	Very limited Too Sandy Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
384: Collinwood-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
384B: Collinwood-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
386: Cordova-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
390: Waldorf-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
485B: Spillville-----	100	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone	1.00	Not limited	
507: Canisteo-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
511: Blue Earth-----	100	Very limited Depth to saturated zone Ponding	1.00 1.00	Very limited Depth to saturated zone Ponding	1.00 1.00	Very limited Depth to saturated zone Ponding	1.00 1.00 1.00

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
583: Minnetonka-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 1.00
585B: Coland-----	60	Very limited Flooding Depth to saturated zone Seepage Too clayey	1.00 1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
Spillville-----	40	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone	1.00	Not limited	
621: Houghton-----	100	Very limited Depth to saturated zone Content of organic matter Seepage Ponding	1.00 1.00 1.00 1.00	Very limited Depth to saturated zone Seepage Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Content of organic matter Ponding Seepage	1.00 1.00 1.00 0.16
638B2: Clarion-----	60	Not limited		Not limited		Not limited	
Storden-----	35	Not limited		Not limited		Not limited	
638C2: Clarion-----	60	Not limited		Not limited		Not limited	
Storden-----	30	Not limited		Not limited		Not limited	
638D2: Clarion-----	60	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
Storden-----	30	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
638E2: Clarion-----	60	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Storden-----	30	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
655: Crippin-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
658: Mayer-----	95	Very limited Too Sandy	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Seepage	1.00	Too Sandy	1.00
		Seepage	1.00			Seepage	1.00
777: Wapsie-----	95	Very limited Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy	1.00
		Seepage	1.00			Seepage	1.00
777B: Wapsie-----	95	Very limited Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy	1.00
		Seepage	1.00			Seepage	1.00
777C: Wapsie-----	90	Very limited Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy	1.00
		Seepage	1.00			Seepage	1.00
787B: Vinje-----	100	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
787C2: Vinje-----	95	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
787D2: Vinje-----	95	Very limited Too clayey	1.00	Somewhat limited Slope	0.63	Very limited Too clayey	1.00
		Slope	0.63			Slope	0.63

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
811: Muskego-----	100	Very limited Depth to saturated zone Content of organic matter Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage Ponding	1.00 1.00 1.00 1.00	Very limited Depth to saturated zone Content of organic matter Carbonate content Ponding	1.00 1.00 1.00 1.00
823: Ridgeport-----	95	Very limited Seepage	1.00	Very limited Seepage	1.00	Somewhat limited Seepage	0.50
823B: Ridgeport-----	100	Very limited Seepage	1.00	Very limited Seepage	1.00	Somewhat limited Seepage	0.50
836B: Kilkenny-----	95	Very limited Too clayey	1.00	Not limited		Very limited Hard to compact Too clayey	1.00 1.00
836C2: Kilkenny-----	90	Very limited Too clayey	1.00	Not limited		Very limited Hard to compact Too clayey	1.00 1.00
836D2: Kilkenny-----	95	Very limited Too clayey Slope	1.00 0.63	Somewhat limited Slope	0.63	Very limited Hard to compact Too clayey Slope	1.00 1.00 0.63
836E2: Kilkenny-----	95	Very limited Too clayey Slope	1.00 1.00	Very limited Slope	1.00	Very limited Hard to compact Too clayey Slope	1.00 1.00 1.00
836F: Kilkenny-----	95	Very limited Slope Too clayey	1.00 1.00	Very limited Slope	1.00	Very limited Hard to compact Slope Too clayey	1.00 1.00 1.00

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
855: Shorewood-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
1133: Colo-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
2811: Muskego-----	95	Very limited Depth to saturated zone Content of organic matter Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Content of organic matter Carbonate content Ponding	1.00 1.00 1.00 1.00
5010: Pits-----	100	Not rated		Not rated		Not rated	
5040: Orthents-----	100	Not rated		Not rated		Not rated	
W: Water-----	100	Not rated		Not rated		Not rated	

