

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
13B: Olmitz-----	40	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
Zook-----	30	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
Colo-----	20	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
23C: Arispe-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
23C2: Arispe-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
24D: Shelby-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
24D2: Shelby-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
24E: Shelby-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
24E2: Shelby-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
24E3: Shelby-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
24F: Shelby-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
24F2: Shelby-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
51: Vesser-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
51B: Vesser-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
54: Zook-----	100	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
54+: Zook-----	100	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	1.00
		Too clayey	1.00				
56C: Cantril-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
		Too clayey	0.50			Too clayey	0.50
65D: Lindley-----	95	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
		Too clayey	0.50			Too clayey	0.50
65E: Lindley-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
		Too clayey	0.50			Too clayey	0.50
65F: Lindley-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
		Too clayey	0.50			Too clayey	0.50
65F2: Lindley-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
		Too clayey	0.50			Too clayey	0.50
65G: Lindley-----	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
		Too clayey	0.50			Too clayey	0.50
69C: Clearfield-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Hard to compact	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	0.50			Too clayey	0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
69C2: Clearfield-----	90	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 0.50
76C2: Ladoga-----	100	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
87B: Zook-----	60	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
Colo-----	40	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
93D: Shelby-----	65	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
Adair-----	35	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
93D2: Shelby-----	60	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Adair-----	40	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
93D3: Adair-----	50	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
Shelby-----	50	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
94D: Caleb-----	70	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50	Very limited Depth to saturated zone Slope	1.00 0.63	Somewhat limited Slope Too clayey	0.63 0.50
Mystic-----	30	Very limited Depth to saturated zone Depth to saturated zone Seepage Slope Too clayey	1.00 1.00 1.00 0.63 0.50	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50
94D2: Caleb-----	60	Very limited Depth to saturated zone Depth to saturated zone Slope Too clayey	1.00 1.00 0.63 0.50	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Mystic-----	40	Very limited Depth to saturated zone Too clayey Seepage Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Slope	1.00 0.63	Very limited Too clayey Slope	1.00 0.63
94E2: Caleb-----	60	Very limited Depth to saturated zone Depth to saturated zone Slope Too clayey	1.00 1.00 1.00 0.50	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 1.00	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50
Mystic-----	40	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope Seepage	1.00 1.00 1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 1.00	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 1.00
131B: Pershing-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
131C: Pershing-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
131C2: Pershing-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
132C: Weller-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone Too clayey	0.86 0.50
133: Colo-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
133B: Colo-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
179D: Gara-----	95	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
179D2: Gara-----	95	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
179E: Gara-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
179E2: Gara-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
179E3: Gara-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
179F: Gara-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
179F2: Gara-----	90	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
192C: Adair-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 1.00
192C2: Adair-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 1.00
192D: Adair-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
192D2: Adair-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
192D3: Adair-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
211: Edina-----	95	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone	1.00
220: Nodaway-----	90	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
222C: Clarinda-----	90	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
222C2: Clarinda-----	90	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
222C3: Clarinda-----	90	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
222D2: Clarinda-----	90	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Hard to compact Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63
269: Humeston-----	100	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
273B: Olmitz-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
273C: Olmitz-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
362: Haig-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
364B: Grundy-----	98	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
368: Macksburg-----	98	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
368B: Macksburg-----	98	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
369: Winterset-----	90	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
370B: Sharpsburg-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
370C: Sharpsburg-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
370C2: Sharpsburg-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
423C2: Bucknell-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
423D: Bucknell-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Hard to compact Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63
423D2: Bucknell-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Hard to compact Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63
425D: Keswick-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
425D2: Keswick-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
430: Ackmore-----	98	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
452C2: Lineville-----	90	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
484: Lawson-----	98	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
570C: Nira-----	100	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone Too clayey	0.86 0.50
570C2: Nira-----	100	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone Too clayey	0.86 0.50
592C2: Mystic-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 1.00
592D2: Mystic-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
730C: Cantril-----	60	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
Nodaway-----	35	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
792C: Armstrong-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 1.00
792C2: Armstrong-----	100	Very limited Depth to saturated zone Depth to	1.00 1.00	Very limited Depth to saturated zone Depth to	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 1.00
		saturated zone Too clayey	1.00	saturated zone			
792D: Armstrong-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
792D2: Armstrong-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
792D3: Armstrong-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
822C: Lamoni-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
822C2: Lamoni-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
822C3: Lamoni-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
822D: Lamoni-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Hard to compact Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
822D2: Lamoni-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Hard to compact Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63
822D3: Lamoni-----	100	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Hard to compact Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63
892C2: Mystic Variant-----	100	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone Too clayey	0.86 0.50
993D2: Gara-----	60	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
Armstrong-----	40	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 0.63	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63
993E2: Gara-----	60	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Clarke County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Armstrong-----	40	Very limited Depth to saturated zone Depth to saturated zone Too clayey Slope	1.00 1.00 1.00 1.00	Very limited Depth to saturated zone Depth to saturated zone Slope	1.00 1.00 1.00	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 1.00
1715: Nodaway-----	50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
Lawson-----	40	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
5030: Pits-----	100	Not rated		Not rated		Not rated	
5040: Orthents-----	100	Not rated		Not rated		Not rated	
W: Water-----	100	Not rated		Not rated		Not rated	

