

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
1B: Ida-----	95	Not limited		Not limited		Not limited	
1C: Ida-----	95	Not limited		Not limited		Not limited	
1C3: Ida-----	95	Not limited		Not limited		Not limited	
1D: Ida-----	95	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
1D3: Ida-----	95	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
1E: Ida-----	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
1E3: Ida-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
1F3: Ida-----	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
8B: Judson-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
8C: Judson-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
9B: Marshall-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
9B2: Marshall-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
9C: Marshall-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
9C2: Marshall-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
9D: Marshall-----	100	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
9D2: Marshall-----	100	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
11B: Colo-----	50	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
Judson-----	40	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
22D3: Dow-----	95	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
26: Kennebec-----	90	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Somewhat limited Too clayey	0.50
26B: Kennebec-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Somewhat limited Too clayey	0.50

FIELD OFFICE TECHNICAL GUIDE Sec. II
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
27B: Terril-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
27C: Terril-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
28C2: Dickman-----	100	Very limited Seepage	1.00	Very limited Seepage	1.00	Somewhat limited Seepage	0.50
28D2: Dickman-----	100	Very limited Seepage Slope	1.00 0.63	Very limited Seepage Slope	1.00 0.63	Somewhat limited Slope Seepage	0.63 0.50
31: Afton-----	100	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
35E2: Steinauer-----	55	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
Burchard-----	40	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
35G: Steinauer-----	55	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
Burchard-----	40	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
54: Zook-----	100	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Hard to compact Depth to saturated zone Too clayey	1.00 1.00 1.00
59D2: Burchard-----	95	Somewhat limited Too clayey Slope	0.50 0.16	Somewhat limited Slope	0.16	Somewhat limited Too clayey Slope	0.50 0.16
78B: Sac-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
78B2: Sac-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
78C: Sac-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
78C2: Sac-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
78D2: Sac-----	95	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
91B: Primghar-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
92: Marcus-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
99C2: Exira-----	100	Not limited		Not limited		Not limited	

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
99D2: Exira-----	100	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
99D3: Exira-----	95	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
99E2: Exira-----	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
100C: Monona-----	100	Not limited		Not limited		Not limited	
100C2: Monona-----	95	Not limited		Not limited		Not limited	
100C3: Monona-----	95	Not limited		Not limited		Not limited	
100D: Monona-----	100	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
100D2: Monona-----	95	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
100D3: Monona-----	95	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
100E: Monona-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
100E2: Monona-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
100E3: Monona-----	95	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
100F: Monona-----	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
100F2: Monona-----	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
100F3: Monona-----	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
133: Colo-----	95	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone Too clayey	1.00 0.50	Depth to saturated zone	1.00	Too clayey	0.50
133+: Colo-----	95	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone Too clayey	1.00 0.50	Depth to saturated zone	1.00	Too clayey	0.50
220: Nodaway-----	90	Very limited Flooding	1.00	Very limited Flooding	1.00	Not limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
309: Allendorf-----	95	Very limited Too Sandy	1.00	Very limited Seepage	1.00	Very limited Seepage	1.00
		Seepage	1.00			Too Sandy	0.50
310: Galva-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
310B: Galva-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
310B2: Galva-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
310C: Galva-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
310C2: Galva-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
310D: Galva-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
310D2: Galva-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
428B: Ely-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50 0.09
430: Ackmore-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Somewhat limited Depth to saturated zone Too clayey	0.86 0.50
430B: Ackmore-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Somewhat limited Depth to saturated zone Too clayey	0.86 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
474C: Bolan-----	95	Very limited Seepage	1.00	Very limited Seepage	1.00	Not limited	
474D2: Bolan-----	95	Very limited Seepage Slope	1.00 0.63	Very limited Seepage Slope	1.00 0.63	Somewhat limited Slope	0.63
475B: Arthur-----	100	Very limited Seepage Too clayey	1.00 0.50	Very limited Seepage	1.00	Somewhat limited Too clayey	0.50
475C2: Arthur-----	95	Very limited Too Sandy Seepage	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
475D2: Arthur-----	100	Very limited Too Sandy Seepage Slope	1.00 1.00 0.63	Very limited Seepage Slope	1.00 0.63	Very limited Seepage Slope Too Sandy	1.00 0.63 0.50
509: Marshall-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
509B: Marshall-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
509C: Marshall-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
509C2: Marshall-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
740C: Hawick-----	95	Very limited Too Sandy Seepage	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
740E: Hawick-----	95	Very limited Too Sandy Seepage Slope	1.00 1.00 0.96	Very limited Seepage Slope	1.00 0.96	Very limited Too Sandy Seepage Slope	1.00 1.00 0.96
740G: Hawick-----	95	Very limited Too Sandy Slope Seepage	1.00 1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Too Sandy Seepage	1.00 1.00 1.00
810: Galva-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
810B: Galva-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
810C2: Galva-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
1220: Nodaway-----	90	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
5010: Pits-----	100	Not rated		Not rated		Not rated	
5040: Orthents-----	100	Not rated		Not rated		Not rated	

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
W: Water-----	100	Not rated		Not rated		Not rated	

