

Selected Soil Interpretations

This report allows the customer to produce a report showing the results of the soil interpretation(s) of his or her choice. It is useful when a standard report that displays the results of the selected interpretation(s) is not available.

When customers select this report, they are presented with a list of interpretations with results for the selected map units. The customer may select up to three interpretations to be presented in table format.

For a description of the particular interpretations and their criteria, use the "Selected Survey Area Interpretation Descriptions" report.

Report—Selected Soil Interpretations

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|---|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| AvA—Avonburg silt loam, 0 to 2 percent slopes | | | | | |
| Avonburg | 85 | Very limited | | Very limited | |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| BaA—Bartle silt loam, 0 to 3 percent slopes | | | | | |
| Bartle | 83 | Very limited | | Very limited | |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Dusty | 0.07 | Dusty | 0.07 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| BeC2—Bonnell silt loam, 6 to 12 percent slopes, eroded | | | | | |
| Bonnell | 100 | Somewhat limited | | Somewhat limited | |
| | | Slope | 0.63 | Dusty | 0.06 |
| | | Dusty | 0.06 | Slope | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| BeC3—Bonnell silt loam, 6 to 12 percent slopes, severely eroded | | | | | |
| Bonnell, severely eroded | 100 | Somewhat limited | | Somewhat limited | |
| | | Slope | 0.63 | Dusty | 0.06 |
| | | Dusty | 0.06 | Slope | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|---|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| BeD2--Bonnell silt loam, 12 to 18 percent slopes, eroded | | | | | |
| Bonnell | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| BeD3--Bonnell silt loam, 12 to 18 percent slopes, severely eroded | | | | | |
| Bonnell, severely eroded | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| BeE--Bonnell silt loam, 18 to 35 percent slopes | | | | | |
| Bonnell | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| CaC2--Carmel silt loam, 6 to 12 percent slopes, eroded | | | | | |
| Carmel | 100 | Somewhat limited | | Somewhat limited | |
| | | Slope | 0.63 | Unstable excavation walls | 0.28 |
| | | Unstable excavation walls | 0.28 | Dusty | 0.05 |
| | | Dusty | 0.05 | Slope | 0.04 |
| CaD2--Carmel silt loam, 12 to 18 percent slopes, eroded | | | | | |
| Carmel | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Unstable excavation walls | 0.28 | Unstable excavation walls | 0.28 |
| | | Dusty | 0.05 | Dusty | 0.05 |
| CaE2--Carmel silt loam, 18 to 25 percent slopes, eroded | | | | | |
| Carmel | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Unstable excavation walls | 0.26 | Unstable excavation walls | 0.26 |
| | | Dusty | 0.05 | Dusty | 0.05 |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|---|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| CcC3—Carmel silty clay loam, 6 to 12 percent slopes, severely eroded | | | | | |
| Carmel, severely eroded | 100 | Somewhat limited | | Somewhat limited | |
| | | Slope | 0.63 | Unstable excavation walls | 0.51 |
| | | Unstable excavation walls | 0.51 | Dusty | 0.06 |
| | | Dusty | 0.06 | Slope | 0.04 |
| CcD3—Carmel silty clay loam, 12 to 18 percent slopes, severely eroded | | | | | |
| Carmel, severely eroded | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Unstable excavation walls | 0.51 | Unstable excavation walls | 0.51 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| CcE3—Carmel silty clay loam, 18 to 25 percent slopes, severely eroded | | | | | |
| Carmel, severely eroded | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Unstable excavation walls | 0.51 | Unstable excavation walls | 0.51 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| Ch—Chagrin silt loam, frequently flooded | | | | | |
| Chagrin | 100 | Very limited | | Very limited | |
| | | Flooding | 1.00 | Flooding | 1.00 |
| | | Seepage | 0.22 | Seepage | 0.22 |
| | | Dusty | 0.04 | Dusty | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| CnB2—Cincinnati silt loam, 2 to 6 percent slopes, eroded | | | | | |
| Cincinnati | 100 | Somewhat limited | | Somewhat limited | |
| | | Wetness | 0.96 | Wetness | 0.96 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|--|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| CnC2—Cincinnati silt loam, 6 to 12 percent slopes, eroded | | | | | |
| Cincinnati | 100 | Very limited | | Very limited | |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Slope | 0.63 | Dusty | 0.06 |
| | | Dusty | 0.06 | Slope | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| CnC3—Cincinnati silt loam, 6 to 12 percent slopes, severely eroded | | | | | |
| Cincinnati, severely eroded | 100 | Very limited | | Very limited | |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Slope | 0.63 | Dusty | 0.06 |
| | | Dusty | 0.06 | Slope | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| Ct—Clermont silt loam | | | | | |
| Clermont | 100 | Very limited | | Very limited | |
| | | Ponding | 1.00 | Ponding | 1.00 |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| De—Dearborn silt loam, frequently flooded | | | | | |
| Dearborn | 100 | Very limited | | Very limited | |
| | | Flooding | 1.00 | Flooding | 1.00 |
| | | Large stones | 0.89 | Large stones | 0.89 |
| | | Seepage | 0.52 | Seepage | 0.52 |
| | | Dusty | 0.04 | Dusty | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| Df—Dearborn channery loam, frequently flooded | | | | | |
| Dearborn | 100 | Very limited | | Very limited | |
| | | Flooding | 1.00 | Flooding | 1.00 |
| | | Large stones | 0.99 | Large stones | 0.99 |
| | | Seepage | 0.52 | Seepage | 0.52 |
| | | Dusty | 0.04 | Dusty | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|--|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| Du—Dumps | | | | | |
| Dumps | 100 | Not rated | | Not rated | |
| EcE2—Eden silty clay loam, 15 to 25 percent slopes, eroded | | | | | |
| Eden | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Depth to bedrock | 1.00 | Depth to bedrock | 1.00 |
| | | Too stony | 0.59 | Too stony | 0.59 |
| | | Unstable excavation walls | 0.51 | Unstable excavation walls | 0.51 |
| | | Large stones | 0.49 | Large stones | 0.49 |
| EdE3—Eden flaggy silty clay loam, 15 to 25 percent slopes, severely eroded | | | | | |
| Eden, severely eroded | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Too stony | 0.89 | Too stony | 0.89 |
| | | Unstable excavation walls | 0.51 | Unstable excavation walls | 0.51 |
| | | Large stones | 0.07 | Large stones | 0.07 |
| | | Dusty | 0.05 | Dusty | 0.05 |
| EdF—Eden flaggy silty clay, 25 to 50 percent slopes | | | | | |
| Eden | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Too stony | 1.00 | Too stony | 1.00 |
| | | Large stones | 0.90 | Large stones | 0.90 |
| | | Unstable excavation walls | 0.51 | Unstable excavation walls | 0.51 |
| | | Dusty | 0.05 | Dusty | 0.05 |
| EkA—Elkinsville silt loam, 0 to 2 percent slopes | | | | | |
| Elkinsville | 100 | Somewhat limited | | Somewhat limited | |
| | | Flooding | 0.40 | Flooding | 0.40 |
| | | Dusty | 0.07 | Dusty | 0.07 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|--|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| EkB2—Elkinsville silt loam, 2 to 6 percent slopes, eroded | | | | | |
| Elkinsville | 100 | Somewhat limited | | Somewhat limited | |
| | | Flooding | 0.40 | Flooding | 0.40 |
| | | Dusty | 0.07 | Dusty | 0.07 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| EkC2—Elkinsville silt loam, 6 to 12 percent slopes, eroded | | | | | |
| Elkinsville | 100 | Somewhat limited | | Somewhat limited | |
| | | Slope | 0.63 | Flooding | 0.40 |
| | | Flooding | 0.40 | Dusty | 0.07 |
| | | Dusty | 0.07 | Slope | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| FoB2—Fox silt loam, 1 to 4 percent slopes, eroded | | | | | |
| Fox | 100 | Very limited | | Very limited | |
| | | Seepage | 1.00 | Seepage | 1.00 |
| | | Too sandy | 1.00 | Too sandy | 1.00 |
| | | Water gathering surface | 0.27 | Water gathering surface | 0.27 |
| | | Dusty | 0.04 | Dusty | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| HcG—Hennepin loam, 40 to 60 percent slopes | | | | | |
| Hennepin | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Dusty | 0.03 | Dusty | 0.03 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| Hu—Huntington silt loam, frequently flooded | | | | | |
| Huntington | 97 | Very limited | | Very limited | |
| | | Flooding | 1.00 | Flooding | 1.00 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|--|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| Ju—Jules silt loam, frequently flooded | | | | | |
| Jules | 100 | Very limited | | Very limited | |
| | | Flooding | 1.00 | Flooding | 1.00 |
| | | Dusty | 0.07 | Dusty | 0.07 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| MaB2—Markland silt loam, 2 to 12 percent slopes, eroded | | | | | |
| Markland | 100 | Very limited | | Very limited | |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| MaF2—Markland silt loam, 18 to 35 percent slopes, eroded | | | | | |
| Markland | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Unstable excavation walls | 0.10 | Unstable excavation walls | 0.10 |
| | | Dusty | 0.07 | Dusty | 0.07 |
| MbD3—Markland silty clay loam, 6 to 18 percent slopes, severely eroded | | | | | |
| Markland, severely eroded | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Dusty | 0.07 | Dusty | 0.07 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| Ne—Newark silt loam, 0 to 2 percent slopes, frequently flooded | | | | | |
| Newark, frequently flooded | 90 | Very limited | | Very limited | |
| | | Flooding | 1.00 | Flooding | 1.00 |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Water gathering surface | 0.33 | Water gathering surface | 0.33 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|--|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| OcA—Ockley silt loam, 0 to 3 percent slopes | | | | | |
| Ockley | 100 | Very limited | | Very limited | |
| | | Seepage | 1.00 | Seepage | 1.00 |
| | | Too sandy | 1.00 | Too sandy | 1.00 |
| | | Dusty | 0.03 | Dusty | 0.03 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| Omz—Orthents, earthen dam | | | | | |
| Orthents | 100 | Not rated | | Not rated | |
| Or—Orrville silt loam, frequently flooded | | | | | |
| Orrville | 97 | Very limited | | Very limited | |
| | | Flooding | 1.00 | Flooding | 1.00 |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Seepage | 0.09 | Seepage | 0.09 |
| | | Dusty | 0.04 | Dusty | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| PaD2—Pate silty clay loam, 12 to 18 percent slopes, eroded | | | | | |
| Pate | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Unstable excavation walls | 0.26 | Unstable excavation walls | 0.26 |
| | | Dusty | 0.05 | Dusty | 0.05 |
| PaE2—Pate silty clay loam, 18 to 25 percent slopes, eroded | | | | | |
| Pate | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Unstable excavation walls | 0.26 | Unstable excavation walls | 0.26 |
| | | Dusty | 0.05 | Dusty | 0.05 |
| Pg—Pits, gravel | | | | | |
| Pits, sand and gravel | 80 | Not rated | | Not rated | |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|---|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| Ra—Rahm silt loam, occasionally flooded | | | | | |
| Rahm | 97 | Very limited | | Very limited | |
| | | Flooding | 1.00 | Flooding | 1.00 |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Dusty | 0.07 | Dusty | 0.07 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| RdG—Rodman sandy loam, 40 to 60 percent slopes | | | | | |
| Rodman | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Seepage | 1.00 | Seepage | 1.00 |
| | | Sand content | 0.86 | Sand content | 0.86 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| | | Dusty | 0.01 | Dusty | 0.01 |
| RoA—Rossmoyne silt loam, 0 to 2 percent slopes | | | | | |
| Rossmoyne | 100 | Very limited | | Very limited | |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| RoB2—Rossmoyne silt loam, 2 to 6 percent slopes, eroded | | | | | |
| Rossmoyne | 100 | Very limited | | Very limited | |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| RxB—Russell-Fincastle silt loams, 1 to 4 percent slopes | | | | | |
| Russell | 57 | Somewhat limited | | Somewhat limited | |
| | | Wetness | 0.31 | Wetness | 0.31 |
| | | Dusty | 0.05 | Dusty | 0.05 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| Fincastle | 40 | Very limited | | Very limited | |
| | | Wetness | 1.00 | Wetness | 1.00 |
| | | Dusty | 0.05 | Dusty | 0.05 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|---|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| St—Stonelick sandy loam, frequently flooded | | | | | |
| Stonelick | 100 | Very limited | | Very limited | |
| | | Flooding | 1.00 | Flooding | 1.00 |
| | | Seepage | 0.52 | Seepage | 0.52 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| | | Dusty | 0.01 | Dusty | 0.01 |
| SwB2—Switzerland silt loam, 2 to 6 percent slopes, eroded | | | | | |
| Switzerland | 100 | Somewhat limited | | Somewhat limited | |
| | | Wetness | 0.97 | Wetness | 0.97 |
| | | Unstable excavation walls | 0.06 | Unstable excavation walls | 0.06 |
| | | Dusty | 0.05 | Dusty | 0.05 |
| SwC2—Switzerland silt loam, 6 to 12 percent slopes, eroded | | | | | |
| Switzerland | 100 | Somewhat limited | | Somewhat limited | |
| | | Wetness | 0.97 | Wetness | 0.97 |
| | | Slope | 0.63 | Unstable excavation walls | 0.06 |
| | | Unstable excavation walls | 0.06 | Dusty | 0.05 |
| | | Dusty | 0.05 | Slope | 0.04 |
| SwC3—Switzerland silt loam, 6 to 12 percent slopes, severely eroded | | | | | |
| Switzerland, severely eroded | 100 | Somewhat limited | | Somewhat limited | |
| | | Wetness | 0.97 | Wetness | 0.97 |
| | | Slope | 0.63 | Unstable excavation walls | 0.06 |
| | | Unstable excavation walls | 0.06 | Dusty | 0.05 |
| | | Dusty | 0.05 | Slope | 0.04 |
| SwD2—Switzerland silt loam, 12 to 18 percent slopes, eroded | | | | | |
| Switzerland | 100 | Very limited | | Very limited | |
| | | Slope | 1.00 | Slope | 1.00 |
| | | Wetness | 0.97 | Wetness | 0.97 |
| | | Unstable excavation walls | 0.06 | Unstable excavation walls | 0.06 |
| | | Dusty | 0.05 | Dusty | 0.05 |
| Ud—Udorthents, loamy | | | | | |
| Udorthents, loamy | 100 | Not rated | | Not rated | |

| Selected Soil Interpretations--Dearborn County, Indiana | | | | | |
|--|------------------|--|-------|---|-------|
| Map symbol and soil name | Pct. of map unit | Dhs - catastrophic mortality, large animal disposal, pit | | Dhs - catastrophic mortality, large animal disposal, trench | |
| | | Rating class and limiting features | Value | Rating class and limiting features | Value |
| W—Water | | | | | |
| Water | 100 | Not rated | | Not rated | |
| WbB2—Weisburg silt loam, 2 to 6 percent slopes, eroded | | | | | |
| Weisburg | 100 | Somewhat limited | | Somewhat limited | |
| | | Wetness | 0.96 | Wetness | 0.96 |
| | | Dusty | 0.06 | Dusty | 0.06 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| WbC2—Weisburg silt loam, 6 to 12 percent slopes, eroded | | | | | |
| Weisburg | 100 | Somewhat limited | | Somewhat limited | |
| | | Wetness | 0.96 | Wetness | 0.96 |
| | | Slope | 0.63 | Dusty | 0.06 |
| | | Dusty | 0.06 | Slope | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| WbC3—Weisburg silt loam, 6 to 12 percent slopes, severely eroded | | | | | |
| Weisburg, severely eroded | 100 | Somewhat limited | | Somewhat limited | |
| | | Wetness | 0.96 | Wetness | 0.96 |
| | | Slope | 0.63 | Dusty | 0.06 |
| | | Dusty | 0.06 | Slope | 0.04 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |
| WhA—Wheeling silt loam, 0 to 2 percent slopes | | | | | |
| Wheeling | 97 | Somewhat limited | | Somewhat limited | |
| | | Dusty | 0.07 | Dusty | 0.07 |
| | | Unstable excavation walls | 0.01 | Unstable excavation walls | 0.01 |

Data Source Information

Soil Survey Area: Dearborn County, Indiana

Survey Area Data: Version 14, Sep 8, 2014