

Conservation Plan Map - Practice Detail Map

Dairy Aire Farms, Inc.


Farm 567, Tract 1234

Any County USDA - NRCS

Assisted By: Conservation Planner



Field	Landuse	Acreage
1	Crop	26.4 ac.
2	Crop	7.3 ac.
3	Crop	22.6 ac.
4	Crop	6.7 ac.
5	Crop	8.1 ac.
6	Farmstead	4.7 ac.
7	Pasture	3.9 ac.
8	Forest	3.0 ac.
9	Forest	11.2 ac.
10	Forest	74.6 ac.
11	Pasture	14.0 ac.
12	Crop	4.1 ac.
13	Assoc. Ag. Land	2.6 ac.
14	Pasture	17.8 ac.
15	Crop	3.0 ac.



Legend

- Streams
- Roads
- ▨ 561 - Heavy Use Area (Curbs on existing concrete) CIN12
- ⋈ 382 - Fence (4strand high tensile - walkway) CIN6
- ⋈ 382 - Fence (Exclusion - HUA) CIN7
- ⋈ 382 - Fence (Chainlink - reception pit, tank) CIN8
- ▬ 560- Access Road CIN11
- ▬ 575 - Trails & Walkways CIN13
- ⋈ 620 - Underground Outlet (Roof runoff) CIN14
- ⋈ 620 - Underground Outlet (Tank footer drain) CIN15
- ⊙ 313 - Waste Storage (Tank) CIN2
- ⊠ 313 - Waste Storage (Dry Stack) CIN3
- ⊠ 367 - Roof (Timber frame) CIN5
- ⬠ 533 - Pumping Plant (milkhouse transfer) CIN9
- ⊕ 558 - Roof Runoff Structure (Trench drain) CIN10
- ⊕ 632 - Waste Separation Facility CIN16
- ⊕ 634 - Waste Transfer (Scrape area, push off) CIN17
- ⊕ 634 - Waste Transfer (Pipe from separator to tank) CIN18
- ⊕ 634 - Waste Transfer (Milkhouse waste) CIN19
- ⊕ 634 - Waste Transfer (Reception pit) CIN20
- Consplan_txxx

Outlet location to be determined at time of design.



Date: TODAY



Cultural Resources

Property Owner: Dairy Aire Farms, Inc. - t1234 **2**
County: Any County
Township: Any Township
Date: Today

Program: **3** CTA

Undertakings Reviewed that have the Potential to Affect Cultural Resources

Undertakings Reviewed 4	Size of Undertakings (acres, feet, sq ft, no.) 5	Acres of Undertakings Reviewed 6
1 - 313 (1200 sq ft)/367 (1500 sq ft)/632 (1)/634 (900 sq ft) Roofed Stack pad, Separator & Reception Pit	--	0.1
2 - 560 Access Road	4000 sq ft	0.1
3 - 558 (100')/620 (1400') Roof Runoff, Underground Outlet	--	0.1
4 - 313 (5600 sq ft)/634 (400') Waste storage tank & Pipe	--	0.2
5 - 533 (1)/634 (1000') Pumping Plant, waste transfer	--	0.1
6 - 575 Animal walkway	4000 sq ft	0.1
7 - 561 (1500 sq ft)/634 (1) Heavy use area, Push Off	--	0.1
Total Number of Undertakings Reviewed =	7 7	Total Acres = 0.8 8

PRS REPORTING DATA FOR ABOVE UNDERTAKINGS

Number of Investigations Conducted	Acres of Investigation Conducted	Number of Sites Identified	Acres of Sites Identified
9 1	10 4.7	11 0	12 0

13 TREATMENT TYPE

Not Applicable	x
Avoidance	_____
Data Recovery	_____
Interpretation	_____
None	_____
Other	_____

AREAS INVESTIGATED - provide separate info if areas vary significantly

14 Which undertakings?	313, 367, 558, 560	516, 614, 561	412
Type of ground cover	Gravel/Fill	Grass	Cropland
Percent of ground visible	95%	0%	40%
Primarily hydric soil (Y/N)?	N	N	N
Percent slope	2%	6%	8%
Feet to perennial stream	300	500	100

15 Cultural Resources: Are any prehistoric or historic cultural resources known to exist **near** the undertaking? No (Yes or No)
 If yes, **describe:**

16 Rock Outcrops: Are there rock outcrops within the APE? No (Yes or No)
 If yes, **describe:**

17 Previous Disturbance: Describe the depth and type of previous disturbance, if any.

 Normal farming and construction activities, to an average depth of 18"

18 Buildings and other structures: Describe any buildings and their estimated age(s) located **within the APE**. *If buildings 50 years old or older may be directly or indirectly effected, send photos of buildings, area of planned practices and wide view of area.*

 Existing barns and house are in the APE, but none are over 50 years old.

Name of USGS Quad: ANY QUAD
If potential cultural resources exist, send portion of 7.5 minute USGS Quad with Area of Potential Effect (APE) delineated.

- How did you acquire this information? Check all that apply**
- National Register of Historic Places (current County listing) - **Required** **19**
 - Recollections from landowner(s) - **Required, if practicable**
 - Historic Documents (old maps, plats, aerial photos)
 - Local historian, museum, historical society.
 - Visual clues: artifacts, buildings, chimneys, walls, bridges, foundations/footing stones, abutments, depressions, mounds earthworks, or other cultural landscape features or the lack of such features - **Required**

Field survey conducted by (mark one):
 (Must have completed NRCS Cultural Resources Training Mods 1-8)

CD / Partner	FO	CRS
	x	

Signature Heather L. Smeltz, PE **20**

NON-DISCRIMINATION STATEMENT
 "The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer."

Cultural Resources

Property Owner: Dairy Aire Farms, Inc. - t1234 **2**
County: Any County
Township: Any Township
Date: Today

Program: **3** CTA

Undertakings Reviewed that have the Potential to Affect Cultural Resources

Undertakings Reviewed 4	Size of Undertakings (acres, feet, sq ft, no.) 5	Acres of Undertakings Reviewed 6
1 - 313 (1200 sq ft)/367 (1500 sq ft)/632 (1)/634 (900 sq ft) Roofed Stack pad, Separator & Reception Pit	--	0.1
2 - 560 Access Road	4000 sq ft	0.1
3 - 558 (100')/620 (1400') Roof Runoff, Underground Outlet	--	0.1
4 - 313 (5600 sq ft)/634 (400') Waste storage tank & Pipe	--	0.2
5 - 533 (1)/634 (1000') Pumping Plant, waste transfer	--	0.1
6 - 575 Animal walkway	4000 sq ft	0.1
7 - 561 (1500 sq ft)/634 (1) Heavy use area, Push Off	--	0.1
Total Number of Undertakings Reviewed =	7 7	Total Acres = 0.8 8

PRS REPORTING DATA FOR ABOVE UNDERTAKINGS

Number of Investigations Conducted 9	Acres of Investigation Conducted 10	Number of Sites Identified 11	Acres of Sites Identified 12
3	16	1	0.1

13 TREATMENT TYPE

Not Applicable _____
 Avoidance x
 Data Recovery _____
 Interpretation _____
 None _____
 Other _____

AREAS INVESTIGATED - provide separate info if areas vary significantly

14 Which undertakings?	313, 367, 558, 560	516, 614, 561	412
Type of ground cover	Gravel/Fill	Grass	Cropland
Percent of ground visible	95%	0%	40%
Primarily hydric soil (Y/N)?	N	N	N
Percent slope	2%	6%	8%
Feet to perennial stream	300	500	100

15 Cultural Resources: Are any prehistoric or historic cultural resources known to exist **near** the undertaking? Yes (Yes or No)
 If yes, **describe:**

Existing spring house (age unknown but over 50 years) approximately 150' southeast of house, approximately 250' from all proposed practices.

16 Rock Outcrops: Are there rock outcrops within the APE? No (Yes or No)
 If yes, **describe:**

17 Previous Disturbance: Describe the depth and type of previous disturbance, if any.

Normal farming and construction activities, to an average depth of 18"

18 Buildings and other structures: Describe **any** buildings and their estimated age(s) located **within the APE**. *If buildings 50 years old or older may be directly or indirectly effected, send photos of buildings, area of planned practices and wide view of area.*

Existing springhouse (age unknown, but over years) approximately 250' away from all proposed practices. All other buildings within APE are less than 50 years old.

Name of USGS Quad: ANY QUAD

If potential cultural resources exist, send portion of 7.5 minute USGS Quad with Area of Potential Effect (APE) delineated.

How did you acquire this information? Check all that apply

- National Register of Historic Places (current County listing) - **Required** **19**
- Recollections from landowner(s) - **Required, if practicable**
- Historic Documents (old maps, plats, aerial photos)
- Local historian, museum, historical society.
- Visual clues: artifacts, buildings, chimneys, walls, bridges, foundations/footing stones, abutments, depressions, mounds earthworks, or other cultural landscape features or the lack of such features - **Required**

Field survey conducted by (mark one):
 (Must have completed NRCS Cultural Resources Training Mods 1-8)

CD / Partner	FO	CRS
	x	

Signature Heather L. Smeltz, PE

20

NON-DISCRIMINATION STATEMENT
 "The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer."

Cultural Resources

Property Owner: Dairy Aire Farms, Inc. - t1234 **2**
County: Any County
Township: Any Township
Date: Today

Program: **3** CTA

Undertakings Reviewed that have the Potential to Affect Cultural Resources

Undertakings Reviewed 4	Size of Undertakings (acres, feet, sq ft, no.) 5	Acres of Undertakings Reviewed 6
1 - 313 (1200 sq ft)/367 (1500 sq ft)/632 (1)/634 (900 sq ft) Roofed Stack pad, Separator & Reception Pit	--	0.1
2 - 560 Access Road	4000 sq ft	0.1
3 - 558 (100')/620 (1400') Roof Runoff, Underground Outlet	--	0.1
4 - 313 (5600 sq ft)/634 (400') Waste storage tank & Pipe	--	0.2
5 - 533 (1)/634 (1000') Pumping Plant, waste transfer	--	0.1
6 - 575 Animal walkway	4000 sq ft	0.1
7 - 561 (1500 sq ft)/634 (1) Heavy use area, Push Off	--	0.1
Total Number of Undertakings Reviewed =	7 7	Total Acres = 0.8 8

PRS REPORTING DATA FOR ABOVE UNDERTAKINGS

Number of Investigations Conducted	Acres of Investigation Conducted	Number of Sites Identified	Acres of Sites Identified
9 3	10 16	11 1	12 0.2

13 TREATMENT TYPE

- Not Applicable _____
- Avoidance _____
- Data Recovery _____
- Interpretation _____
- None _____
- Other Photo Documentation

AREAS INVESTIGATED - provide separate info if areas vary significantly

14 Which undertakings?	313, 367, 558, 560	516, 614, 561	412
Type of ground cover	Gravel/Fill	Grass	Cropland
Percent of ground visible	95%	0%	40%
Primarily hydric soil (Y/N)?	N	N	N
Percent slope	2%	6%	8%
Feet to perennial stream	300	500	100

15 Cultural Resources: Are any prehistoric or historic cultural resources known to exist **near** the undertaking? Yes (Yes or No)
 If yes, **describe:**

Heavy Use Area planned in front of 100 +/- year old bank barn.

16 Rock Outcrops: Are there rock outcrops within the APE? No (Yes or No)
 If yes, **describe:**

17 Previous Disturbance: Describe the depth and type of previous disturbance, if any.

Normal farming and construction activities, to an average depth of 18". Construction of existing HUA in front of 100 +/- year old bank barn.

18 Buildings and other structures: Describe **any** buildings and their estimated age(s) located **within the APE**. *If buildings 50 years old or older may be directly or indirectly effected, send photos of buildings, area of planned practices and wide view of area.*

Existing house and barns within the APE, but only bank barn is over 50 years old. Gutters have been installed on existing 100' year old bank barn by landowner. Updates and other modifications have been done to barn by landowner.

Name of USGS Quad: ANY QUAD

If potential cultural resources exist, send portion of 7.5 minute USGS Quad with Area of Potential Effect (APE) delineated.

How did you acquire this information? Check all that apply

- National Register of Historic Places (current County listing) - **Required**
- Recollections from landowner(s) - **Required, if practicable**
- Historic Documents (old maps, plats, aerial photos)
- Local historian, museum, historical society.
- Visual clues: artifacts, buildings, chimneys, walls, bridges, foundations/footing stones, abutments, depressions, mounds earthworks, or other cultural landscape features or the lack of such features - **Required**

19

Field survey conducted by (mark one):
 (Must have completed NRCS Cultural Resources Training Mods 1-8)

CD / Partner	FO	CRS
	x	

Signature

Heather L. Smeltz, PE

20

NON-DISCRIMINATION STATEMENT

"The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer."